

# managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

January 31, 20	Signature on File	For Custodial Supervisor Use Only
TO:	Mr. Michael Garretson, Deputy Superintendent Facilities and Construction Management	Custodial Issues Addressed  Custodial Issues Not Addressed
FROM:	Edward See, Project Manager Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment Building 7 - FISH 701	

On December 14, 2007 I conducted an assessment of Building 7 at Facilities and Construction Management Hortt Complex. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Derrick Ragland, Executive Director, Facilities and Construction Management Jeffrey S. Moquin, Director, Risk Management Jack Cooper, Senior Project Manager, Facilities and Construction Management Israel Canales, Manager, Administrative Sites Henry Verdugo, Project Manager, Facilities and Construction Management Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

Facilities and Construction Management/Hortt							Evaluat	tion Requested		
Time of Day 12:00 pm							ı	Evaluation Date	Decem	ber 14, 2007
Outdoor Cond	itions	Te	emperature	81.8	Rela	tive Humidity	69.9	9 Ambie	nt CO2 [	454
Fish	Tempe	rature	Range	Relative Humi	dity R	ange	CO2	Ran	ige	# Occupants
701	74	1.5	72 - 78	53.2	30%	- 60%	601	Max 700	> Ambie	nt 7
Noticeable Oc	dor [	No		Visible wa damage / stai		Visible micr growth		Amount of ma	terial	
Ceiling Type	Tectum		ım	No		No	10		None	
Wall Type	Wood Panel		No		No		None			
Flooring		Carpet		Yes		No		Various		
	(	Clean	Minor D / Debr				Corre	ctive Action Re	equired	
Ceiling		Yes	No	No	<b>D</b>					
Walls		Yes	No	No	<b>)</b>					
Flooring		No	Yes	Ye	s	E	Evaluate	for cleaning ar	nd repair	
HVAC Supply	Grills	Yes	No	No	<b>D</b>					
HVAC Return	Grills	Yes	No	No	<b>)</b>					
Ceiling at Sup Grills	ply	Yes	No	No						
Surfaces in Re	oom	No	Yes	Ye	s		Cle	an as appropri	ate	

IAQ Assessment

9067

**Location Number** 

# Observations

## Findings:

- 2 live plants with visible microbial growth in soil
- Spider webs along window sills
- Heavy dust build up on environmental surfaces throughout the building. Excessive clutter throughout hindering cleaning efforts.
- Open holes in wall (FISH 701) two conduits with open space allowing outside air into occupied space and access for pests. Observed pest droppings on floor.
- Carpet is worn, buckling and torn in multiple areas
- Dust build up on window blinds

#### Recommendations:

# Site Based Maintenance:

- Remove live plants
- Thoroughly clean window sills and blinds to remove spider webs and dust.
- Thoroughly clean environmental surfaces throughout building 7 and encourage occupants to reduce clutter to assist with cleaning efforts.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

### Physical Plant Operations

- Provide custodial assistance to thoroughly clean building 7
- Seal holes in wall (FISH 701)
- Initiate work order for pest control
- Evaluate carpet for cleaning and repair

NOTE - Custodial supervisor advised that they cleaned the building the beginning of January and sealed the holes in FISH 701.