

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

September 13, 2006

Signature on File

TO: Israel Canales, Manager Administrative Sites

- FROM: Kenneth I. Partee, Project Manager Occupational Health and Environmental Control Risk Management Department
- SUBJECT: Indoor Air Quality (IAQ) Assessment Portable A and B

On June 16, 2006 I conducted an assessment of Portable A and B at **HRD Administration**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Jeffrey S. Moquin, Director, Risk Management
Henry Verdugo, Project Manager, Facilities and Construction Management
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

		IAQ Assessment		Loca	tion Number	9754		
HRD Administration					Evalu	Evaluation Requested		5, 2006
Time of Day	9:00 am					Evaluation Date	June 1	6, 2006
Outdoor Cond	litions Te	emperature		Relative Hum	nidity	Ambie	nt CO2	
Fish	Temperature	Range	Relative Humidity	Range	CO2	Ran	ige #	Occupants
Portable A	69.7	72 - 78	59.3	30% - 60%	789	Max 700	> Ambient	5
Noticeable O	dor No		Visible water damage / staining		microbial wth?	Amount of mar affected	terial	
Ceiling Type	2 x 4 La	ay In	Yes	1	10	<u> </u>	/arious	
Wall Type	Plaster		No		10	None		
Flooring	Carpo	et	No	1	10		None	
	Clean	Minor Du / Debris	•••		Corr	ective Action Re	equired	
Ceiling	No	Yes	Yes		Replace	ceiling tiles as r	necessary	
Walls	Yes	No	No					
Flooring	No	Yes	Yes		(Clean and sanitiz	ze	
HVAC Supply	Grills No	Yes	Yes		Clean w	ith Wexcide disi	infectant	
HVAC Return	Grills No	Yes	Yes		Clean w	ith Wexcide disi	infectant	
Ceiling at Sup Grills	oply No	Yes	Yes		CI	ean as appropri	ate	
Surfaces in R	oom Yes	No	No					

Observations

Findings:

- Stained area under desk from unknown spill and sticky substance under desk

- Dust and debris on HVAC supply and return grills and on ceiling at supply grills

- Condensate dripping from HVAC supply grill (sticky substance) in storage room. Thermostat set to 60 degrees.
- Ceiling tile around HVAC supply grill in storage room is stained with possible microbial growth

- Hole in floor in Northwest corner of portable

- Ceiling tile around exhaust fans in both restrooms are stained and warped
- Metallic sound coming from left restroom supply vent
- Various stained and broken ceiling tiles throughout the portable

Recommendations:

Site Based Maintenance:

- Thoroughly clean and sanitize floor

- Clean HVAC supply and return grills throughout the portable with Wexcide disinfecrtant solution and clean ceiling at supply grills

- Replace stained and broken ceiling tiles that do not require cuts
- Adjust thermostat to increase temperature

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate **Physical Plant Operations:**

- Evaluate cause of condensation dripping from HVAC supply grill in storage room
- Evaluate and repair hole in floor in Northwest corner of portable
- Evaluate portable for leaks and remove and replace stained and warped ceiling tiles throughout the portable that require cuts
- Evaluate metallic sound coming from left restroom supply grill and reseat exhaust fan grills in restrooms

			IAQ Assessment		Loca	tion Number	9754	
HRD Administration					Evalu	Evaluation Requested June		5, 2006
Time of Day	9:00 am					Evaluation Date	June 1	6, 2006
Outdoor Condi	tions Te	emperature		Relative Humi	dity	Ambie	nt CO2	
Fish	Temperature	Range	Relative Humidity	Range	CO2	Ran	ige #	Occupants
Portable B	73.8	72 - 78	59	30% - 60%		Max 700	> Ambient	
Noticeable Od	lor No		Visible water damage / staining	Visible n ? grov		Amount of ma affected	terial	
Ceiling Type	2 x 4 La	iy In	Yes	N	0	2 ce	eiling tiles	
Wall Type	Plaste	er	No	No	0		None	
Flooring	Carpe	et	No	N	0		None	
	Clean	Minor Du / Debris			Corr	ective Action Re	equired	
Ceiling	No	Yes	Yes		Replace	ceiling tiles as r	necessary	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean w	ith Wexcide disi	infectant	
HVAC Return	Grills No	Yes	Yes		Clean w	ith Wexcide disi	infectant	
Ceiling at Sup Grills	ply No	Yes	Yes		CI	ean as appropri	ate	
Surfaces in Ro	oom Yes	No	No					

Observations

Findings:

- Dust and debris on HVAC supply and return grills and on ceiling at supply grills
- Noisy return vent
- Portable has dehumidifiers
- 2 stained ceiling tiles

Recommendations:

Site Based Maintenance:

 Clean HVAC supply and return grills throughout the portable with Wexcide disinfecrtant solution and clean ceiling at supply grills
Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate portable for leaks and remove and replace stained ceiling tiles
- Evaluate noisy return vent and repair as appropriate