

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

October 25, 2006 Signature on File

TO: Israel Canales, Manager

Administrative Sites

FROM: Aston A. Henry, Jr., Supervisor

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

7th Floor and 9th Floor

On September 28, 2006 I conducted an assessment of the 7th and 9th floors at **Kathleen C. Wright Administration**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Jeffrey S. Moquin, Director, Risk Management
Henry Verdugo, Project Manager, Facilities and Construction Management
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AAH/tc Enc.

	IAQ Assessment							Location	on Nun	nber			
Kathleen C. Wright Administration							Evaluation Requested		September 28, 2006				
Time of Day	11:5	7 am						E	Evaluat	tion Date	Septer	mber 28, 2	2006
Outdoor Condi	tions	Tem	perature			Relative Hu	midity			Ambie	nt CO2		
Fish	Tempera	ature _I	Range	Relativ	ve Humidity	Range		CO2		Ran	ge	# Occup	pants
7th Floor	76.	4 7	2 - 78		51	30% - 60%		586		Max 700	> Ambi	ent 🦳 🤄	3
Noticeable Od	lor	No			sible water ge / staining		e micro rowth?	bial	Amou	unt of mat affected	erial		
Ceiling Type	2	2 x 4 Lay	In	[No		No				None		
Wall Type		Drywall		No			No		None				
Flooring		Carpet		No			No		None				
	С	lean	Minor D		Needs Cleaning			Correc	ctive A	Action Re	quired		
Ceiling	[Yes	No]	No								
Walls	[Yes	No]	No								
Flooring	[Yes	No]	No								$\square \mid$
HVAC Supply	Grills [Yes	No]	No								
HVAC Return	Grills [Yes	No]	No								
Ceiling at Sup Grills	ply [Yes	No]	No								
Surfaces in Ro	oom [No	Yes		Yes			Clea	an as a	appropria	ate		
bservations													
Findings:	on envir	onmental	surfaces										

0

- Dust and debris on HVAC coils and drain pan
- No visible signs of water intrusion or microbial growth

Recommendations:

Site Based Maintenance:

- Clean environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:
- Coil and drain pan cleaning is scheduled to be done 10-27-06 through 10-29-06 (EQ00668)

			Location N	umber				
	Kathleen (C. Wright Adm	Evaluation l	Requested	September 28, 2006			
Time of Day	11:57 am				Eval	uation Date	Septem	nber 28, 2006
Outdoor Condit	ions Tem	perature		Relative Humidity		Ambie	nt CO2 [
Fish T	emperature F	Range Rel	ative Humidity	Range	CO2	Ran	ge	# Occupants
9th Floor	75.4 7	2 - 78	54.8	30% - 60%	564	Max 700	> Ambie	ent 3
Noticeable Odd	or No	da	Visible water mage / staining	Visible micro growth?	bbial An	nount of mat affected	terial	
Ceiling Type	2 x 4 Lay	ln	No	No			None	
Wall Type	Drywall		No	No	None			
Flooring	Carpet		No	No		None		
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	e Action Re	equired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		Clean a	s appropri	ate	
Flooring	Yes	No	No					
HVAC Supply (Grills Yes	No	No					
HVAC Return G	Grills Yes	No	No					
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Ro	om No	Yes	Yes		Clean a	s appropri	ate	
bservations								
Findings: - Dust build up on environmental surfaces								

- Insulation debris on walls
- Dust and debris on HVAC coils and drain pan
- No visible signs of water intrusion or microbial growth

Recommendations:

Site Based Maintenance:

- Clean environmental surfaces
- Clean walls to remove insulation debris
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Coil and drain pan cleaning is scheduled to be done 10-27-06 through 10-29-06 (EQ00668)