

managing risk with responsibility

Aston A. Henry, Supervisor Risk Management Department Telephone:754 321-1900Fax:754 321-1917

1 11 1 0 0010				
April 16, 2012	Signature on File	For Custodial Supervisor Use Only		
TO:	Israel Canales, Manager Administrative Sites	Custodial Issues Addressed Custodial Issues Not Addressed		
FROM:	Richard Rosa, Project Manager Facilities and Construction Management			
SUBJECT:	Indoor Air Quality (IAQ) Assessment			

On February 13, 2012 I conducted an assessment at **New River Circle Portable Annex**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities and Construction Management Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Sonja Coley, Project Manager III, Facilities and Construction Management Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management

RK/tc Enc.

			IAQ Ass	sessment	Location Number	
New River Circle Portable Annex					Evaluation Requested	February 7, 2012
Time of Day	9:15]			Evaluation Date	February 13, 2012
Outdoor Cond	itions Tei	mperature	59.2	Relative Humidity	58.1 Ambie	ent CO2 531
Fish	Temperature	Range Rela	ative Humidity	Range	CO2 Rai	nge # Occupants
P-78PD	53.7	72 - 78	57.7	30% - 60%	533 Max 700	> Ambient
Noticeable Oc	dor No		Visible water nage / staining	Visible micro ? growth?	bial Amount o material affe	
Ceiling Type	2 x 4 Lay	/ In	Yes	No	Less the	an 1 square feet
Wall Type	Drywall/V	′inyl	Yes	No	50 s	square feet
Flooring	12 x 12 V	inyl	Yes	No	E	Intrances
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired
Ceiling	No	Yes	Yes		See below	
Walls	No	Yes	Yes		See below	
Flooring	No	Yes	Yes		See below	
HVAC Supply	Grills No	Yes	Yes		Clean as appropr	ate
HVAC Return	Grills No	Yes	Yes		Clean as appropr	iate
Ceiling at Sup Grills	oply				N/A	
Surfaces in R	oom No	Yes	Yes		Clean as appropr	iate

Observations

- Findings (being used for storage)
- Termite droppings along walls.
- Stained ceiling tiles
- Water damaged interior wall system under windows (SW)
- Water damaged T-1-11 on exterior (see pictures)
- Water damaged flooring at entrances
- Build up on A/C shaker unit coils
- Dust build up on surfaces throughout the room

Site Based Maintenance:

- Remove and replace ceiling tiles once repairs have been completed.
- Clean A/C shaker units grills with Wexcide disinfectant solution
- Thoroughly clean all surfaces throughout the rooms
- Ensure temperature is set within SBBC limits (72-78)
- Wipe down light fixture lenses inside and out with Wexcide disinfectant solutions
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Pest control to evaluate for termites
- Evaluate for cause of stained ceiling tiles and repair as appropriate.
- Evaluate for cause of interior wall damage under windows and T-1-11 damage and repair as appropriate. Repair/replace wall material -- interior and exterior -- as necessary.
- Evaluate flooring at entrances and repair/replace as necessary
- Clean coils on A/C shaker units

- NOTE: Work orders EQ02324 through EQ02331 generated 3-7-12

			IAQ Ass	sessment	Location Number	
New River Circle Portable Annex					Evaluation Requested	February 7, 2012
Time of Day	9:15]			Evaluation Date	February 13, 2012
Outdoor Cond	itions Tei	mperature	59.2	Relative Humidity	58.1 Ambie	ent CO2 531
Fish	Temperature	Range Rel	ative Humidity	Range	CO2 Ra	nge # Occupants
P-79PD	52.3	72 - 78	60.7	30% - 60%	541 Max 700	> Ambient
Noticeable Oc	dor No]da	Visible water mage / staining	Visible micro ? growth?	bial Amount o material affe	
Ceiling Type	2 x 4 Lay	/ In	Yes	No	60	eiling tiles
Wall Type	Drywall/V	′inyl	Yes	No	150	square feet
Flooring	12 x 12 V	inyl	Yes	No	E	Intrances
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired
Ceiling	No	Yes	Yes		See below	
Walls	No	Yes	Yes		See below	
Flooring	No	Yes	Yes		See below	
HVAC Supply	Grills No	Yes	Yes		Clean as appropr	iate
HVAC Return	Grills No	Yes	Yes		Clean as appropr	iate
Ceiling at Sup Grills	oply				N/A	
Surfaces in R	oom No	Yes	Yes		Clean as appropr	iate

Observations

- Findings (being used for storage)
- Termite droppings along walls.
- Stained ceiling tiles
- Water damaged interior wall system under windows (SW)
- Water damaged T-1-11 on exterior (see pictures)
- Water damaged flooring at entrances
- Build up on A/C shaker unit coils
- Dust build up on surfaces throughout the room

Site Based Maintenance:

- Remove and replace ceiling tiles once repairs have been completed.
- Clean A/C shaker units grills with Wexcide disinfectant solution
- Thoroughly clean all surfaces throughout the rooms
- Ensure temperature is set within SBBC limits (72-78)
- Wipe down light fixture lenses inside and out with Wexcide disinfectant solutions
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Pest control to evaluate for termites
- Evaluate for cause of stained ceiling tiles and repair as appropriate.
- Evaluate for cause of interior wall damage under windows and T-1-11 damage and repair as appropriate. Repair/replace wall material -- interior and exterior -- as necessary.
- Evaluate flooring at entrances and repair/replace as necessary
- Clean coils on A/C shaker units

- NOTE: Work orders EQ02324 through EQ02331 generated 3-7-12