

# managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

June 25, 2008

Signature on File

For Custodial Supervisor Use Only

Custodial Issues Addressed

Custodial Issues Not Addressed

FROM:

Aston A. Henry, Supervisor
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 201, 202 and 203

On June 19, 2008 I conducted an assessment of FISH 201, 202 and 203 at **Old Dillard Museum**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Jeffrey S. Moquin, Director, Risk Management
Israel Canales, Manager, Administrative Sites
James Carballo, Project Manager, Facilities and Construction Management
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AH/tc Enc.

		Old Dillard	d Museum		Evaluat	ion Requested	June 17, 2008
Time of Day	3:40 pm				E	Evaluation Date	June 19, 2008
Outdoor Cond	litions Ten	nperature	80.1	Relative Hum	idity 81.2	Ambie	nt CO2 547
Fish	Temperature	Range Re	ative Humidity	Range	CO2	Ran	ge # Occupants
201	75	<b>72 - 78</b>	59.9	30% - 60%	913	Max 700	> Ambient 3
Noticeable O	dor No	da	Visible water mage / staining		microbial wth?	Amount of mat affected	terial
Ceiling Type	Drywal		No	N	lo		None
Wall Type	Drywal		No	N	lo		None
Flooring	Carpet		No	N	lo		None
	Clean	Minor Dust / Debris	Needs Cleaning	ı	Correc	ctive Action Re	equired
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills Yes	No	No				
HVAC Return	Grills Yes	No	No				
Ceiling at Sup Grills	oply Yes	No	No				
Surfaces in R	oom No	Yes	Yes		Clea	an as appropri	ate
Observations							
	ns of microbial gr			eading displays	s 75 degrees.		

**IAQ Assessment** 

9518

**Location Number** 

- Excessive paper, boxes, books and clutter throughout room
- Dust build up on environmental surfaces due to clutter

### Recommendations:

## Site Based Maintenance:

- Encourage occupant to reduce clutter to assist with cleaning efforts
- Remove items (paper, boxes, books, etc.) from room and clean thoroughly
  Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations

Evaluate thermostat for proper operation and repair/replace as appropriate

		Old Dil	llard Museum		Evaluat	ion Requested June 17, 2008		
Time of Day	3:40 pm				F	Evaluation Date June 19, 2008		
Outdoor Condi	tions Ter	mperature	80.1	Relative Humidity	81.2	Ambient CO2 547		
Fish	Temperature	Range	Relative Humidity	<sup>'</sup> Range	CO2	Range # Occupants		
202	74.7	72 - 78	61.3	30% - 60%	912	Max 700 > Ambient 3		
Noticeable Od	Odor No		Visible water damage / staining	Visible micro g? growth?		Amount of material affected		
Ceiling Type	Drywall		No	No		None		
Wall Type	Drywa	ıII	No No			None		
Flooring	Carpet	Ĺ	No	No		None		
Clean Minor Dust Needs Corrective Action Required / Debris Cleaning								
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return (	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Room No Yes		Yes	Yes		Clean as appropriate			
) Dbservations								
Findings:								
- No visible signs of microbial growth or water intrusion								
- Humidity level was slightly elevated at the time of the assessment								
<ul><li>Excessive paper, boxes, books and clutter throughout room</li><li>Dust build up on environmental surfaces due to clutter</li></ul>								
Recommendations:								
- Remove items	cupant to reduce (paper, boxes,	books, etc.)	assist with cleaning from room and cligns of microbial g	ean thoroughly	st and de	ebris accumulation and clean as		

Physical Plant Operations
- Evaluate HVAC for proper operation and repair as appropriate to lower humidity level

appropriate

**IAQ Assessment** 

9518

**Location Number** 

		Old Dillard I	Museum		Evaluation	n Requested [	June 17, 2008	}
Time of Day	3:25 pm				Eva	aluation Date [	June 19, 2008	}
Outdoor Condition	ns Temper	ature 8	30.1	Relative Humidity	81.2	Ambier	nt CO2 547	]
Fish Ten	nperature Ranç	ge Rela	tive Humidity	Range	CO2	Ran	ge # Occupa	ants
203	70.9 <b>72 - 7</b>	78	69.7	30% - 60%	844	Max 700	> Ambient 2	
Noticeable Odor	Yes	-	Visible water Visible micr damage / staining? growth?		bial A	Amount of material affected		
Ceiling Type	Drywall		No No			None		
Wall Type	Drywall		No No			None		
Flooring	Flooring Carpet		No No			None		
		linor Dust / Debris	Needs Cleaning		Correcti	ve Action Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Gri	ills Yes	No	No					
HVAC Return Gri	IIs Yes	No	No					
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Room	n Yes	No	No					
Observations								
Findings: - Room has a musty odor - HVAC condensate lines dripping, dust and debris on coils and build up in drain pan - Humidity level was elevated at the time of the assessment  Recommendations:								
Site Based Maintenance: - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate								

Physical Plant Operations
- Evaluate HVAC condensate lines and repair as appropriate to alleviate dripping

Evaluate HVAC for proper operation and repair as appropriate to lower humidity level

Clean HVAC coils and drain pan

**IAQ Assessment** 

9518

**Location Number**