

Aston A. Henry, Supervisor Risk Management Department

managing risk with responsibility

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

July 13, 2010	Signature on File	For Custodial Supervisor Use Only
TO:	Mr. Israel Canales, Manager Administrative Sites	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management	
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 239, 245 and 257	

On May 24, 2010 and May 25, 2010 IAQ assessments of FISH 239, 245 and 257 were conducted at **Sawgrass Central Area Office**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Leontine Butler, Area Superintendent Jeffrey S. Moquin, Executive Director, Support Operations Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Aston Henry, Supervisor, Risk Management Greg Boardman, Project Manager, Facilities and Construction Management Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

			IAQ As	sessment	Location Number		
	:	Sawgrass Admi	nistration		Evaluation Requested	May	19, 2010
Time of Day	10:30 am]			Evaluation Date	May	24, 2010
Outdoor Condi	itions Ter	nperature	87.4	Relative Humidity	59.7 Amb	ient CO2	374
Fish	Temperature	Range Rela	ative Humidity	Range	CO2 Ra	ange i	# Occupants
239	72.9	72 - 78	53.9	30% - 60%	582 Max 70	0 > Ambieı	nt 3
Noticeable Od	lor No		Visible water nage / staining	Visible microl ? growth?	bial Amount material affe		
Ceiling Type	2 x 2 Lay	' In	No	No		None	
Wall Type	Drywa	I	No	No		None	
Flooring	Carpet		Yes	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action F	Required	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills Yes	No	No				
HVAC Return	Grills Yes	No	No				
Ceiling at Sup Grills	ply Yes	No	No				
Surfaces in Ro	oom Yes	No	No				

Observations

Findings (Central Area Office)

- Live plant against window on North wall with visible microbial growth

- Temperature, CO2 and humidity were all within an acceptable range at the time of the assessment

Site Based Maintenance:

- Remove live plant from room. Soil is a source of microbial growth.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location Numb	ber		
		Sawgrass Adm	inistration		Evaluation Requ	uested	May	19, 2010
Time of Day	10:30 am]			Evaluatio	on Date	May	24, 2010
Outdoor Condi	tions Ter	nperature	87.4	Relative Humidity	59.7	Ambie	nt CO2	374
Fish	Temperature	Range Rela	ative Humidity	Range	CO2	Ran	ge #	# Occupants
245	73.5	72 - 78	52.8	30% - 60%	589 M	lax 700	> Ambier	nt 3
Noticeable Od	lor No]dai	Visible water mage / staining	Visible microl 9? growth?		nount of rial affec		
Ceiling Type	2 x 2 Lay	' In	No	No			None	
Wall Type	Drywa	I	No	No			None	
Flooring	Carpet		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Ac	ction Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Νο	Yes	Yes		Clean and	d sanitiz	e	
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Observations

Findings (Central Area Office)

- Minor staining on carpet

- Live plant on West wall with visible microbial growth in FISH 237

- Temperature, CO2 and humidity were all within an acceptable range at the time of the assessment

Site Based Maintenance:

- Generate a request to clean carpet

- Remove live plant from room. Soil is a source of microbial growth.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location Number		
Sawgrass Administration					Evaluation Requested	May 19, 2	010
Time of Day	12:30 pm]			Evaluation Date	May 26, 2	010
Outdoor Condi	itions Ter	nperature	88.3	Relative Humidity	52.2 Ambie	nt CO2 34	8
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Rar	ige # O <u>cc</u>	upants
257	73.7	72 - 78	49.3	30% - 60%	630 Max 700	> Ambient	7
Noticeable Oc	lor No		Visible water nage / staining	Visible microl ? growth?	bial Amount o material affe	-	
Ceiling Type	2 x 2 Lay	' In	Νο	No		None	
Wall Type	Drywa	I	No	No		None	
Flooring	Carpet		No	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	No	Yes	Yes		Clean and Saniti	ze	
HVAC Supply	Grills Yes	Νο	No				
HVAC Return	Grills Yes	No	No				
Ceiling at Sup Grills	oply Yes	No	No				
Surfaces in Ro	oom Yes	No	No				

Observations

Findings (Central Area Office)

- Minor staining on carpet

- 1 1/2" hole in ceiling tile

- 6 live plants in area - 3 in soil and 3 in water

- Staff advised that when the HVAC system is not working, which has been quite often, the occupied space is unbearable. At the time of the assessment the system was working properly and the temperature, CO2 and humidity were all within an acceptable range.

Site Based Maintenance:

- Generate a request to replace ceiling tile and clean carpet

- Remove live plants from room. Soil is a source of microbial growth.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate