

Aston A. Henry, Supervisor Risk Management Department

FISH 210

March 9, 2010

TO:

FROM:

SUBJECT:

managing risk with responsibility

Telephone: 754 321-1900 Fax: 754 321-1917

Signature on File	For Custodial Supervisor Use Only		
Israel Canales, Manager Administrative Sites	Custodial Issues Addressed Custodial Issues Not Addressed		
Edward See, Project Manager Risk Management Department			
Indoor Air Quality (IAQ) Assessment			

On February 25, 2010, I conducted an assessment of FISH 210 at TSSC. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Jeffrey S. Moquin, Executive Director, Support Operations Aston Henry, Supervisor, Risk Management Israel Rodriguez-Soto, Project Manager, Facilities and Construction Management Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			IAQ Ass	sessment	Location Number	1291	
			TSSC		Evaluation Requested	February 19, 2010	
Time of Day	10:00 am				Evaluation Date	February 25, 2010	
Outdoor Conditions Temperature 53.3 Relative Humidity 47.7 Ambient CO2 356							
Fish	Temperature	Range Relat	ive Humidity	Range	CO2 Ran	ige # Occupants	
210	67.7	/2 - 78	49.2	30% - 60%	717 Max 700	> Ambient 8	
Noticeable Od	lor No	-	/isible water age / staining	Visible micro ? growth?	bial Amount o material affec		
Ceiling Type	2 x 4 Lay	In	No	No		None	
Wall Type	Wall Type Drywall/Plaster		No			None	
Flooring	Raised floor	· 2x2	No	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills Yes	No	No				
HVAC Return	Grills Yes	No	No				
Ceiling at Sup Grills	pply				N/A - A/C supply at	floor	
Surfaces in Ro	oom No	Yes	Yes		Clean as appropri	ate	

Observations

- Findings (Computer Room)
- Occupant not present at the time of the assessment.
- Minor dust on boxes
- FISH 221 Mechanical Room No issues identified

Site Based Maintenance:

- Wipe down boxes to remove dust. Ensure that boxes are wiped down prior to bringing into building

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate