

Aston A. Henry, Supervisor

FISH 121 and 126

managing risk with responsibility

754 321-1900

Telephone:

Risk Managen	nent Department	Fax:	754 321-1917
May 17, 2010	Signature on File	For Custodia	l Supervisor Use Only
TO:	Israel Canales, Manager Administrative Sites		Issues Addressed Issues Not Addressed
FROM:	Edward See, Project Manager Risk Management Department	<u> </u>	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	-	

On May 11, 2010, I conducted an assessment of FISH 121 and 126 at **TSSC**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Jeffrey S. Moquin, Executive Director, Support Operations
Aston Henry, Supervisor, Risk Management
Israel Rodriguez-Soto, Project Manager, Facilities and Construction Management
Lula Taylor, Supervisor, Personnel Records
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			TS	<u>ssc</u>		Evaluati	ion Requested	April 3	30, 2010
Time of Day						E	Evaluation Date	May 1	11, 2010
Outdoor Conditions Temperature 89.3 Relative Humidity 69.6 Ambient CO2 398									
Fish 121 Noticeable Od Ceiling Type Wall Type	76.2 or No 2 x 4 La			1 3 e water staining?		_	Amount of material affec	> Ambient	Occupants t 18
Flooring	Carp	et	N	0	N	0		None	
Ceiling Walls Flooring HVAC Supply HVAC Return Ceiling at Sup Grills Surfaces in Ro	Grills No	Minor / Del N N Ye	oris C	Needs leaning No No No Yes Yes No		Clea	an as appropri	ate	
bservations									

IAQ Assessment

9356

Location Number

0

Findings

- Dust build up on HVAC supply and return grills and in drops
- Minor dust build up along edge of cubicle
- Carpet worn
- 3 potted plants
- Occupant desk near fire door South wall

Site Based Maintenance:

- Remove potted plants from room. Soil is a source of microbial growth.
- Clean along edge of cubicle to remove dust build up
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate carpet and repair as appropriate
- Clean HVAC supply and return grills and inside HVAC supply and return drops

			TSSC		Evaluati	ion Requested	April 30	0, 2010
Time of Day					E	Evaluation Date	May 1	I, 2010
Outdoor Conditions	Tempe	rature 8	9.3	Relative Humidit	y 69.6	Ambient	CO2	398
Fish Tempe	erature Ran 72 -	78	ive Humidity	Range 30% - 60%	CO2	Rang Max 700 >		Occupants
Noticeable Odor	No		isible water age / staining	Visible micr growth		Amount of material affecte	d	
Ceiling Type	2 x 4 Lay In		No	No		N	lone	
Wall Type	Drywall/Plaste	r	No	No		N	one	
Flooring	Tile		No	No		N	lone	
		linor Dust / Debris	Needs Cleaning		Correc	ctive Action Req	uired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Grills	s No	Yes	Yes		Clea	an as appropriat	е	
HVAC Return Grills	No	Yes	Yes		Clea	an as appropriat	е	
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Room	Yes	No	No					
Dbservations								
Findings RESTROOM - Dust build up on HVAC supply grill and in drop - Dust build up on HVAC return grill and in drop outside of FISH 126 - Rusted soap dispenser								
Site Based Maintenance: - Clean soap dispenser and generate a work order through COMPASS to replace - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate								
Physical Plant Operations: - Clean HVAC supply and return grills and inside HVAC supply and return drops - Return grill is located outside of FISH 126								

IAQ Assessment

9356

Location Number