



Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

March 10, 2005

TO: Mr. Kenneth Fulop, Principal Cross Creek School

- FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental Control Risk Management Department
- SUBJECT: Indoor Air Quality (IAQ) Assessment FISH 501 and 713

On February 28, 2005 the IAQ Assessment Team conducted an assessment FISH 501 and 713 at **Cross Creek School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

 cc: Dr. Joanne Harrison, Area Superintendent Sharon Airaghi, Area Director Jeffrey S. Moquin, Director, Risk Management Raul Ascarrunz, Project Manager II, Facilities and Construction Management LaFrances Trotter, Broward Teachers Union Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Project Manager II, Facilities and Construction Management

KP/tc Enc.

IAQ Assessment											
Cross Creek School					Evaluation Requested February 24, 200						
Time of Day 11	1:30 am				I	Evaluation Date	Febru	ary 28, 2005			
Outdoor Conditions	5 Tempera	ature	F	Relative Hum	nidity	Ambier	nt CO2				
Fish Temp	erature Rang	je Relativ	e Humidity	Range	CO2	Ran	ge	# Occupants			
501	72.5 <b>72 - 7</b>	8	70	30% - 60%	628	< 1,000	PPM	4			
Noticeable Odor	No	-	ible water ge / staining?		microbial owth?	Amount of mat affected	erial				
Ceiling Type	2 x 4 Lay In		Νο		No		None				
Wall Type	Plaster/Lexan		No	Yes		10' x 10'					
Flooring	Tile		Νο		No		None				
	/	nor Dust Debris	Needs Cleaning		Corre	ctive Action Re	quired				
Ceiling	Yes	Νο	No								
Walls	Νο	Yes	Yes	Remo	ve Lexan and	l clean with We	xcide d	isinfectant			
Flooring	Νο	Yes	Yes		Cl	ean and sanitiz	е				
HVAC Supply Grills	s No	Yes	Yes		Clean wit	h Wexcide disi	nfectan	t			
HVAC Return Grills	s No	Yes	Yes		Clean wit	h Wexcide disi	nfectan	t			
Ceiling at Supply Grills	Νο	Yes	Yes		Clean or	replace as app	ropriate	•			
Surfaces in Room	Yes	No	No								

# Observations

### Findings:

- Visible microbial growth identified behind Lexan. Room is used for time out and the Lexan is 6' up the walls and moisture is getting trapped behind the Lexan. Children attack the walls and other surfaces.

- Dust and debris on HVAC supply and return grills
- Stained and dusty ceiling tiles
- Dust and debris on flooring
- Humidity level is elevated

### Recommendations:

### Site Based Maintenance:

- Clean HVAC supply and return grills with wexcide disinfectant solution
- Clean or replace ceiling tiles
- Clean and sanitize flooring

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations Division:

- Clean microbial growth and install Wonder Board on all appropriate surfaces at least 7 feet high
- Evaluate and repair HVAC system in order to lower the humidity level

IAQ Assessment											
Cross Creek School					Evaluation Requested February 24, 20						
Time of Day	1:30 am				I	Evaluation Date	Febru	ary 28, 2005			
Outdoor Condition	s Temj	perature		Relative Hun	nidity	Ambie	nt CO2				
Fish Tem	perature R	ange Rela	tive Humidity	Range	CO2	Ran	ge	# Occupants			
713	73.2 <b>72</b>	2 - 78	60.07	30% - 60%	795	< 1,000	PPM	4			
Noticeable Odor	No		/isible water age / staining		microbial owth?	Amount of mat affected	erial				
Ceiling Type	2 x 4 Lay I	n	No		No		None				
Wall Type	Plaster/Lexa	an	No	Yes		10' x 10'					
Flooring	Tile		No		No		None				
Ceiling	Clean	Minor Dust / Debris	Needs Cleaning No	[	Corre	ctive Action Re	quired				
-											
Walls	No	Yes	Yes	Remo	ve Lexan and	I clean with We	xcide d	isinfectant			
Flooring	No	Yes	Yes		CI	ean and sanitiz	е				
HVAC Supply Gril	ls No	Yes	Yes		Clean wit	h Wexcide disi	nfectan	t			
HVAC Return Grill	s No	Yes	Yes		Clean wit	h Wexcide disi	nfectan	t			
Ceiling at Supply Grills	Νο	Yes	Yes		Clean or	replace as app	ropriate	•			
Surfaces in Room	Yes	No	No								

# Observations

### Findings:

- Visible microbial growth identified behind Lexan. Room is used for time out and the Lexan is 6' up the walls and moisture is getting trapped behind the Lexan. Children attack the walls and other surfaces.

- Dust and debris on HVAC supply and return grills
- Stained and dusty ceiling tiles
- Dust and debris on flooring

### Recommendations:

### Site Based Maintenance:

- Clean HVAC supply and return grills with wexcide disinfectant solution

- Clean or replace ceiling tiles
- Clean and sanitize flooring

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

### Physical Plant Operations Division:

- Clean microbial growth and install Wonder Board on all appropriate surfaces at least 7 feet high