

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department

September 6, 2006

Telephone: 754-321-3200 Facsimile: 754-321-3290

Signature on File

TO: Mr. Kenneth Fulop, Principal

Cross Creek School

FROM: Kenneth I. Partee, Project Manager Occupational Health and Environmental Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 127, 402, 404 and 407

On August 31, 2006 I conducted an assessment of FISH 127, 402, 404 and 407 at **Cross Creek School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent
Sharon Airaghi, Area Director
Jeffrey S. Moquin, Director, Risk Management
Joe DeLillo, Project Manager, Facilities and Construction Management
Jamie Daniels, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

		Cross Cr	eek School		Evaluation I	Requested [August	31, 2006
Time of Day	12:00 pm]			Evalu	uation Date	August	31, 2006
Outdoor Cond	ditions Te	mperature [94.2	Relative Humidity	66.1	Ambier	nt CO2	512
Fish	Temperature	Range Re	elative Humidity	Range	CO2	Ran	ge #	Occupants
127	69	72 - 78	56.8	30% - 60%	650	Max 700 :	> Ambient	3
Noticeable O	dor No	d	Visible water amage / staining	Visible micro growth?	,	nount of mate affected		
Ceiling Type	2 x 4 La	y In	Yes	No		3 Ce	iling Tiles	
Wall Type	Plaste	r	No	No			None	
Flooring	Tile		No	No			None	
	Clean	Minor Dus / Debris	t Needs Cleaning		Corrective	Action Re	quired	
Ceiling	No	Yes	Yes	R	emove and	replace ceil	ing tiles	
Walls	No	Yes	Yes		Clean a	s appropria	ite	
Flooring	No	Yes	Yes		Clean	and sanitiz	е	
HVAC Supply	Grills No	Yes	Yes	С	lean with W	excide disir	nfectant	
HVAC Return	Grills No	Yes	Yes	С	lean with W	excide disir	nfectant	
Ceiling at Sup Grills	pply Yes	No	No					
Surfaces in R	Room No	Yes	Yes		Clean a	s appropria	ite	
L Observations								

3222

Location Number

Findings:

- 3 stained ceiling tiles to the left above lockers
- Dust build up on walls
- Dust and debris on HVAC supply and return grills
- Dust and debris on floor
- Dust build up on environmental surfaces

Recommendations:

Site Based Maintenance:

- Clean walls as appropriate
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean and sanitize floor
- Clean environmental surfaces throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

Remove and replace 3 stained ceiling tiles requiring cut. Leak was recently repaired.

		Cros	ss Creek Schoo	<u>ol</u>		Evaluation	n Requested	August	1 31, 2006
Time of Day	12:00 pn	n		_		Eva	aluation Date	August	31, 2006
Outdoor Condi	itions	Temperatur	re 94.2	Rela	tive Humidity	66.1	Ambie	nt CO2	512
Fish	Temperature	Range	Relative Hur	midity R	ange	CO2	Ran	ge #	Occupants
402		72 - 78		30%	- 60%		Max 700	> Ambien	t
Noticeable Oc			Visible w damage / st		Visible microl growth?	bial #	Amount of mat affected		
Ceiling Type	2 x 4	Lay In	Yes]	No	Ļ	1 cc	eiling tile	
Wall Type	Pla	aster	No		No			None	
Flooring	Т	Tile	No		No			None	
_	Clean	/ Del	bris Clea	eeds aning			ive Action Re	•	
Ceiling	No] <u>Y</u> e	es Y	/es	Re	move and	d replace ceil	ling tiles	
Walls No Yes Yes Clean as appropriate									
Flooring	No] <u>Y</u> e	es Y	res [Clea	an and sanitiz	.e	
HVAC Supply	Grills No] Ye	es Y	/es	Cle	ean with \	Wexcide disi	nfectant	
HVAC Return	Grills No] <u>Y</u> e	es Y	res [Cle	ean with \	Wexcide disir	nfectant	
Ceiling at Sup Grills	oply Yes	N	lo N	No [
Surfaces in Ro	oom No	Ye	s Y	res [Clean	n as appropria	ate	
Observations									
Findings: - Stained ceiling tile at rear of room - Dust build up on walls - Dust and debris on HVAC supply and return grills - Dust and debris on floor - Dust build up on environmental surfaces									

3222

August 31, 2006

Location Number Evaluation Requested

Recommendations:

Site Based Maintenance:

- Clean walls as appropriate
 Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean and sanitize floor
- Clean environmental surfaces throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate for leak at rear of room and repair. Remove and replace stained ceiling tiles as appropriate.

Time of Day	12:00 pm]			Evaluation Date August 31, 2006			
Outdoor Condi	tions Ten	nperature 9	14.2 Re	elative Humidity	66.1 Ambient CO2 512			
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Range # Occupants			
404		72 - 78	30)% - 60%	Max 700 > Ambient			
Noticeable Od	L	dam	/isible water nage / staining?	Visible microk growth?	affected			
Ceiling Type	2 x 4 Lay		No	No	None			
Wall Type	Plaster	•	No	No	None			
Flooring	Tile		No	No	None			
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Required			
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		Clean as appropriate			
Flooring	No	Yes	Yes		Clean and sanitize			
HVAC Supply	Grills No	Yes	Yes	Cle	ean with Wexcide disinfectant			
HVAC Return (Grills No	Yes	Yes	Cle	ean with Wexcide disinfectant			
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clean as appropriate			
Observations Findings:								
- Visible microbial growth on log in room - Dust build up on walls - Dust and debris on HVAC supply and return grills - Dust and debris on floor - Dust build up on environmental surfaces								
Recommendati	ons:							
Site Based Maintenance: Remove log with visible microbial growth Clean walls as appropriate Clean HVAC supply and return grills with Wexcide disinfectant solution Clean and sanitize floor Clean environmental surfaces throughout the room Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate								

Cross Creek School

3222

August 31, 2006

Location Number
Evaluation Requested

		0.000 0.00				- !	
Time of Day	12:00 pm				E	/aluation Date	August 31, 2006
Outdoor Condi	tions Tem	perature 9	4.2 Re	elative Humidity	66.1	Ambie	nt CO2 512
Fish	Temperature p	Range Relat	tive Humidity	Range	CO2	Ran	ge # Occupants
407	7	2 - 78	30	0% - 60%		Max 700	> Ambient
Noticeable Od	lor No		isible water age / staining?	Visible microl growth?	bial	Amount of ma	terial
Ceiling Type	2 x 4 Lay	In	Yes	No		1	Various
Wall Type	Plaster		No	No			None
Flooring	Tile		No	No			None
	Clean	Minor Dust / Debris	Needs Cleaning		Correct	ive Action Re	equired
Ceiling	No	Yes	Yes	Re	move ar	nd replace cei	iling tiles
Walls	No	Yes	Yes		Clea	n as appropri	ate
Flooring	No	Yes	Yes		Cle	an and sanitiz	ze
HVAC Supply	Grills No	Yes	Yes	Cle	ean with	Wexcide disi	nfectant
HVAC Return	Grills No	Yes	Yes	Cle	ean with	Wexcide disi	nfectant
Ceiling at Sup Grills	ply Yes	No	No				
Surfaces in Ro	oom No	Yes	Yes		Clea	n as appropri	ate

Cross Creek School

3222

August 31, 2006

Location Number

Evaluation Requested

Observations

Findings:

- Stained ceiling tile above teacher's desk and at rear of room above whiteboard
- Dust build up on walls
- Dust and debris on HVAC supply and return grills
- Dust and debris on floor
- Dust build up on environmental surfaces

Recommendations:

Site Based Maintenance:

- Clean walls as appropriate
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean and sanitize floor
- Clean environmental surfaces throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate for leak over teacher's desk and repair. Remove and replace stained ceiling tiles requiring cut - over teacher's desk and at rear of room above whiteboard.