

managing risk with responsibility

Aston A. Henry, Supervisor **Risk Management Department**

SUBJ

754 321-1900 Telephone: Fax: 754 321-1917

November 1	0, 2009	Signature on File	For Custodial Supervisor Use Only
TO:		ent Alessi, Principal Run Education Center	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:		See, Project Manager agement Department	
SUBJECT:	Indoor A FISH 146	ir Quality (IAQ) Assessment and 148	

On October 12, 2009, I conducted an assessment of FISH 146 and 148 at Cypress Run Education Center. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Sharon Airaghi, Area Superintendent Anne Dilgen, Area Director Jeffrey S. Moquin, Executive Director, Support Operations Aston Henry, Supervisor, Risk Management Hilda Jimenez, Project Manager, Facilities and Construction Management Lynn Cavall, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

ES/tc Enc.

			IAQ Ass	sessment	Locati	on Number	2123	
Cypress Run Education Center				Evaluat	Evaluation Requested October 9, 2009			
Time of Day	5:06 pm]			I	Evaluation Date	October	⁻ 12, 2009
Outdoor Condi	tions Ten	nperature		Relative Hum	nidity	Ambie	nt CO2	
Fish	Temperature	Range Relat	ive Humidity	Range	CO2	Ran	ge #	Occupants
146	74.2	72 - 78	74.3	30% - 60%	451	Max 700	> Ambient	2
Noticeable Od	lor No	-	'isible water age / staining'		microbial owth?	Amount of material affec		
Ceiling Type	Drywal		No	Y	es	<u> </u>	Various	
Wall Type	Cerami	с	No	Y	es	V	/arious	
Flooring	Terrazo)	No	N	lo		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	No	Yes	Yes		Clean wi	th Wexcide disi	infectant	
Walls	No	Yes	Yes		Clean wi	th Wexcide disi	infectant	
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Observations

Findings:

- Humidity level was elevated at the time of the assessment

- Visible microbial growth on ceiling and walls

Site Based Maintenance:

- Wipe down ceiling and walls with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level. Possibly in negative pressure bringing in outside air via supply.

			IAQ Asse	essment	Location	n Number	2123	
	Cypres	s Run Educatior	n Center		Evaluatio	on Requested	Octobe	r 9, 2009
Time of Day	5:06 pm				E٧	aluation Date	October	12, 2009
Outdoor Condi	itions Ten	nperature	R	elative Humidit	у	Ambie	nt CO2	
Fish	Temperature	Range Relat	ive Humidity	Range	CO2	Ran	ge #	Occupants
148	70.2 7	2 - 78	65.4 3	0% - 60%	441	Max 700	> Ambient	2
Noticeable Od	lor No		isible water age / staining?	Visible mici growth		Amount of material affec		
Ceiling Type	Drywall		No	No	L		None	
Wall Type	Ceramio	;	No	No			None	
Flooring	Terrazo		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correct	ive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Observations

Findings:

- Humidity level was elevated at the time of the assessment

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.

Note: Outside air vent above 151 and 161 is blowing cool air.