

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

October 10, 2	008 Signature on File	For		
TO:	Mrs. Tracy Lockhart-Talley, Principal Charles Drew Family Resource Center			
FROM:	Edward See, Project Manager Risk Management Department			
SUBJECT:	Indoor Air Quality (IAQ) Assessment Portable 550C, 590C and 841CT			

<u>Fo</u>	or Custodial Supervisor Use Only
	Custodial Issues Addressed
	Custodial Issues Not Addressed
-	

On October 7, 2008 I conducted an assessment of Portable 550C, 590C and 841CT at Charles Drew Family Resource Center. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Leontine Butler, Area Superintendent Dr. Desmond Blackburn, Area Director Jeffrey S. Moquin, Director, Risk Management Robert Goode, Project Manager, Facilities and Construction Management Lynn Cavall, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			IAQ As	sessment	Location Nu	umber	0301	
	Charles Drew	Family Resourc	ce Center		Evaluation R	Requested	Octobe	r 2, 2008
Time of Day	8:15 am				Evalu	ation Date	Octobe	r 7, 2008
Outdoor Conditi	ions Ten	perature	83.1	Relative Humidity	68.3	Ambie	nt CO2	385
Fish To	emperature	Range Rela	ative Humidity	Range	CO2	Ran	nge #	Occupants
P-550C	77.6 7	2 - 78	51.2	30% - 60%	416	Max 700	> Ambient	4
Noticeable Odd	or No		Visible water nage / staining	Visible micro growth?	obial Am	ount of mai affected	terial	
Ceiling Type	2 x 4 Lay	In	Yes	No		4 staine	ed ceiling til	es
Wall Type	Wood		No	No			None	
Flooring	12 x 12 Vi	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	No	Yes	Yes	R	emove and r	eplace cei	iling tiles	
Walls	No	Yes	Yes		Clean as	s appropri	ate	
Flooring	Yes	No	No					
HVAC Supply G	Grills Yes	No	No					
HVAC Return G	irills Yes	No	No					
Ceiling at Supp Grills	ly Yes	No	No					
Surfaces in Roo	om Yes	Νο	No					

Observations

Findings:

- 4 stained ceiling tiles

- Dust and debris on window sills

- Visible microbial growth on exterior of portable

Recommendations:

Site Based Maintenance:

 Remove and replace stained ceiling tiles. If stains return contact COMPASS to generate a work order to evaluate and for cause and repair as appropriate.

- Thoroughly clean window sills

- Pressure clean exterior of portable

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location I	Number	0301	
	Charles Drew F	amily Resourc	e Center		Evaluation	Requested	Octobe	r 2, 2008
Time of Day	8:15 am				Eva	luation Date	Octobe	r 7, 2008
Outdoor Condit	tions Tem	perature 8	3.1	Relative Humidity	68.3	Ambie	nt CO2	385
Fish T	Temperature	Range Relat	tive Humidity	Range	CO2	Ran	nge #	Occupants
P-590C	80.3 7	2 - 78	63.4	30% - 60%	375	Max 700	> Ambient	2
Noticeable Od	or No	-	isible water age / staining	Visible micro growth?		mount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Wood		No	No			None	
Flooring	12 x 12 Vir	ıyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correctiv	e Action Re	equired	
Ceiling	Yes	Νο	No					
Walls	Yes	No	No					
Flooring	Yes	Νο	No					
HVAC Supply (Grills Yes	No	No					
HVAC Return (Grills Yes	Νο	No					
Ceiling at Supp Grills	oly					N/A		
Surfaces in Ro	om No	Yes	Yes		Clean	as appropri	ate	

Observations

Findings:

- 3 potted plants with visible microbial growth
- Both A/C units were off at the time of the assessment
- Non-approved chemicals in room potpourri
- Dust build up on environmental surfaces

Recommendations:

Site Based Maintenance:

- Remove potted plants from room. Soil is a source of microbial growth.

- Ensure that both A/C units remain on during occupied hours and one A/C unit is on during unoccupied hours
- Remove non-approved chemicals from room potpourri
- Thoroughly clean environmental surfaces throughout the room

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ Ass	essment	Location Number	0301
	Charles Drew I	amily Resource	e Center		Evaluation Requeste	d October 2, 2008
Time of Day	8:15 am				Evaluation Da	te October 7, 2008
Outdoor Conditio	ons Tem	perature 8	3.1	Relative Humidity	68.3 Amt	pient CO2 385
Fish Te	mperature F	Range Relat	ive Humidity	Range	CO2 R	ange # Occupants
P-841CT	7	2 - 78		30% - 60%	Max 7	00 > Ambient
Noticeable Odor	r No		isible water age / staining?	Visible micro growth?	bial Amount of r affecte	
Ceiling Type	Wood pan	el	Yes	No		Various
Wall Type	Plastic		Yes	No		Various
Flooring	12 x 12 Vir	iyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action	Required
Ceiling	No	Yes	Yes		Work orders gen	erated
Walls	No	Yes	Yes		Work orders gen	erated
Flooring	No	Yes	Yes		Clean and san	tize
HVAC Supply G	rills No	Yes	Yes	CI	lean with Wexcide d	isinfectant
HVAC Return Gr	rills Yes	Νο	No			
Ceiling at Supply Grills	у No	Yes	Yes		Work orders gen	erated
Surfaces in Roo	m Yes	Νο	No			

Observations

Findings: (women's restroom)

- Visible signs of water intrusion - walls buckling, ceiling stained

- Dust and debris on HVAC supply grills

- Glue seeping up through floor seams

Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution

- Thoroughly clean and sanitize floor to remove glue

- Monitor progress of work orders

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

- Work orders generated by staff - J326819 and J328174 to address issues