

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

October 27, 2006 Signature on File

TO: Mr. Daniel Boegli, Principal

Sheridan Technical Center

FROM: Aston A. Henry, Jr., Supervisor

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 469 and 469A

On September 27, 2006 Kenneth Partee conducted an assessment of FISH 469 and 469A at **Sheridan Technical Center**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Harry LaCava, Area Superintendent

Fran Bolden, Area Director

Jeffrey S. Moquin, Director, Risk Management

Joe DeLillo, Project Manager, Facilities and Construction Management

Diane Watts, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AAH/tc Enc.

| | SI | neridan Technic | al Center | | Evaluation | on Requested | September | r 27, 2006 |
|---|-------------------|------------------|--|---------------------|-------------|-------------------|---------------------|------------|
| Time of Day | |] | | | E | valuation Date | September | 27, 2006 |
| Outdoor Condi | tions Ter | mperature | | Relative Humidity | | Ambie | nt CO2 | |
| Fish 469 & 469A | | Range Rela | tive Humidity | Range 30% - 60% | CO2 | Ran Max 700 | ge # 0 > Ambient | Occupants |
| Noticeable Od | lor No | | Visible water Visible micro damage / staining? growth? | | | | | |
| Ceiling Type | 2 x 4 Lay | | No No | No Stoken | | affected | None | |
| Wall Type | Vall Type Plaster | | No | No | | None | | |
| Flooring | Tile | | No | No | [| | None | |
| Clean Minor Dust Needs / Debris Cleaning Corrective Action Required | | | | | | | | |
| Ceiling | Yes | No | No | | | | | |
| Walls | Yes | No | No | | | | | |
| Flooring | Yes | No | No | | | | | |
| HVAC Supply | Grills Yes | No | No | | | | | |
| HVAC Return | Grills Yes | No | No | | | | | |
| Ceiling at Sup Grills | ply Yes | No | No | | | | | |
| Surfaces in Ro | oom Yes | No | No | | | | | |
| Observations | | | | | | | | |
| Findings: - Insulation arou | und the A/C duct | work is saturate | ed. Appears to | be a leak. | | | | |
| Recommendat | ions: | | | | | | | |
| Site Based Mai - Continue to mo appropriate | | on for any signs | of microbial gr | owth as well as dus | st and deb | oris accumulation | on and clean | as |
| Physical Plant - Evaluate caus | | sulation and rep | air. Remove a | and replace duct wo | ork insulat | ion as necessa | ary. | |
| NOTE: WO EQ00779 already issued | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| 1 | | | | | | | | |

IAQ Assessment

1051

Location Number