

Report: PPO

**SHERIDAN TECHNICAL CENTER**

Walkthrough Date: 05/30/2007 Temp RH CO2

Outdoor Parameters: 80.7 64.9 530

Room	Priority	Responsible	Answer	Recommendation
113	Inside Parameters:	Temp 65.8	RH 64.2	CO2 610

2 PPO Humidity was slightly elevated at the time of assessment. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
122	Inside Parameters:	Temp 70.6	RH 54.6	CO2 865

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
208	Inside Parameters:	Temp 71.7	RH 55.3	CO2 776

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
431B	Inside Parameters:	Temp 72.5	RH 57.2	CO2 738

1 PPO Condensation on walls or surfaces at the time of assessment. No leak identified. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
431C	Inside Parameters:	Temp	RH	CO2

		73.7	54	752
--	--	------	----	-----

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
440	Inside Parameters:	Temp	RH	CO2
		67	71.2	429

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Odor detected and no microbial growth identified. Physical Plant operations to evaluate cause odor.

Room	Priority	Responsible	Answer	Recommendation
445	Inside Parameters:	Temp	RH	CO2
		72.1	61.2	472

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
462	Inside Parameters:	Temp	RH	CO2
		69.2	48.2	938

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
463	Inside Parameters:	Temp	RH	CO2
		73.4	54.7	631

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
469	Inside Parameters:	Temp	RH	CO2
		73.1	62.3	747

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
506	Inside Parameters:	Temp 68.3	RH 68.4	CO2 437

2 PPO Humidity was slightly elevated at the time of assessment. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
518B	Inside Parameters:	Temp 80.3	RH 47.3	CO2 608

2 PPO Odor detected and no microbial growth identified. Physical Plant operations to evaluate cause odor.

Room	Priority	Responsible	Answer	Recommendation
519B	Inside Parameters:	Temp 71.9	RH 64.5	CO2 533

2 PPO Humidity was slightly elevated at the time of assessment. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.

2 PPO Humidity was slightly elevated at the time of assessment. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.

Room	Priority	Responsible	Answer	Recommendation
522	Inside Parameters:	Temp 72.0	RH 67.2	CO2 532

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Humidity was slightly elevated at the time of assessment. Gaps in windows or doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
524B	Inside Parameters:	Temp	RH	CO2
		74.7	49.6	657

2 PPO Odor detected at the time of assessment. Physical Plant operations to evaluate cause of odor.

2 PPO Odor detected at the time of assessment. Cause not found. Physical Plant operations to evaluate cause of odor.

Room	Priority	Responsible	Answer	Recommendation
530	Inside Parameters:	Temp	RH	CO2
		73.0	63.5	548

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
532	Inside Parameters:	Temp	RH	CO2
		71.3	65.6	529

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.