

Aston A. Henry, Supervisor  
Risk Management Department

Telephone: 754 321-1900  
Fax: 754 321-1917

February 10, 2011

**Signature on File**

TO: Mr. David Watkins, Principal  
**Whiddon-Rogers Education Center**

FROM: Edward See, Project Manager  
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment  
**Room 5**

On January 26, 2011, I conducted an assessment of Room 5 at the Thompson Academy (off site location).. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and we recommend that the building owner initiate action to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Desmond Blackburn, Area Superintendent  
Jan Beal, Area Director  
Jeffrey S. Moquin, Executive Director, Support Operations  
Mark Howard, Assistant Principal, Whiddon-Rogers Education Center  
Joe DeLillo, Project Manager, Facilities and Construction Management  
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1  
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division  
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc  
Enc.

# IAQ Assessment

Location Number

Thompson Academy - Whiddon Rogers Off Site

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions      Temperature       Relative Humidity       Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="Room 5"/>	<input type="text" value="73.2"/>	<input type="text" value="72 - 78"/>	<input type="text" value="72.9"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="2028"/>	<input type="text" value="Max 700 &gt; Ambient"/>	<input type="text" value="22"/>
<b>Noticeable Odor</b>	<input type="text" value="Yes"/>		<b>Visible water damage / staining?</b>	<input type="text" value="No"/>	<b>Visible microbial growth?</b>	<input type="text" value="No"/>	<b>Amount of material affected</b>
<b>Ceiling Type</b>	<input type="text" value="2 x 4 Lay In"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
<b>Wall Type</b>	<input type="text" value="Drywall"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
<b>Flooring</b>	<input type="text" value="Vinyl"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
<b>Ceiling</b>	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
<b>Walls</b>	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
<b>Flooring</b>	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean and sanitize"/>
<b>HVAC Supply Grills</b>	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean as appropriate"/>
<b>HVAC Return Grills</b>	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean as appropriate"/>
<b>Ceiling at Supply Grills</b>	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
<b>Surfaces in Room</b>	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean as appropriate"/>

**Observations**

**Findings (Building not owned by SBBC)**

- **Musty odor in room**
- Dust and debris on floor
- Dust and debris on HVAC supply and return grills
- Dust build up on environmental surfaces
- Dust and debris on A/C filters
- Humidity and CO2 were elevated at the time of the assessment
- HVAC return grill not cemented properly

**Building Owner:**

- Evaluate for cause of stained ceiling tiles and repair as appropriate. Remove and replace ceiling tiles as necessary.
- Clean and sanitize flooring
- Clean HVAC supply and return grills
- Clean environmental surfaces throughout the room
- Remove and replace A/C filters
- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity and CO2
- Properly install HVAC return grill