

# managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

September 6, 2006 Signature on File

TO: Mr. Chris Carney, Principal

**Bennett Elementary School** 

FROM: Kenneth I. Partee, Project Manager Occupational Health and Environmental Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 009C, 501, 909, 921 and 923

On August 31, 2006 I conducted an assessment of FISH 009C, 501, 909, 921 and 926 at **Bennett Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent

Joel Herbst, Area Director

Jeffrey S. Moquin, Director, Risk Management

Matt Decker, Project Manager, Facilities and Construction Management

Jerrod Neal, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

<u> </u>	В	ennett Elementa	ary School		Evaluat	ion Requested	August 3	31, 2006
Time of Day	10:15 am				I	Evaluation Date	August 3	31, 2006
Outdoor Condi	tions Te	mperature	98.7	Relative Humidi	ty 56.4	Ambie	nt CO2	429
Fish 009C	Геmperature	Range Re 72 - 78	lative Humidity	30% - 60%	CO2	Ran Max 700	ge # 0 > Ambient	Occupants
Noticeable Od	or No	da	Visible water mage / staining	Visible mid growt!		Amount of mat affected	terial	
Ceiling Type	2 x 4 La	y In	Yes	No	]	4 Ce	eiling Tiles	
Wall Type	Concre	ete	No	No			None	
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	No	Yes	Yes	F	Replace ce	eiling tiles as a	ppropriate	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return (	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					
Dbservations								
Findings: Cafe - 4 stained ceilin								
Recommendati	ons:							
Site Based Mai - Remove and re - Continue to mo appropriate	eplace stained	ceiling tiles ion for any signs	s of microbial g	rowth as well as c	lust and de	ebris accumulatio	on and clear	n as

0201

**Location Number** 

	В	ennett Eleme	ntary School		Evaluat	ion Requested	August 31, 2006	
Time of Day	10:15 am				E	Evaluation Date	August 31, 2006	
Outdoor Condi	tions Te	mperature	98.7	Relative Humidit	y 56.4	Ambien	t CO2 429	
Fish	Temperature	Range F	Relative Humidity	Range	CO2	Rang	ge # Occupant	ts
501	68.7	72 - 78	66.3	30% - 60%	532	Max 700 >	- Ambient 5	
Noticeable Od	or No		Visible water damage / staining	Visible mic g? growth		Amount of mate affected		_
Ceiling Type	2 x 4 La	y In	Yes	No		4 Cei	ling Tiles	]
Wall Type	Concre	ete	No	No		N	lone	
Flooring	Tile		No	No			None	]
	Clean	Minor Du / Debris		I	Correc	ctive Action Rec	quired	
Ceiling	No	Yes	Yes	R	eplace ce	iling tiles as ap	propriate	]
Walls	No	Yes	Yes		Cle	an as appropria	te	]
Flooring	No	Yes	Yes		Cle	ean and sanitize	9	]
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide disin	fectant	]
HVAC Return	Grills No	Yes	Yes		Clean wit	h Wexcide disin	fectant	]
Ceiling at Sup Grills	ply No	Yes	Yes		Cle	an as appropria	te	]
Surfaces in Ro	oom Yes	No	No					]

0201

**Location Number** 

## Observations

#### Findings: Cafeteria

- Ceiling tiles and HVAC supply grills are painted blue
- 2 stained ceiling tiles between HVAC return grills and 2 missing ceiling tiles from previous repair (cuts required)
- Dust and debris on HVAC supply and return grills and on ceiling at HVAC supply grills
- Dust and debris on floor. Build up in corner to the right of the exit door.
- Temperature was low and humidity level was slightly elevated

## Recommendations:

### Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution and ceiling at supply grills
- Clean and sanitize floor
- Adjust thermostat to increase temperature which will also lower the humidity level.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

### Physical Plant Operations:

- Evaluate for leaks and repair. Remove and replace stained ceiling tiles requiring cut and replace missing ceiling tiles.

	Bennett Eleme	entary School		Evaluation R	equested [	August 31, 2006
Time of Day 10:	15 am			Evalu	ation Date [	August 31, 2006
Outdoor Conditions	Temperature	98.7 F	Relative Humidity	56.4	Ambier	nt CO2 429
Fish Tempe	Range 72 - 78	Relative Humidity	Range 30% - 60%	CO2	Ran Max 700	ge # Occupants > Ambient
Noticeable Odor	No	Visible water damage / staining?	Visible micro growth?	bial Am	ount of mat	erial
Ceiling Type	2 x 4 Lay In	Yes	No			eiling Tile
Wall Type	Concrete	No	No			None
Flooring	Tile	No	No			None
	Clean Minor Du / Debri			Corrective	Action Re	quired
Ceiling	No	Yes	Rep	olace ceiling	tiles as ap	propriate
Walls	Yes No	No				
Flooring	Yes No	No				
HVAC Supply Grills	Yes No	No				
HVAC Return Grills	Yes No	No				
Ceiling at Supply Grills	Yes No	No				
Surfaces in Room	Yes No	No				
Observations						
Findings: Cafeteria - 1 stained ceiling tile						
Recommendations:						
Site Based Maintena - Remove and replace - Continue to monitor tappropriate	nce: e stained ceiling tile this location for any si	gns of microbial gro	owth as well as dus	t and debris a	accumulatio	on and clean as

0201

August 31, 2006

**Location Number** Evaluation Requested

Bennett Elementary School Evaluation Requested August 31, 2006
Time of Day 10:15 am Evaluation Date August 31, 2006
Outdoor Conditions Temperature 98.7 Relative Humidity 56.4 Ambient CO2 429
Fish Temperature Range Relative Humidity Range CO2 Range # Occupants
921
Noticeable Odor No Visible water Visible microbial Amount of material damage / staining? growth? affected
Ceiling Type 2 x 4 Lay In Yes No 1 Ceiling Tile
Wall Type Concrete No None
Flooring Tile No None
Clean Minor Dust Needs Corrective Action Required / Debris Cleaning
Ceiling No Yes Yes Replace ceiling tiles as appropriate
Walls Yes No No
Flooring Yes No No
HVAC Supply Grills Yes No No
HVAC Return Grills Yes No No
Ceiling at Supply Yes No No Sills
Surfaces in Room Yes No No
bservations
Findings: Cafeteria - 1 stained ceiling tile - Elevator in building 9 not working properly
Recommendations:
Site Based Maintenance:  Remove and replace stained ceiling tile  Call in a work order to have elevator checked for proper operation  Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

0201

**Location Number** 

	Bennett Eleme	entary School		<b>Evaluation Requested</b>	August 31, 2006
Time of Day 10	:15 am			<b>Evaluation Date</b>	August 31, 2006
Outdoor Conditions	Temperature	98.7 F	Relative Humidity	56.4 Ambie	ent CO2 429
Fish Tempe	erature Range 72 - 78	Relative Humidity	Range 30% - 60%	CO2 Rar Max 700	nge # Occupants > Ambient
Noticeable Odor	No	Visible water damage / staining?	Visible micro growth?	bial Amount of ma affected	terial
Ceiling Type	2 x 4 Lay In	Yes	No		eiling Tiles
Wall Type	Concrete	No	No		None
Flooring	Tile	No	No		None
	Clean Minor Do			Corrective Action Re	equired
Ceiling	No Yes	Yes	Rep	place ceiling tiles as a	ppropriate
Walls	Yes No	No			
Flooring	Yes No	No			
HVAC Supply Grills	Yes No	No			
HVAC Return Grills	Yes No	No			
Ceiling at Supply Grills	Yes No	No			
Surfaces in Room	Yes No	No			
Observations					
Findings: Cafeteria - 2 stained ceiling tiles					
Recommendations:					
Site Based Maintena - Remove and replace - Continue to monitor appropriate	e stained ceiling tiles	gns of microbial gro	owth as well as dus	t and debris accumulati	on and clean as

0201

August 31, 2006

**Location Number** Evaluation Requested