

# managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

June 10, 2008	Signature on File	For Custodial Supervisor Use Only			
TO:	Mr. Chris Carney, Principal Bennett Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed			
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management				
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 301				

On May 23, 2008 I conducted an assessment of FISH 301 at **Bennett Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Verda Farrow, Area Superintendent
Margaret Underhill, Area Director
Jeffrey S. Moquin, Director, Risk Management
Matt Decker, Project Manager, Facilities and Construction Management
Jerrod Neal, Broward Teachers Union
Roy Jarrett, National Federation of Public and Private Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

-	Ben	nett Elementary	School		Evaluation	on Requested	May 21	, 2008
Time of Day	12:00 p.m.				E	valuation Date	May 23	, 2008
Outdoor Condit	tions Tem	perature 89	9.2	Relative Humidit	y 64.3	Ambie	nt CO2	468
Fish T	Temperature g	Danga Poloti	ve Humidity		CO2	D	# 0	\
301	· ·	Range Relati 2 - 78	55.7	Range 30% - 60%	491	Ran	<b>J</b> •	Occupants 4
Will do Will do was a second								
Noticeable Od	or No	dama			affected	eriai		
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Tackable/Pla	aster	No	No			None	
Flooring	12 x 12 Vin	yl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	tive Action Re	quired	
Cailing	Yes	No	No	F				
Ceiling	163	140	140					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply (	Grills Yes	No	No					
TIVAO Gappiy	011113 [103]	140	140					
HVAC Return (	Grills Yes	No	No					
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Ro	om Yes	No	No					
hsorvations								

**IAQ Assessment** 

0201

**Location Number** 

#### **Observations**

#### Findings:

- Cabinet under sink is wet inside from water being splashed out of the sink and down the front of the cabinet
- Non-approved chemicals/cleaners under sink
- Mechanical room FISH 316 inside of unit clean, coils clean, filters clean and pan clean and dry. Mechanical room is open to attic space above building and open to crawl space below building (ducted return)
- Sewer vent pipe outside of room vents 18 inches below the top of the windows to the room may be source of complaints

### Recommendations:

## Site Based Maintenance:

- Remove non-approved chemicals/cleaners from room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Cap sewer vent pipe outside of room or extend above roof line