

Jeffrey S. Moquin, Director  
Risk Management Department

Telephone: 754-321-3200  
Facsimile: 754-321-3290

August 2, 2005

TO: Ms. Mary Lou Ridge, Principal  
**Bethune Elementary School**

FROM: Robert J. Krickovich, Coordinator, LEA  
Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment  
FISH 801K, 806, 807, 809, 810 and 815

On July 21, 2005 the IAQ Assessment Team conducted an assessment of FISH 801K, 806, 807, 809, 810 and 815 at **Bethune Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Sam Gregg, Area Superintendent  
Margaret Underhill, Area Director  
Jeffrey S. Moquin, Director, Risk Management  
Bertram Lewars, Project Manager II, Facilities and Construction Management  
Jerrod Neal, Broward Teachers Union  
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1  
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc  
Enc.

# IAQ AHU Assessment

Bethune Elementary

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions      Temperature       Relative Humidity       Ambient CO2

AHU Room #	Temperature	Range	Relative Humidity	Range	CO2	Range
<input type="text" value="801K"/>	<input type="text"/>	<input type="text" value="72 - 78"/>	<input type="text"/>	<input type="text" value="30% - 60%"/>	<input type="text"/>	<input 1,000="" ppm)"="" type="text" value("&lt;=""/>
Noticeable Odor	<input type="text" value="No"/>	Visible water damage / staining?	Visible microbial growth?	Amount of material affected		
Ceiling Type	<input type="text" value="Metal Deck"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Wall Type	<input type="text" value="Drywall"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Flooring	<input type="text" value="Concrete"/>	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="Standing water on floor"/>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Room	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean Room"/>
Filters	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Coil	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean Coils"/>
Pan	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Duct	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean inside of unit"/>
Motorized Damper Installed	<input type="text" value="Unknown"/>		<input type="text" value="Cannot determine location"/>	
Damper Open / Operating	<input type="text" value="Unknown"/>		<input type="text" value="Cannot determine location"/>	
Fresh Air Intake Un-obstructed	<input type="text" value="Unknown"/>		<input type="text" value="Cannot determine location"/>	
Pollutant Sources Near Air Intake	<input type="text" value="Unknown"/>		<input type="text" value="Cannot determine location"/>	
AHU Supply Water Temp	<input type="text" value="47"/>		AHU Return Water Temp	<input type="text" value="52"/>

## Observations

<b>Findings:</b>	<ul style="list-style-type: none"> <li>- AHU in room has the wrong size filters or is missing filler panels allowing air to bypass filters (unfiltered air causes dirty supply grills, dirty ceiling tiles at supply grills and IAQ complaints)</li> <li>- Heavy dust and debris on filters (one was so dirty that it was sucked out of the frame and into the air handler coil)</li> <li>- Standing water on floor from leaking valves</li> <li>- Dust and debris in room and on floor (Pictures, television and carpet remnants stored in room)</li> <li>- Dust and debris on HVAC coils</li> </ul>
<b>Recommendations:</b>	
<b>Site Based Maintenance:</b>	<ul style="list-style-type: none"> <li>- Install new filters - proper size</li> <li>- Thoroughly clean room</li> </ul>
<b>Physical Plant Operations Division:</b>	<ul style="list-style-type: none"> <li>- Clean HVAC coils and duct at units due to filter bypass</li> <li>- Evaluate and repair leaking chilled water valves and evaluate and repair to lower humidity levels throughout the building</li> </ul>

# IAQ Assessment

Bethune Elementary School

Evaluation Requested July 21, 2005

Time of Day 11:50 am

Evaluation Date July 21, 2005

Outdoor Conditions      Temperature 93.1      Relative Humidity 58.8      Ambient CO2 404

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
806	73.8	72 - 78	66.8	30% - 60%	397	Max 700 > Ambient	3
Noticeable Odor	No		Visible water damage / staining?	Visible microbial growth?	Amount of material affected		
Ceiling Type	2x4 Lay In		Yes	No	One Tile		
Wall Type	Drywall		Yes	Yes	120 square feet - 2 Locations		
Flooring	Carpet		No	No	Carpet is New		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	No	Yes	Yes	Cobwebs in corners
Walls	No	Yes	Yes	Clean and paint
Flooring	Yes	No	No	Carpet is new
HVAC Supply Grills	No	Yes	Yes	Clean with Wexcide disinfectant
HVAC Return Grills	No	Yes	Yes	Clean with Wexcide disinfectant
Ceiling at Supply Grills	No	Yes	Yes	Clean as appropriate
Surfaces in Room	No	Yes	Yes	Clean as appropriate

## Observations

**Findings:**

- Visible microbial growth on Southwest wall (previously reported) and on South wall (new)
- Visible microbial growth on instrument cases
- One stained ceiling tile
- Water damaged drywall on left side of water cooler and in corridors at doors
- All exterior walls have water intrusion (elevated moisture levels)
- Heavy dust and debris on environmental surfaces and clutter throughout the room (boxes, papers, etc.)
- Heavy dust and debris on HVAC supply and return grills
- Dust and debris on ceiling at HVAC supply grills
- Elevated humidity level

**Recommendations:**

**Site Based Maintenance:**

- Dispose of all instrument cases with visible microbial growth
- Replace stained ceiling tile
- Clean all environmental surfaces and encourage occupant to remove clutter
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

**Physical Plant Operations Division:**

- Remove and replace all drywall where water damaged - Southwest wall and South wall, left side of water cooler and corridors at doors
- Evaluate and repair HVAC system to lower humidity level

**Project Manager:**

- Evaluate cause of water intrusion and initiate repair ASAP

# IAQ Assessment

Bethune Elementary School

Evaluation Requested July 21, 2005

Time of Day 11:50 am

Evaluation Date July 21, 2005

Outdoor Conditions      Temperature 93.1      Relative Humidity 58.8      Ambient CO2 404

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
807	75.1	72 - 78	69.3	30% - 60%	415	Max 700 > Ambient	3
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
Ceiling Type		No		No		None	
Wall Type		Yes		No		Around secondary exit door	
Flooring		No		No		Carpet is New	

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	No	Yes	Yes	Cobwebs in corners
Walls	No	Yes	Yes	Clean and paint
Flooring	Yes	No	No	Carpet is new
HVAC Supply Grills	No	Yes	Yes	Clean with Wexcide disinfectant
HVAC Return Grills	No	Yes	Yes	Clean with Wexcide disinfectant
Ceiling at Supply Grills	No	Yes	Yes	Clean as appropriate
Surfaces in Room	No	Yes	Yes	Clean as appropriate

## Observations

### Findings:

- Water damaged drywall around secondary exit door and in corridors at doors
- All exterior walls have water intrusion (elevated moisture levels)
- Heavy dust and debris on environmental surfaces and clutter throughout the room (boxes, papers, etc.)
- Heavy dust and debris on HVAC supply and return grills
- Dust and debris on ceiling at HVAC supply grills
- Elevated humidity level

### Recommendations:

#### Site Based Maintenance:

- Clean all environmental surfaces and encourage occupant to remove clutter
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations Division:

- Remove and replace drywall where water damaged - around secondary exit doors and in corridors at doors
- Evaluate and repair HVAC system to lower humidity level

#### Project Manager:

- Evaluate cause of water intrusion and initiate repair ASAP

# IAQ Assessment

Bethune Elementary School

Evaluation Requested July 21, 2005

Time of Day 11:50 am

Evaluation Date July 21, 2005

Outdoor Conditions      Temperature 93.1      Relative Humidity 58.8      Ambient CO2 404

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<span style="border: 1px solid black; padding: 2px;">809</span>	<span style="border: 1px solid black; padding: 2px;">72.9</span>	<span style="border: 1px solid black; padding: 2px;">72 - 78</span>	<span style="border: 1px solid black; padding: 2px;">69</span>	<span style="border: 1px solid black; padding: 2px;">30% - 60%</span>	<span style="border: 1px solid black; padding: 2px;">397</span>	<span style="border: 1px solid black; padding: 2px;">Max 700 &gt; Ambient</span>	<span style="border: 1px solid black; padding: 2px;">3</span>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">One ceiling tile</span>	
Ceiling Type	<span style="border: 1px solid black; padding: 2px;">2x4 Lay In</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Around secondary exit door</span>		
Wall Type	<span style="border: 1px solid black; padding: 2px;">Drywall</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Carpet is New</span>		
Flooring	<span style="border: 1px solid black; padding: 2px;">Carpet</span>		<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>			

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Cobwebs in corners</span>
Walls	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean and paint</span>
Flooring	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Carpet is new</span>
HVAC Supply Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean with Wexcide disinfectant</span>
HVAC Return Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean with Wexcide disinfectant</span>
Ceiling at Supply Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>
Surfaces in Room	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>

## Observations

### Findings:

- Water damaged drywall around secondary exit door and in corridors at doors
- All exterior walls have water intrusion (elevated moisture levels)
- One stained ceiling tile
- Heavy dust and debris on environmental surfaces and clutter throughout the room (boxes, papers, etc.)
- Heavy dust and debris on HVAC supply and return grills
- Dust and debris on ceiling at HVAC supply grills
- Elevated humidity level

### Recommendations:

#### Site Based Maintenance:

- Replace stained ceiling tile
- Clean all environmental surfaces and encourage occupant to remove clutter
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations Division:

- Remove and replace drywall where water damaged - around secondary exit doors and in corridors at doors
- Evaluate and repair HVAC system to lower humidity level

#### Project Manager:

- Evaluate cause of water intrusion and initiate repair ASAP

# IAQ Assessment

Bethune Elementary School

Evaluation Requested July 21, 2005

Time of Day 11:50 am

Evaluation Date July 21, 2005

Outdoor Conditions      Temperature 93.1      Relative Humidity 58.8      Ambient CO2 404

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<span style="border: 1px solid black; padding: 2px;">810</span>	<span style="border: 1px solid black; padding: 2px;">70.9</span>	<span style="border: 1px solid black; padding: 2px;">72 - 78</span>	<span style="border: 1px solid black; padding: 2px;">74.6</span>	<span style="border: 1px solid black; padding: 2px;">30% - 60%</span>	<span style="border: 1px solid black; padding: 2px;">396</span>	<span style="border: 1px solid black; padding: 2px;">Max 700 &gt; Ambient</span>	<span style="border: 1px solid black; padding: 2px;">3</span>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">None</span>	
Ceiling Type	<span style="border: 1px solid black; padding: 2px;">2x4 Lay In</span>		<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">None</span>		
Wall Type	<span style="border: 1px solid black; padding: 2px;">Drywall</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Around secondary exit door</span>		
Flooring	<span style="border: 1px solid black; padding: 2px;">Carpet</span>		<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Carpet is New</span>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Cobwebs in corners</span>
Walls	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean and paint</span>
Flooring	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Carpet is new</span>
HVAC Supply Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean with Wexcide disinfectant</span>
HVAC Return Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean with Wexcide disinfectant</span>
Ceiling at Supply Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>
Surfaces in Room	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>

## Observations

### Findings:

- Visible microbial growth on vinyl bag and instrument cases in room
- Visible microbial growth on wood furniture in room
- Water damaged drywall around secondary exit door - frame rusted through
- All exterior walls have water intrusion (elevated moisture levels)
- Heavy dust and debris on environmental surfaces and clutter throughout the room (boxes, papers, etc.)
- Heavy dust and debris on HVAC supply and return grills
- Dust and debris on ceiling at HVAC supply grills
- Elevated humidity level

### Recommendations:

#### Site Based Maintenance:

- Dispose of vinyl bag and all instrument cases with visible microbial growth
- Clean wood furniture with Wexcide disinfectant solution to remove microbial growth
- Clean all environmental surfaces and encourage occupant to remove clutter
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations Division:

- Remove and replace all drywall where water damaged - around secondary exit door - and replace exterior door frame
- Evaluate and repair HVAC system to lower humidity level

#### Project Manager:

- Evaluate cause of water intrusion and initiate repair ASAP

# IAQ AHU Assessment

Bethune Elementary

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions      Temperature       Relative Humidity       Ambient CO2

AHU Room #	Temperature	Range	Relative Humidity	Range	CO2	Range
<input type="text" value="815"/>	<input type="text"/>	<input type="text" value="72 - 78"/>	<input type="text"/>	<input type="text" value="30% - 60%"/>	<input type="text"/>	<input 1,000="" ppm)"="" type="text" value("&lt;=""/>
Noticeable Odor	<input type="text" value="No"/>	Visible water damage / staining?	<input type="text" value="No"/>	Visible microbial growth?	<input type="text" value="No"/>	Amount of material affected
Ceiling Type	<input type="text" value="Metal Deck"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>	<input type="text" value="None"/>
Wall Type	<input type="text" value="Drywall"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>	<input type="text" value="None"/>
Flooring	<input type="text" value="Concrete"/>	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="Standing water on floor"/>	<input type="text" value="Standing water on floor"/>

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Room	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean Room"/>
Filters	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Change Filters"/>
Coil	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean Coils"/>
Pan	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Duct	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean inside of unit"/>
Motorized Damper Installed	<input type="text" value="Yes"/>		<input type="text"/>	
Damper Open / Operating	<input type="text" value="Yes"/>		<input type="text"/>	
Fresh Air Intake Un-obstructed	<input type="text" value="Yes"/>		<input type="text"/>	
Pollutant Sources Near Air Intake	<input type="text" value="Yes"/>		<input type="text" value="Return air grills are located on east side of building by bus loop"/>	
AHU Supply Water Temp	<input type="text" value="47"/>		AHU Return Water Temp	<input type="text" value="52"/>

## Observations

<p><b>Findings:</b></p> <ul style="list-style-type: none"> <li>- 3 AHU's in room all have the wrong size filters or are missing filler panels allowing air to bypass filters (unfiltered air causes dirty supply grills, dirty ceiling tiles at supply grills and IAQ complaints)</li> <li>- Heavy dust and debris on filters (one was so dirty that it was sucked out of the frame and into the air handler coil)</li> <li>- Standing water on floor from leaking valves</li> <li>- Dust and debris in room (newspapers, soda cans, food wrappers, etc.)</li> <li>- Dust and debris on HVAC coils</li> </ul> <p><b>Recommendations:</b></p> <p><b>Site Based Maintenance:</b></p> <ul style="list-style-type: none"> <li>- Install new filters - proper size</li> <li>- Thoroughly clean room</li> </ul> <p><b>Physical Plant Operations Division:</b></p> <ul style="list-style-type: none"> <li>- Clean HVAC coils and duct at units due to filter bypass</li> <li>- Evaluate and repair leaking chilled water valves and evaluate and repair to lower humidity levels throughout the building</li> </ul> <p><b>Project Manager:</b></p> <ul style="list-style-type: none"> <li>- Evaluate location of fresh air intakes and relocate away from bus loop</li> </ul>
--