

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

February 2, 2	2009 Signature on File	For Custodial Supervisor Use Only
TO:	Mr. Donald Cottrell, Principal Broadview Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Edward See, Project Manager Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment Portable OPR-2 – 301, 302, 303, 304	

On January 30, 2009 I conducted an assessment of Portable QPR-2 – 301, 302, 303 and 304 at **Broadview Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Leontine Butler, Area Superintendent
Dr. Desmond Blackburn, Area Director
Jeffrey S. Moquin, Executive Director, Support Operations
Henry Verdugo, Project Manager, Facilities and Construction Management
Gary Itzkowitz, Broward Teachers Union
Roy Jarrett, Federation of Public Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

	Broadview Eler	mentary School		Evaluation Red	January 28, 2009
Time of Day				Evaluat	ion Date January 30, 2009
Outdoor Conditions	Temperature	74.9	Relative Humidity	762	Ambient CO2 395
l	erature Range 72.8 72 - 78	Relative Humidity	Range 30% - 60%	CO2	Range # Occupants Max 700 > Ambient 14
Noticeable Odor	No	Visible water damage / staining	Visible microg? growth?		unt of material affected
Ceiling Type	2 x 4	No No	No No		None
Wall Type	Tackable	No	No		None
Flooring	12 x 12	No	No		None
	Clean Minor / Deb		ı	Corrective A	ction Required
Ceiling	Yes	No			
Walls	Yes	No			
Flooring	Yes	No			
HVAC Supply Grills	Yes	No			
HVAC Return Grills	Yes	No			
Ceiling at Supply Grills	Yes	No			
Surfaces in Room	Yes	No			
Diservations Findings: Portable - Environmental parar Recommendations: Site Based Maintena - Continue to monitor appropriate	meters were accepta ance:			at and debris ac	cumulation and clean as

0811

Location Number

	Broa	dview Eleme	entary School		Evaluati	ion Requested	January 28, 2009		
Time of Day					E	Evaluation Date	January 30, 2009		
Outdoor Conditions	s Te	mperature	74.9	Relative Humidity	762	Ambier	nt CO2 395		
Fish Temp	perature	Range	Relative Humidity	Range	CO2	Ran	ge # Occupants		
P-302	70.4	72 - 78	57.3	30% - 60%	950	Max 700 :	> Ambient 10		
Noticeable Odor	No		Visible water damage / staining	obial	erial				
Ceiling Type	2 x 4		Yes	[3 ceiling tiles				
Wall Type	Tackab	ole	No	[None				
Flooring	12 x 1	2	No	No			None		
	Clean	Minor D / Debri		J	Correc	ctive Action Re	quired		
Ceiling	No	Yes	Yes Remove and replace ceiling tile						
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply Grill	s Yes	No	No						
HVAC Return Grills	s Yes	No	No						
Ceiling at Supply Grills	Yes	No	No						
Surfaces in Room	Yes	No	No						
L Observations									
Findings: Portable									
 3 stained ceiling tile Temperature was le 		ime of the as	ssessment						
Recommendations Site Based Mainten - Remove and replace Physical Plant Opera - Adjust thermostat to Physical Plant Opera	: nance: ce stained exations to exo o increase ations to ex	ceiling tiles a valuate for w temperature valuate HVA	and monitor. If sta vater intrusion. e. If temperature of C system.	aining returns, contact does not improve, col growth as well as dus	ntact CO	MPASS to gene	erate a work order for		

0811

Location Number

	Broadview Elen	nentary School		Evaluation	Requested January 28, 2009
Time of Day				Eva	luation Date January 30, 2009
Outdoor Conditions	Temperature	74.9	Relative Humidity	762	Ambient CO2 395
l	Perature Range 73.4 72 - 78	Relative Humidity	Range 30% - 60%	CO2 1096	Range # Occupants Max 700 > Ambient 18
Noticeable Odor	No	Visible water damage / staining	Visible micro growth?	bial A	mount of material affected
Ceiling Type	2 x 4	No	No		None
Wall Type	Tackable	No	No		None
Flooring	12 x 12	No	No		None
	Clean Minor I		l	Correctiv	ve Action Required
Ceiling	Yes No	No			
Walls	Yes No	No			
Flooring	Yes	No			
HVAC Supply Grills	Yes	No			
HVAC Return Grills	Yes No	No			
Ceiling at Supply Grills	Yes	No			
Surfaces in Room	Yes No	No			
Dbservations					
Findings: Portable - Environmental parar Recommendations:	neters were accepta	ble at the time of th	ne assessment		
Site Based Maintena - Continue to monitor appropriate		signs of microbial g	rowth as well as dus	st and debri	s accumulation and clean as

0811

Location Number

Broadview Elementary School					School			Evaluati	on Re	quested [Janua	ary 28, 2	2009
Time of Day								E	valuat	tion Date [Janua	ary 30, 2	2009
Outdoor Condi	tions	Tem	perature	74.9	9	Relative Hui	midity	762		Ambier	nt CO2	395	
Fish ⁷	Tempera	ature F	Range	Relative	e Humidity	Range		CO2		Ran	ge	# Occi	upants
P-304	72.	2 7	2 - 78	7	0.6	30% - 60%		798		Max 700 :	> Ambie	ent 🗀	16
Noticeable Od	or _	No		_	ible water e / staining		e micro owth?	bial	Amo	unt of mat affected	erial		
Ceiling Type		2 x 4			Yes		No			1 ce	eiling tile	9	
Wall Type		Tackable	9		Yes		No		1 square foot				
Flooring		12 x 12			No		No				None		
	С	lean	Minor D / Debri		Needs Cleaning			Correc	tive A	Action Re	quired		
Ceiling		No	Yes]	Yes		R	emove a	and re	eplace cei	ling tile)	
Walls	[No	Yes]	Yes			Clea	n as	appropria	ite		
Flooring		Yes	No]	No								
HVAC Supply	Grills [Yes	No]	No								
HVAC Return (Grills [No	Yes]	Yes		CI	ean witl	h Wex	cide disi	nfectan	t	
Ceiling at Supp Grills	ply [Yes	No]	No								
Surfaces in Ro	oom [Yes	No		No								

0811

Location Number

Observations

Findings: Portable QPR-2

- Humidity level was elevated at the time of the assessment
- One stained ceiling tile at West wall
- Visible staining on wall at restroom door @1 square foot
- Dust and debris on HVAC return grills
- Visible microbial growth on exterior of portable side and windows

Recommendations:

Site Based Maintenance:

- Remove and replace stained ceiling tile and monitor. If staining returns, contact COMPASS to generate a work order for Physical Plant Operations to evaluate for water intrusion.
- Wipe down wall at restroom door
- Clean HVAC return grills with Wexcide disinfectant solution
- Wash down exterior of portable to remove microbial growth
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level