

## managing risk with responsibility

Risk Management Department			Fax:	754 321-1900 754 321-1917
September 8	3, 2014	Signature on File	For Custodial S	upervisor Use Only
TO:	Donald Lee, Principal Broadview Elementary School			ues Addressed ues Not Addressed
FROM:	•	er, Project Manager agement Department	-	
SUBJECT:	Indoor Ai	r Quality (IAQ) Assessment	-	

On August 28, 2014, I conducted an assessment at **Broadview Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

DM/tc Enc.

## **IAQ Assessment**

Broadview Elementary Eval	Aluation Date August 28, 2014 Time of Day 2:00 PM
Outdoor Conditions Temperature 89.6	Relative Humidity 70.1 Ambient CO2 425
Fish         Temperature         Range         Relative Hum           301         74.4         72 - 78         62.8	midity Range CO <sup>2</sup> Range # Occupants  30% - 60% 763 MAX 700 > 6  Ambient 6
Noticeable Odor Yes Visible water da staining?	
Ceiling 2' X 4' Lay in Yes	No 8 tiles
Walls Drywall Yes	No
Floor 12" x 12" Vinyl No	No
Ceiling Clean No HVAC Su Grills Cle	
Flooring Clean Yes Inside of Duct Clea	
Room Surfaces Yes Ceiling at Clean Grills Cle	at Supply lean Yes
Trash Removed Yes Exhaust Fans V	Cleaners in Room No
Signs of Pests No Drain Tr  Room Cluttered No Food if Stored in in Sealed Contain	III ROOIII
Mechanical Equipment Location Bard like HVAC system	tem in classroom Mechanical Room Clean N/A
Filters Installed Properly Yes Filter	ers Clean Yes Inside of HVAC Unit Clean Yes
Condensate Pan Clean Yes Cooling Co	coil Clean Yes
Fresh Air Intake Location  Pollutant Sources Near Air  No	xterior wall  ▼ Fresh Air Intake Free of Obstruction  Yes
intake	
	are wet per moisture indicator. Wet wood above ceiling tile has c. Water intrusion around windows. Supply grills rusty.
Corrective Actions to be Completed by Site Based Sta	
	▼ Evaluate and repair roof leaks ▼  Evaluate and repair cause of water damage ▼
	▼ Evaluate and repair cause of water damage ▼ Remove and replace wall material as necessary ▼
	▼ Repair HVAC to reduce humidity level ▼
	▼ Remove and replace HVAC supply grills ▼
	▼ Replace ceiling tiles ▼
	<del> </del>

▼

▼

Remove and replace HVAC supply grills

Replace ceiling tiles

▼

▼

▼

▼

Remove and replace HVAC supply grills

Replace ceiling tiles

Replace water damaged floor tile
Evaluate wooden cabinet - water damage

▼

<u>\*</u>

## **IAQ Assessment**

Broadview Elem	entary Evaluation Da	August 28, 2014	Time of Day 2:00 PM	И
Outdoor Conditions Temperature	89.6 Relativ	e Humidity 70.1	Ambient CO2 425	
Fish         Temperature         Range           304         75.2         72 - 78	Relative Humidity 62.9 30	Range <u>Co</u> 9% - 60% 56		
Noticeable Odor Yes	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	Yes	Yes	6 tiles	
Walls Drywall	Yes	No		
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean No Walls Clean No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	lo
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	es
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room	lo
Signs of Pests No	Drain Traps Wet	Yes	Air Fresheners	
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	in Room	lo
Mechanical Equipment Location Bare	d like HVAC system in cla	assroom	Mechanical Room Clean N	/A
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean Y	es
Condensate Pan Clean Yes	Cooling Coil Clean	Yes		
Fresh Air Intake Location Beh	ind Bard unit/Exterior wa	ıll 🔻	Fresh Air Intake Free	es
Pollutant Sources Near Air Intake		▼	or obstruction	
Observations				
Open ceiling tiles due to extensive ro microbial growth. Microbial growth al boards are wet. Strong odor in classr	so on ductwork. Water ir			
Corrective Actions to be Completed			ons to be Completed by PPO	
	▼		and repair roof leaks pair cause of water damage	▼
	▼		ce wall material as necessary	▼
	▼	Repair HVAC	to reduce humidity level	▼
	▼		eplace HVAC supply grills	▼
	▼	Кері	ace ceiling tiles	<b>▼</b>

## **IAQ Assessment**

Broadview	v Elementary Evaluation	on Date August 28, 20	14 <b>Time of Day</b> 2:00 PM	Л					
Outdoor Conditions Temper	rature 89.6 Re	elative Humidity 70.1	Ambient CO2 425						
	ange Relative Humidity 2 - 78 70.4		CO <sup>2</sup> Range # Occupation    MAX 700 > 3  Ambient						
Noticeable Odor No	Visible water damag staining?	le / Visible microbia growth?	Amount of material affected						
Ceiling 2' X 4' Lay in	Yes	No	4 tiles						
Walls Drywall	Yes	No							
Floor 12" x 12" Vinyl	No	No							
Ceiling Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	es					
Walls Clean Yes Flooring Clean Yes	Inside of Sup Duct Clean	Yes	Inside of Return Duct Clean	es					
Room Surfaces Yes Clean	Ceiling at Su Grills Clean	yes Yes							
Trash Removed Yes	Exhaust Fans Worl		Unapproved Chemicals / Cleaners in Room	lo					
Signs of Pests No	Drain Traps	Wet Yes	Air Fresheners N	lo					
Room Cluttered No	Food if Stored in Roc in Sealed Containers	· · ·   NI/A	in Room						
Mechanical Equipment Location	Bard like HVAC system i	in classroom	Mechanical Room Clean N	/A					
Filters Installed Properly Ye	s Filters Cl	ean Yes	Inside of HVAC Unit Clean You	es					
Condensate Pan Clean Yes	S Cooling Coil Cl	ean Yes							
Fresh Air Intake Location	Fresh Air Intake Free of Obstruction	es							
Pollutant Sources Near Air Intake	No	Į,							
Observations									
South wall wet. Ceiling tiles are	wet. A/C unit not working	properly - high humidit	y <b>.</b>						
Corrective Actions to be Completed by Site Based Staff  Corrective Actions to be Completed by PPO									
	▼		te and repair roof leaks	▼					
	▼		repair cause of water damage	<b>│</b> ▼					
	▼		to wall material	┸					
	▼		olace wall material as necessary  AC to reduce humidity level	<b>▼</b>					
	▼	1.cpaii 1147		V					
				$\neg \neg$					