Report: Responsible Party

CASTLE HILL ELEMENTARY

Walkthrough Date: 04/26/2006 Temp RH CO2
Outdoor Parameters: 92.6 53.1 390

Room	Priority	Responsible	Answer	Recommendation
103B	Inside Parameters:	Temp	RH	CO2
		73.3	69.3	604
	1	PPO	Humidity was slightly elevated at time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
	1	PPO	Occupant advised that room is usually very hot.	Physical Plant Operations to evaluate HVAC for proper operation
Room	Priority	Responsible	Answer	Recommendation
103C	Inside Parameters:	Temp	RH	CO2
		73.3	68.5	612
	1	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
Room	Priority	Responsible	Answer	Recommendation
104	Inside Parameters:	Temp	RH	CO2
		76.4	60.8	1137
	2	PPO	of assessment - 10% greater than outdoors.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
	2	PPO	Environmental parameters were not within acceptable range at the time of assessment	Physical Plant Operations to evaluate HVAC for proper operation
			Only one vent was working at the time of	Physical Plant Operations to evaluate HVAC for proper

	1	PPO	assessment.	operation
	2	PPO	Carpet was stained, torn, rippled or buckled.	Physical Plant Operations to evaluate and repair/replace as appropriate.
Room	Priority	Responsible	Answer	Recommendation
106	Inside Parameters:	Temp	RH	CO2
		72.9	65.5	967
	1	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
	2	PPO	Carpet was stained, torn, rippled or buckled.	Physical Plant Operations to evaluate and repair/replace as appropriate.
Room	Priority	Responsible	Answer	Recommendation
107	Inside Parameters:	Temp	RH	CO2
		73.3	64	1064
	1	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
Room	Priority	Responsible	Answer	Recommendation
108	Inside Parameters:	Temp	RH	CO2
		73.8	61.3	820
	1	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC for proper operation and repair as appropriate to lower humidity level.
Room	Priority	Responsible	Answer	Recommendation
114	Inside Parameters:	Temp	RH	CO2
	II II	74.6	60.4	1094

Humidity was slightly elevated at the time Physical Plant Operations to evaluate HVAC system for

	1	PPO	of assessment.	proper operation and repair as appropriate to lower humidity level.
Room	Priority	Responsible	Answer	Recommendation
1111/11	Inside Parameters:	Temp	RH	CO2
		72.2	69	837
	1	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC for proper operation
	1	PPO	Humidity was slightly elevated at time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
Room	Priority	Responsible	Answer	Recommendation
120	Inside Parameters:	Temp	RH	CO2
		72.3	54.2	911
	1	PPO	Occupant advised that termperature fluctuates.	Physical Plant Operations to evaluate HVAC for proper operation
Room	Priority	Responsible	Answer	Recommendation
121	Inside Parameters:	Temp	RH	CO2
		72.8	68.9	877
	1	PPO	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	1	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
Room	Priority	Responsible	Answer	Recommendation
122	Inside Parameters:	Temp	RH	CO2
		72.8	68.9	877

	1	PPO	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
Room	Priority	Responsible	Answer	Recommendation
141/ 1	Inside Parameters:	Temp	RH	CO2
		69.7	60.4	602
	1	PPO	Humidity was slightly elevated at time of assessment.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
	2	PPO	Environmental parameters were not within acceptable range at the time of assessment	Physical Plant Operations to evaluate HVAC for proper operation