

managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

FISH 130

June 23, 2008	Signature on File	For Custodial Supervisor Use Only		
TO:	Ms. Dee Knabb, Principal Central Park Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed		
FROM:	Richard Rosa, Project Manager Facilities and Construction Management			
SUBIECT:	Indoor Air Quality (IAQ) Assessment			

On June 9, 2008 I conducted an assessment of FISH 130 at Central Park Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1637.

cc: Dr. Verda Farrow, Area Superintendent
Jan Beal, Area Director
Jeffrey S. Moquin, Director, Risk Management
Gerry Usallan, Project Manager, Facilities and Construction Management
Ruby Fitzgerald, Broward Teachers Union
Roy Jarrett, National Federation of Public and Private Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

RR/tc Enc.

-		ant Elementary				· L	·	
Time of Day	12:10 pm					Evaluation Date	June 9, 2008	
Outdoor Condition	ons Tem	perature 8	3.5	Relative Hum	nidity 62.	7 Ambient	t CO2 292	
Fish Ter	mperature F	Range Relat	ive Humidity	Range	CO2	Rang	e # Occupants	
130	70.5 7	2 - 78	55.8	30% - 60%	330	Max 700 >	Ambient 1	
Noticeable Odor No			Visible water Visible microbial damage / staining? growth?			Amount of mate affected	rial	
Ceiling Type	2 x 4 Lay	ln	No	1	No	N	lone	
Wall Type [e Drywall/Tackable/AKI		Yes		'es	98 Square Feet		
Flooring	12 x 12 Vinyl		No		No	N	None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ective Action Req	uired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		Remove and replace per survey		survey	
Flooring	Yes	No	No					
HVAC Supply Gr	ills Yes	No	No					
HVAC Return Gr	ills No	Yes	Yes		Clean wi	th Wexcide disin	fectant	
Ceiling at Supply Grills	/ Yes	No	No					
Surfaces in Roor	m No	Yes	Yes		Cle	ean as appropriat	е	

IAQ Assessment

Central Park Flementary School

2641

June 9, 2008

Location Number

Evaluation Requested [

Observations

Findings:

- Dust and debris on HVAC return grills
- Minor dust on elevated surfaces throughout the room
- Four tackboard panels are water damaged and need to be replaced. Drywall behind the tackboard is dry. Ceiling tiles above tackboard panels are dry and unstained.

Recommendations:

Site Based Maintenance:

- Clean HVAC return grills with Wexcide disinfectant solution
- Clean elevated surfaces throughout the room
- Thoroughly clean room after remediation is completed
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Environmental Department contractor will be removing tackboard panels and room will be accessible for Physical Plant Operations to repair the wall system by July 14, 2008.

Physical Plant Operations:

- Repair wall system as appropriate. Schedule to begin work on July 14, 2008.