

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

August 11, 2005 Signature on File

TO: Mr. William Roach, Principal

Coconut Creek Elementary School

FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental

Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable 16H and FISH 852

On August 1, 2005 the IAQ Assessment Team conducted an assessment of Portable 16H and FISH 852 at Coconut Creek Elementary School. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent

Sharon Airaghi, Area Director

Jeffrey S. Moquin, Director, Risk Management

Philip Kaufold, Project Manager II, Facilities and Construction Management

Ruby Fitzgerald, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

IAQ Assessment **Evaluation Requested** July 24, 2005 Coconut Creek Elementary School **Evaluation Date** August 1, 2005 2:30 pm Time of Day **Outdoor Conditions Temperature** 93 58.4 **Relative Humidity Ambient CO2** 312 Temperature Fish CO₂ **Relative Humidity** Range Range Range # Occupants P-16H 71.7 54 365 72 - 78 30% - 60% Max 700 > Ambient 2 Visible water Visible microbial **Amount of material Noticeable Odor** Yes damage / staining? growth? affected None **Ceiling Type** Gypsum No No **Wall Type** Gypsum None No No **Flooring** Tile None No No Clean **Minor Dust** Needs **Corrective Action Required** Cleaning / Debris Ceiling Yes No No Yes No No Walls **Flooring** Yes No No HVAC Supply Grills | Yes No No HVAC Return Grills | Yes No No **Ceiling at Supply** Yes No No **Grills Surfaces in Room** Yes No No **Observations** Findings: No visible signs of microbial growth or signs of water intrusion No moisture detected in walls throughout the portable Slight odor from paint is emanating from the wooden panted deck General cleanliness was acceptable at the time of assessment Recommendations: Site Based Maintenance:

Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

IAQ Assessment **Evaluation Requested** July 24, 2005 Coconut Creek Elementary School **Evaluation Date** August 1, 2005 2:00 pm Time of Day **Outdoor Conditions Temperature** 93 57.6 **Relative Humidity Ambient CO2** 312 Temperature Fish CO₂ **Relative Humidity** Range Range Range # Occupants 74 59.1 395 852 72 - 78 Max 700 > Ambient 2 30% - 60% Visible water Visible microbial **Amount of material Noticeable Odor** No damage / staining? growth? affected **Ceiling Type** 2 x 4 Lay In No None No **Wall Type** Drywall West wall joint (bottom) Yes Yes **Flooring** Tile None No No Clean **Minor Dust Needs Corrective Action Required** Cleaning / Debris Ceiling Yes No No Yes No Walls No **Flooring** Yes No No HVAC Supply Grills Yes No No No HVAC Return Grills | Yes No **Ceiling at Supply** Yes No No **Grills Surfaces in Room** Yes No No **Observations**

Findings:

- Visible microbial growth on bottom West wall at wall joint
- No moisture detected in the walls (including the West wall)
- General cleanliness was acceptable at the time of assessment

Recommendations:

Site Based Maintenance:

Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate interior and exterior West wall for signs of water intrusion
- Evaluate and repair/replace bottom West wall at wall joint as appropriate