

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

March 7, 2006 Signature on File

TO: Mrs. Cheri Zahn, Principal

Croissant Park Elementary School

FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental

Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 755

On March 3, 2006 the IAQ Assessment Team conducted an assessment of FISH 755 at **Croissant Park Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent

Dr. Roberta Insel, Area Director

Jeffrey S. Moquin, Director, Risk Management

Matt Decker, Project Manager, Facilities and Construction Management

Jerrod Neal, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc

Enc.

Time of Day	1:05 pm]			Ev	aluation Date M	larch 3, 2006
Outdoor Conditions Temperature 85.6 Relative Humidity 45.7 Ambient CO2 541							
Fish	Temperature	Range Rel	ative Humidity	Range	CO2	Range	# Occupants
755	74.9	72 - 78	69.7	30% - 60%	578	Max 700 > Aml	bient 1
Noticeable Odor Yes			Visible water nage / staining	Visible micro growth?	bial /	Amount of material affected	
Ceiling Type	Ceiling Type 2 x 4 Lay In		Yes	No No		4 ceiling tiles	
Wall Type	Plaster		Yes	Yes		2' x 4'	
Flooring	Tile		Yes	No		Variou	s
	Clean	Minor Dust / Debris	Needs Cleaning		Correcti	ve Action Require	d
Ceiling	No	Yes	Yes		Replace as appropriate		
Walls	No	Yes	Yes	F	Repairr/eplace as appropriate		e
Flooring	No	Yes	Yes		Clean and sanitize		
HVAC Supply	Grills No	Yes	Yes	CI	lean with	Wexcide disinfecta	ant
HVAC Return (Grills Yes	No	No				
Ceiling at Support Grills	ply Yes	No	No		Clean	as appropriate	
Surfaces in Ro	oom No	Yes	Yes		Clean	as appropriate	

IAQ Assessment

Croissant Park Elementary School

0221

March 2, 2006

Location Number

Evaluation Requested

Observations

Findings: Room is currently not being used

- Visible microbial growth on wall under emergency exit
- 4 stained ceiling tiles
- Visible microbial growth in false ceiling plenum at conduit entry points above whiteboard
- Dust and debris on floor
- Dust and debris on HVAC supply grills
- Dust build up on environmental surfaces throughout the room
- Coated paper on walls
- Humidity level was elevated at the time of the assessment

Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Thoroughly clean and sanitize floor
- Thoroughly clean environmental surfaces throughout the room
- Remove coated paper from walls
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate wall under emergency exit for source of water intrusion and repair as appropriate. Remove and replace wall material as necessary
- Evaluate false ceiling plenum for leaks and repair as appropriate. Replace ceiling tiles as necessary.
- Evaluate and repair HVAC system to lower humidity level