

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

November 19, 2	2007 Signature on File
TO:	Mr. Robert Schneider, Principal Davie Elementary School
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 122

For Custodial Supervisor Use Only						
	Custodial Issues Addressed					
	Custodial Issues Not Addressed					
-						

On October 17, 2007 I conducted an assessment of FISH 122 at **Davie Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joel Herbst, Area Superintendent Steven Friedman, Area Director Jeffrey S. Moquin, Director, Risk Management Frank Girardi, Project Manager, Facilities and Construction Management Dianne Watts, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

		IAQ Assessment			Locatio	on Number	2801	
Davie Elementary School					Evaluat	ion Requested	October	15, 2007
Time of Day	9:55 am				E	Evaluation Date	October	17, 2007
Outdoor Condit	ions Ten	nperature	82.9	Relative Humidit	y 70.3	Ambie	nt CO2	430
Fish T	emperature	Range Re	lative Humidity	Range	CO2	Ran	ge #	Occupants
122	73 7	/2 - 78	52.6	30% - 60%	775	Max 700	> Ambient	20
Noticeable Odd	or No	da	Visible water mage / staining	Visible mic ? growth		Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Wall Type Tackboard		Yes	No		Old staining		
Flooring	12 x 12 Vi	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	Νο					
HVAC Supply G	Grills Yes	No	No					
HVAC Return G	Brills Yes	No	No					
Ceiling at Supp Grills	ly Yes	No	No					
Surfaces in Roo	om Yes	No	No					

Observations

Findings:

- Classroom being used as an art room

- Old water damage/staining on tackboard wall surfaces. All walls were dry at the time of the assessment (8-10% WME).

- 2 large air purifiers and 11 cardboard boxes (stored items) in room

- Large (29 gallon) trash can overflowing with emply cardboard boxes

- Sink trap was wet with no signs of staining or leaking

Recommendations:

Site Based Maintenance:

- Remove cardboard boxes from room. All stored items should be kept in plastic containers.

- Initiate a work order to paint tackboard wall surfaces

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate