

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

July 24, 2006 Signature on File

TO: Mr. John Hodge, Principal

Deerfield Beach Elementary School

FROM: Kenneth I. Partee, Project Manager Occupational Health and Environmental Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable R-6 and FISH 109

On July 19, 2006 Aston Henry and I conducted an assessment of Portable R-6 and a follow up assessment of FISH 109 at **Deerfield Beach Elementary School**. The assessment consisted of a reevaluation walkthrough of the previously identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included reviewing previously generated work orders as well as observations of the areas of concern as stated in the IAQ Assessments performed on August 31, 2005 by Aston Henry and on September 13, 2005 by Robert Krickovich. Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent

Craig Anderson, Area Director

Jeffrey S. Moquin, Director, Risk Management

David DeWald, Project Manager, Facilities and Construction Management

Jamie Daniels, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

	Deerfield	Beach Eleme	entary School	Evaluation Requested July 18, 2006					
Time of Day	11:20 a.m.				E	Evaluation Date	July 19, 2006		
Outdoor Cond	litions Te	emperature	90.1	Relative Humid	ity 63.6	Ambie	nt CO2 527		
Fish	Temperature	Range	Relative Humidity	Range	CO2	Ran	ige # Occupants		
R-6		72 - 78		30% - 60%			> Ambient		
Noticeable Odor No			Visible water damage / staining	crobial h?	Amount of material affected				
Ceiling Type	2 x 4 Lay In		Yes	Yes		Various			
Wall Type	Plaster		No	Yes		Various			
Flooring	Tile		No	No			None		
	Clean	Minor Dı / Debri			Correc	ctive Action Re	equired		
Ceiling	No	Yes	Yes		Rep	lace stained ti	les		
Walls	No	Yes	Yes		Clean witl	h Wexcide disi	infectant		
Flooring	Yes	No	No						
HVAC Supply	Grills No	Yes	Yes		Clean witl	h Wexcide disi	infectant		
HVAC Return	Grills No	Yes	Yes		Clean witl	h Wexcide disi	infectant		
Ceiling at Sup Grills	oply No	Yes	Yes		Clea	anas appropria	ate		
Surfaces in R	oom Yes	No	No						

IAQ Assessment

0011

Location Number

Observations

Findings:

- Southeast section of the unit Temperature 69.5, Relative Humidity 68.9, CO2 531
- Southwest section of the unit Temperature 71, Relative Humidity 69.1, CO2 522
- Visible microbial growth on walls throughout the unit
- Temperature was low and humidity level was elevated throughout the unit
- Dust dirt impaction on ceiling tiles at HVAC supply grills
- Dust and debris on HVAC supply and return grills
- Dust and debris on HVAC coils
- Damaged insulation around A/C unit ducts
- Visible microbial growth and staining on various ceiling tiles throughout the unit
- Southwest section damaged plaster, baseboard and tile under A/C unit

Recommendations:

Site Based Maintenance:

- Clean walls with Wexcide disinfectant solution
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Increase temperature to 72 degrees
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate roof for leaks in Northwest and Northeast section of unit and repair
- Replace ceiling tiles for staining and visible growth as appropriate throughout the unit
- Remove and replace ceiling tiles around HVAC supply grills
- Evaluate HVAC for proper operation and adjust to lower humidity level
- Clean HVAC coils and remove and replace damaged insulation around A/C unit ducts
- Evaluate and repair damaged plaster, baseboard and tile in Southwest section of unit

Deerfield Beach Elementary School							Evaluation Requested July 19, 2				July 19, 2006
Time of Day	1:3	30 pm						E	Evaluation	Date [July 19, 2006
Outdoor Conditions Temperature Relative Humidity Ambient CO2											
Fish	Tempe	rature	Range	Relative	Humidity	Range		CO2		Ranç	ge # Occupants
109 72 - 78 30% - 60% Max 700 > An								> Ambient			
Noticeable Odor Yes				Visible water damage / staining		Visible microbial ? growth?			Amount of material affected		
Ceiling Type	2 x 4 Lay In		In	Yes		Yes		Various			
Wall Type		Plaster		No		[No		None		None
Flooring		Wood		_	'es	[No			V	/arious
	(Clean	Minor D		Needs Cleaning	l		Correc	ctive Actio	on Red	quired
Ceiling		No	Yes		Yes		R	Remove a	and replac	e ceil	ing tiles
Walls		Yes	No]	No						
Flooring		No	Yes]	Yes			Evalu	ate floor	from I	eak
HVAC Supply	Grills	Yes	No		No						
HVAC Return	Grills	Yes	No		No						
Ceiling at Sup Grills	ply	Yes	No]	No						
Surfaces in Ro	oom	Yes	No		No						

IAQ Assessment

0011

Location Number

Observations

Findings:

- Ceiling tiles saturated with visible microbial growth in various areas of the room
- Floor to the back of the room (separated by a door) is soaked

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate for cause of saturated ceiling tiles and repair. Replace ceiling tiles as appropriate.
- Evaluate floor for saturation and repair/replace floor material as appropriate

Note - Work order FM12886 was reopened to address