

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

August 8, 2005

TO: Ms. Constantina Robinson, Principal

Deerfield Park Elementary School

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 008 and 603

On July 19, 2005 the IAQ Assessment Team conducted an assessment FISH 008 and 603 at **Deerfield Park Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

Craig Anderson, Area Superintendent
Craig Anderson, Area Director
Jeffrey S. Moquin, Director, Risk Management
Rigo Zubizarreta, Project Manager II, Facilities and Construction Management
LaFrances Trotter, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

IAQ Assessment

	Deerfield Park E	lementary School	Evaluation Requested July 19, 2005				
Time of Day 1:	40 pm			Eva	luation Date J	uly 19, 2005	
Outdoor Conditions	Temperat	ure 89.5	Relative Humidity	63.4	Ambient CO	2 415	
Fish Tempe	erature Range	Relative Humid	^{lity} Range	CO2	Range	# Occupants	
008	70 72 - 78	67.2	30% - 60%	394	Max 700 > Aml	bient 2	
Noticeable Odor	No	Visible wate damage / stain		bial A	mount of material affected		
Ceiling Type	2 x 4 Lay In	No	No		None		
Wall Type	Orywall/Plaster	No	No		None		
Flooring	12 x 12 Vinyl	No	No		None		
		or Dust Need Debris Cleani	-	Correctiv	e Action Require	d	
Ceiling	Yes	No No					
Walls	No	Yes	CI	Clean with Wexcide disinfectant			
Flooring	Yes	No					
HVAC Supply Grills	No	Yes	CI	lean with \	Vexcide disinfecta	ant	
HVAC Return Grills	Yes	No					
Ceiling at Supply Grills	No	Yes Yes		Clean	as appropriate		
Surfaces in Room	Yes	No No					

Observations

Findings: This is a corridor

- Visible microbial growth on walls in various areas throughout corridor (wall board is dry only surface growth)
- Custodian indicated that painters were on site and had the HVAC controls bypassed
- Dust and debris on HVAC supply grills
- Dust and debris on ceiling at HVAC supply grills
- Elevated humidity level
- Temperature was low at the time of assessment

Recommendations:

Site Based Maintenance:

- Clean walls with Wexcide disinfectant solution
- Clean HVAC supply grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Adjust thermostat
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate and repair HVAC system to lower humidity level

IAQ Assessment

Deerfield Park Elementary School				Evaluation Requested July 19, 2005				
Time of Day	1:40 pm				i	Evaluation Date	July 19, 2005	
Outdoor Condi	tions T	emperature	89.5	Relative Hun	nidity 63.4	Ambien	t CO2 415	
· · · · · · · · · · · · · · · · · ·	- Formmaratura							
	Temperature	Range	Relative Humidity	Range	CO2	Rang	I	
603	67.5	72 - 78	72.4	30% - 60%	376	Max 700 >	Ambient 2	
Noticeable Od	or No		Visible water damage / staining		microbial owth?	Amount of mate affected	rial	
Ceiling Type	2 x 4 L	ay In	Yes	Y	'es	16 sq	uare feet	
Wall Type	Drywall/F	Plaster	No		No	None		
Flooring	12 x 12	Vinyl	No		No	None		
	Clean	Minor D / Debri		l	Correc	ctive Action Req	uired	
Ceiling	No	Yes	Yes		Clea	n two ceiling til	es	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return (Grills No	Yes	Yes		Clean wit	h Wexcide disin	fectant	
Ceiling at Supp Grills	ply No	Yes	Yes		Clea	an as appropriat	te	
Surfaces in Ro	oom Yes	No	No					

Observations

Findings:

- Visible microbial growth on two ceiling tiles around return grill above entry door to room 604C
- Custodian indicated that painters were on site and had the HVAC controls bypassed
- Dust and debris on HVAC return grills
- Dust and debris on ceiling at HVAC supply grills
- Elevated humidity level
- Temperature was low at time of assessment

Recommendations:

Site Based Maintenance:

- Clean ceiling tiles around return grill above entry door to room 604C
- · Clean HVAC return grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Adjust thermostat
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate and repair cause of stained ceiling tiles over entry door to room 604C
- Evaluate and repair HVAC system to lower humidity level