

managing risk with responsibility

Aston A. Henry, Supervisor	Telephone:	754 321-1900
Risk Management Department	Fax:	754 321-1917

August 27, 2010 Signature on File

TO: Ms. Josetta Campbell, Principal

Fairway Elementary School

FROM: Aston A. Henry, Supervisor

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 615 and 616

On August 17, 2010 I conducted an assessment of FISH 615 and 616 at **Fairway Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Joel Herbst, Area Superintendent

Valerie Wanza, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance

Sonja Coley, Project Manager, Facilities and Construction Management

Iris Froehlich, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AH/tc Enc.

	Fair	way Elementary	School		Evaluati	on Requested	August 11, 2010	
Time of Day	3:20 pm				E	valuation Date	August 17, 2010	
Outdoor Conditions Temperature 92.9 Relative Humidity 55.7 Ambient CO2 327								
Fish Temperature Range 615 65.8 72 - 78 Noticeable Odor No Ceiling Type 2 x 4 Lay In Wall Type Drywall		2 - 78 V dama	ive Humidity 62.7 3isible water age / staining? Yes No	gro	CO2 403 microbial owth? lo	Range # Occupants Max 700 > Ambient 2 Amount of material affected 2 ceiling tiles Various		
Flooring	Tile		No	N	lo		None	
Ceiling	Clean	Minor Dust / Debris Yes	Needs Cleaning Yes			ctive Action Re		
Walls	No	Yes	Yes		Wipe down v	with Wexcide o	disinfectant	
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					
bservations								

IAQ Assessment

1641

Location Number

0

Findings

- Stained ceiling tiles around HVAC supply grills
- Visible microbial growth on walls and doors
- Temperature was low and humidity was slightly elevated
- Dust and debris on HVAC supply grills

Site Based Maintenance:

- Remove and replace stained ceiling tiles
- Wipe down walls and doors with Wexcide disinfectant solution
- Clean HVAC supply grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity

		F	airway Elen	nentary Schoo	<u>l</u>			Evaluat	ion Re	equested	Augus	t 11, 2010
Time of Day	3	:20 pm						E	Evalua	tion Date	Augus	t 17, 2010
Outdoor Cond	litions	Т	emperature	92.9	Rel	ative H	umidity	55.7	7	Ambie	nt CO2	327
Fish		erature 64.9	Range	Relative Hum	— ·	Range		CO2 391		Ran	•	# Occupants
616 Noticeable O		No] 72 - 78 	Visible w	ater		le micro	bial		Max 700 Amount of terial affection		nt 2
Ceiling Type		2 x 4 La	ay In	Yes	g :]	[No				eiling tiles	
Wall Type		Dryw	rall	No	J	[Yes			V	/arious	
Flooring		Tile	;	No]	[No				None	
		Clean	Minor I / Deb	- 401	eds ining			Corre	ctive /	Action Re	equired	
Ceiling		No	Yes	S Y	es		R	emove a	and re	place cei	ling tiles	
Walls		No	Yes	S Y	es		Wipe	e down	with V	Vexcide o	disinfecta	nt
Flooring		Yes	No		lo							
HVAC Supply	/ Grills	s Yes	No		lo							
HVAC Return	Grills	Yes	No		lo							
Ceiling at Sup Grills	pply	Yes	No		lo							
Surfaces in R	oom	Yes	No		lo							

IAQ Assessment

1641

Location Number

Observations

Findings

- 2 stained ceiling tiles
- Visible microbial growth on walls
- Temperature was low and humidity was slightly elevated
- Dust and debris build up on curtains
- Signs of water intrusion in Northeast corner of cafeteria
- Visible microbial growth on insulated chilled water lines in FISH 609

Site Based Maintenance:

- Remove and replace stained ceiling tiles
- Wipe down walls with Wexcide disinfectant solution
- Clean curtains
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity
- Evaluate for cause of water intrusion Northeast corner of room and repair as appropriate
- Evaluate insulated chilled water lines in FISH 609