THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

November 29	. 2017	Signature on File	_	0 . 11.10
1,0,011100129	, =017	0.0	For	Custodial Supervisor Use Only
TO:	Janice Crosby, Principa	1		Custodial Issues Addressed
	Flamingo Elementary			Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, P Environmental Health		_	
SUBJECT:	Indoor Air Quality (IA	Q) Assessment		

On January 31, 2017, I conducted an assessment at **Flamingo Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations
Shelley Meloni, Director, Pre-Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Greg Neiman, Area Supervisor, Zone 1
Kurt Wirz, Area Manager Trades
Gerald Devio, Supervisor II Custodial
Benjamin Osborne, Supervisor II Custodial
Mark Murray, Supervisor II Custodial
Broward Teachers Union
Federation of Public Employees

Multiple Room IAQ Assessment

		wuitiple Room IAQ		1	
Flar	mingo Elementary	School Evaluation Date	e November 27, 2017	Time of Day11	145
Outdoor Conditions	S Temperature	P 79.1 Relative	Humidity 56.0	Ambient CO2 39	6
Fish # of rooms FISH 123, 132 Similar complaints		125, 126, 127, 128, 131			
-	ty Range in the Roc	sessed was Between oms Assessed was Between	69.9 And 71.8 45.8 And 51.8 1006 And 1041	Acceptable Range Acceptable Range Acceptable Range Acceptable Acceptable Range Acceptable Ambie	60% 00 >
Walls Tac	No 4' Lay in k Board 12" Vinyl	Visible water damage / staining? No No No	Visible microbial growth? No No No	Amount of material affected	
Ceiling Clean Walls Clean Flooring Clean Room Surfaces Clean	Yes Yes No	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes No Yes	HVAC Return Grills Clean Inside of Return Duct Clean	Yes N/A
Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests Room Cluttered	Yes	Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes N/A	Air Fresheners in Room	No

Multiple Room IAQ Assessment

Flamingo Elemen	tary School Evaluation Date November 27, 20	17 Time of Day 1145
Outdoor Conditions Tempera	ature 79.1 Relative Humidity 56.0	Ambient CO2 396
IVAC System		
Mechanical Equipment Location	FISH 109 (clsrm 123) / 153 (clsrm 132)	Mechanical Room Clean Yes
Filters Installed Properly Yes	Filters Clean No	Inside of HVAC Unit Clean No
Condensate Pan Clean Yes	Cooling Coil Clean Yes	N/A in this section = Not Accessible
Fresh Air Intake Location	Roof top ▼	Fresh Air Intake Free
Pollutant Sources Near Air Intake	Not readily accessible-roof replacement ▼	of Obstruction

Observations

Building 1 of the school is currently in the midst of roof replacement. The contractor is reportedly working on the north side and staging materials on the south side. Occupants if FISH 123 and 132 complained upon initiation of work on the roof; likely a result of the staging of materials on the south side of the roof.

Generally the main areas of the rooms are clean (floor, walls, ceiling). There is a light layer of dust on stored items and bookshelves throughout the classroom. Due to the amount of items on the bookshelves it is not feasible for the entire area to be thoroughly cleaned each day. A moderate level of dust was observed within the computer storage carts for each room.

A light layer of dust was observed behind the northwest return grill in FISH 123. Rooms supplied by HVAC unit in FISH 109 were complaining that area is too cold. The HFSP reportedly adjusted the dampers to increase the temperature.

Corrective Actions to be Completed by Site Based Staff

Room too cluttered to clean properly	▼
Encourage occupant to reduce clutter	▼
Thoroughly clean elevated/horizontal surfaces	•
Store items in plastic containers with lids	▼
Coordinate dusting of items stored on shelves	▼
Assign dusting interior of computer carts	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Evaluate and repair HVAC system as needed	▼
JW39035 / EQ09390	▼
Set Temperature to 72 - 78 degrees	▼
Evaluate/Replace fresh air damper at HVAC	▼
mechanical room / roof (EQ09390)	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Flamingo Eler	mentary Evaluation Date	e November 27, 2017	7 Time of Day1	145
Outdoor Conditions Temperature	e 79.1 Relative	Humidity 56.0	Ambient CO2 3	96
Fish Temperature Range Port 830C 74.7 72 - 78		Range <u>CO</u> % - 60 %		16
Noticeable Odor	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	Yes	No	4 Ceiling Tiles	
Walls Tack Board	No	No		
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	Yes
Walls Clean Yes Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	Yes
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	N/a		
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A	Air Frankanara	\ \
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Location Wi	indow unit (2 present - 1 on))	Mechanical Room Clean	N/A
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean N/A	Cooling Coil Clean	Yes		
Fresh Air Intake Location Th	ru exterior wall	▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake)	▼	or obstruction	
Observations				
One area with two stained ceiling til	es at southwest corner of p	ortable. Second area	(north-near center) with t	wo

One area with two stained ceiling tiles at southwest corner of portable. Second area (north-near center) with two ceiling tiles with small stains at corners of tiles near lights. One window with what looks like termite debris near the southwest corner of the portable. Consider operation of both AC units to regulate CO2 levels and humidity on hotter / more humid days.

HFSP reports that ceiling and floor are new as of this past summer. Roof was repaired, but not completely replaced prior to replacement of ceiling and floor.

Corrective Actions to be Completed by Site Based Staff

▼
▼
▼
▼
▼
▼
▼
▼

Corrective Actions to be Completed by PPO

· · · · · · · · · · · · · · · · · · ·	
Evaluate and repair cause of stained ceiling tile	▼
Work order needed for pest control	▼
(maybe termite issue)	▼
	▼
	▼
	▼
	▼
	▼