

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

May 23, 2007	Signature on File	For C
TO:	Ms. Julianne Smith,, Principal Forest Hills Elementary School	
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management	
SUBJECT:	Indoor Air Quality (IAQ) Assessment Portable 1023PK	

 For Custodial Supervisor Use Only

 Custodial Issues Addressed

 Custodial Issues Not Addressed

On May 15, 2007 I conducted an assessment of Portable 1023PK at **Forest Hills Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joanne Harrison, Area Superintendent Jackie Haywood, Area Director Jeffrey S. Moquin, Director, Risk Management Denise Cone, Project Manager, Facilities and Construction Management Ruby Fitzgerald, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

		IAQ As	sessment	Location Number	2631
Forest Hills Elementary School			Evaluation Requested	May 15, 2007	
Time of Day 11	:30 am			Evaluation Date	May 15, 2007
Outdoor Conditions	Temperature	83	Relative Humidity	63.2 Ambie	ent CO2 598
	erature Range	Relative Humidity	Range	CO2 Rar	nge # Occupants
P-1023PK	69 72 - 78	53.5	30% - 60%	1067 Max 700	> Ambient 1
Noticeable Odor	Yes	Visible water damage / staining	Visible micro g? growth?	bial Amount of ma affected	terial
Ceiling Type	2 x 4 Lay In	No	No		None
Wall Type	Drywall	No	No		None
Flooring	12 x 12 Vinyl	No	No		None
	Clean Minor I / Deb			Corrective Action Re	equired
Ceiling	Yes	No			
Walls	Yes	No			
Flooring	Yes	No			
HVAC Supply Grills	No Yes	No	C	lean with Wexcide dis	infectant
HVAC Return Grills	No	Yes	C	lean with Wexcide dis	infectant
Ceiling at Supply Grills				Wall Mounted Ur	nit
Surfaces in Room	Yes	No			

Observations

Findings:

- Complaint of odor in the room. There is a sewer lift station behind the portable and noticeable odor in the area. Grass around lift station shows staining.

- Grounds were recently treated for flea infestation. Complaint of insecticide odor at ramp of portable.

- 3 A/C units in the room and none were set for fresh air. One of the units is on the side of the lift station. Opened other 2 units to allow fresh air.

- Dust and debris on HVAC coils

- Dust and debris on HVAC supply and return grills
- Non-approved chemicals in room gallon of Clorox bleach, insect fogger, spray glitter and disinfectant spray
- 2 holes in vinyl siding at lift station 1 with wires sticking out
- No signs of microbial growth or water intrusion
- Plastic and insulation hanging from the bottom of the portable

-Recommendations:

Site Based Maintenance:

- Hose down area under portable ramp to remove possible odor from insecticide
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Remove non-approved chemicals from room (HFSP removed during assessment)

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate **Physical Plant Operations:**

- Evaluate sewer lift station behind the portable for proper operation and repair as appropriate
- Clean HVAC coils on all wall mounted units
- Evaluate and repair 2 holes in the side of the portable at lift station
- Evaluate underneath the portable for proper seal insulation and plastic hanging