

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

September 21, 2006 Signature on File

TO: Mrs. Vered Roberts, Principal

Hollywood Hills Elementary School

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable 701VE and 702VE

On September 15, 2006 I conducted an assessment of Portable 701VE and 702VE at **Hollywood Hills Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Sam Gregg, Area Superintendent
Margaret Underhill, Area Director
Jeffrey S. Moquin, Director, Risk Management
Frank Girardi, Project Manager, Facilities and Construction Management
Diane Watts, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

	11011911000	· ·····o =·o····o····a·	y 			•		-,
Time of Day	12:20 pm				E	Evaluation Date	Septembe	er 15, 2006
Outdoor Condi	tions Tem	perature 8	39.8	Relative Humi	dity 56.9	Ambie	ent CO2	490
	Temperature	Range Rela	tive Humidity	Range	CO2	Rar	nge #	Occupants
P-701VE	81.8	2 - 78	48.9	30% - 60%	2774	Max 700	> Ambient	26
Noticeable Od	or No		/isible water nage / staining		nicrobial wth?	Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No	0		None	
Wall Type Tackable		Э	No No		0	None		
Flooring	Carpet		No	No		None		
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide dis	infectant	
HVAC Return (Grills No	Yes	Yes		Clean wit	h Wexcide dis	infectant	
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropri	ate	

IAQ Assessment

Hollywood Hills Flementary School

0111

Evaluation Requested September 15, 2006

Location Number

Observations

Findings:

- Dust and debris on HVAC supply and return grills
- Temperature was elevated at the time of the assessment. Only East A/C unit was running. Fresh air vent was closed and was opened at the time of the assessment.
- Dust build up on environmental surfaces
- Dust and debris on HVAC coils East unit
- Elevated moisture content in walls under all windows and all of West wall
- Exterior caulking missing around South door and around windows on North side
- Exterior Fungus growing on West wall and T-1-11 is soft to the touch
- Exterior Possible birds nesting above ceiling as evidenced by soffit screen in Norhwest corner of portable

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfecrtant solution
- Ensure that both HVAC units are running and set to fresh air
- Thoroughly clean environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Clean HVAC coils East unit
- Evaluate cause of water intrusion and repair. Repair/replace wall material as appropriate (see above).
- · Caulk around South door and around indows on North side
- Replace damaged T-1-11 on exterior of portable
- Seal birds out of the building Northwest corner of portable

Time of Day	12:20 pm				Ev	aluation Date	Septembe	r 15, 2006		
Outdoor Conditions Temperature 89.8 Relative Humidity 56.9 Ambient CO2 490										
Fish	Temperature R	ange Relati	ve Humidity	Range	CO2	Range	e #0	Occupants		
P-702VE	76.7 7 2	2 - 78	49.9	30% - 60%	1811	Max 700 >		22		
Noticeable Odor No			Visible water Visible microbial damage / staining? growth?			Amount of material affected				
Ceiling Type	pe 2 x 4 Lay In		Yes	No		3 ceiling tiles				
Wall Type	Tackable		No	No		None				
Flooring	Carpet		No	No		N	lone			
	Clean	Minor Dust / Debris	Needs Cleaning		Correcti	ve Action Req	uired			
Ceiling	No	Yes	Yes		Replace	stained ceiling	tiles			
Walls	Yes	No	No							
Flooring	Yes	No	No							
HVAC Supply	Grills No	Yes	Yes	С	lean with	Wexcide disinf	fectant			
HVAC Return (Grills No	Yes	Yes	С	lean with	Wexcide disinf	fectant			
Ceiling at Supp Grills	ply Yes	No	No							
Surfaces in Ro	oom No	Yes	Yes		Clean	as appropriate	е			

IAQ Assessment

Hollywood Hills Elementary School

0111

Evaluation Requested September 15, 2006

Location Number

Observations

Findings:

- Dust and debris on HVAC supply and return grills
- Dust and debris on A/C filters
- Dust build up on environmental surfaces
- Dust and debris on HVAC coils both units. Coils frozen on West unit.
- Elevated moisture content in East and West wall and South wall from restroom door to portable door
- Exterior T-1-11 on West side is severely water damaged
- Exterior T-1-11 patch on South side is allowing water into the building entire length of the wall
- Exterior caulking missing around windows and doors

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfecrtant solution
- Remove and replace A/C filters
- Thoroughly clean environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Clean HVAC coils both units
- Evaluate cause of water intrusion and repair. Repair/replace wall material as appropriate (see above).
- Caulk around all doors and windows
- Replace damaged T-1-11 on exterior of portable as indicated above