

# managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

May 22, 2007 Signature on File For Custodial Supervisor

TO: Mrs. Vered Roberts, Principal

**Hollywood Hills Elementary School** 

FROM: Robert Krickovich, Coordinator, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable 59N

odial Issues Addressed	
odial Issues Not Addressed	

On April 16, 2007 Richard Rosa conducted an assessment of Portable 59N at Hollywood Hills Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Steven Friedman, Area Superintendent (Task Assigned)

Margaret Underhill, Area Director

Jeffrey S. Moquin, Director, Risk Management

Frank Girardi, Project Manager, Facilities and Construction Management

Diane Watts, Broward Teachers Union

Roy Jarrett, National Federation of Public and Private Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

RK/tc Enc.

Hollywood Hills Elementary School					Evaluati	ion Requested	April 13,	2007
Time of Day	9:30 am				E	Evaluation Date	April 16,	2007
Outdoor Cond	litions	Temperature	59.9	Relative Humidit	y 38.6	Ambient (	CO2 5	501
Fish	Temperature	Range	Relative Humidity	<sup>/</sup> Range	CO2	Range	# O	ccupants
P-59N	64.9	72 - 78	56.1	30% - 60%	2043	Max 700 > A	Ambient	19
Noticeable Odor Yes		Visible water Visible micr damage / staining? growth			Amount of material affected			
Ceiling Type	Homasote		No			None		
Wall Type	Homasote		No	No		None		
Flooring	Cai	rpet	No	No		None		
	Clean	Minor D / Debr		J	Correc	ctive Action Requ	ired	
Ceiling	No	Yes	Yes		Replace Bowed Homasote			
Walls	Yes	No	No					
Flooring	No	Yes	Yes		Remov	e and replace car	pet	
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide disinfe	ectant	
HVAC Return	Grills No	Yes	Yes		Clean wit	h Wexcide disinfe	ectant	
Ceiling at Sup Grills	oply No	Yes	Yes		Clea	an as appropriate		
Surfaces in R	oom No	Yes	Yes		Clea	an as appropriate		

IAQ Assessment

0111

**Location Number** 

## Observations

#### Findings:

- Odor emanating from carpet. Carpet is rippled.
- A/C units were not on at the time of the assessment. CO2 level was slightly elevated.
- Dust and debris on window A/C unit grills
- Dust build up on ceiling in front of window A/C units
- Minor dust build up in corners
- Ceiling material is bowed
- Dust and debris on A/C filters
- Dust and debris on window A/C unit coils
- No visible microbial growth or water intrusion at the time of the assessment
- -Recommendations:

### Site Based Maintenance:

- Clean grills on window A/C units with Wexcide disinfectant solution
- Clean ceiling in front of window A/C units
- Clean corners as appropriate
- Change A/C filters
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of bowed ceiling material and repair as appropriate and replace ceiling material as appropriate
- Evaluate and repair cause of elevated CO2 level
- Evaluate carpet for replacement
- Clean coils on window A/C units