

Report: PPO

HUNT JAMES S ELEMENTARY

Walkthrough Date: 03/30/2007 Temp RH CO2

Outdoor Parameters: 75.4 59.8 581

Room	Priority	Responsible	Answer	Recommendation
103	Inside Parameters:	Temp	RH	CO2
		74.0	52.2	970

2 PPO Exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
127	Inside Parameters:	Temp	RH	CO2
		72.7	62.6	847

2 PPO Humidity was slightly elevated at the time of assessment. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.

Room	Priority	Responsible	Answer	Recommendation
129	Inside Parameters:	Temp	RH	CO2
		71.1	67.3	885

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
134	Inside Parameters:	Temp	RH	CO2
		70.2	69.1	846

2 PPO Temperature was low at the time of assessment and humidity was elevated. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity level.

Room	Priority	Responsible	Answer	Recommendation
135	Inside Parameters:	Temp	RH	CO2
		71.1	67.1	858

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
142	Inside Parameters:	Temp 70.8	RH 60.9	CO2 951

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
144	Inside Parameters:	Temp 70.2	RH 64.9	CO2 946

2 PPO Temperature was low at the time of assessment and humidity was elevated. Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity level.

Room	Priority	Responsible	Answer	Recommendation
176	Inside Parameters:	Temp 74.6	RH 59.6	CO2 865

2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
504	Inside Parameters:	Temp 72.6	RH 54.4	CO2 936

1 PPO Condensation on walls or surfaces at the time of assessment. No leak identified. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
508	Inside Parameters:	Temp 73.1	RH 56.5	CO2 945

1 PPO No visible condensation at the time of assessment. Signs of previous water intrusion as evidenced by stains on walls. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
602	Inside Parameters:	Temp	RH	CO2

		73.1	54.2	1013
	2	PPO	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
603	Inside Parameters:	Temp	RH	CO2
		72.2	51.7	776
	2	PPO	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.