

# managing risk with responsibility

Aston A. Henry, Supervisor Telephone: 754 321-1900 Risk Management Department Fax: 754 321-1917

March 15, 2010 Signature on File

TO: Ms. Marvis Ward, Principal

Martin Luther King Elementary School

FROM: Robert Krickovich, Coordinator, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 850, 851 and 855

On March 3, 2010 I conducted an assessment of FISH 850, 851 and 855 at Martin Luther King Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Leontine Butler, Area Superintendent

Michaelle Pope, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Aston Henry, Supervisor, Risk Management

Sheldon Dash, Project Manager, Facilities and Construction Management

Jerrod Neal, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

	Martin Lutner	king Elementar	y School		Evaluati	on Requested [	March 1, 2010
Time of Day	9:45 am				E	valuation Date	March 3, 2010
Outdoor Conditi	ons Tem	perature 6	61.8	Relative Hum	idity 48.2	Ambien	nt CO2 349
Fish Te 850  Noticeable Odo Ceiling Type Wall Type	72.2 7	2 - 78 dam	tive Humidity 46.5 /isible water tage / staining No No			Amount of material affect	> Ambient 21
Flooring	12 x 12 Vir	nyl	No	N	0	None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Rec	quired
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	No	Yes	Yes		Clean and sanitize		e
HVAC Supply Grills No		Yes	Yes		Clean with Wexcide disinfectant		
HVAC Return G	rills No	Yes	Yes		Clean wit	h Wexcide disi	nfectant
Ceiling at Supp Grills	ly No	Yes	Yes		Clean as appropriate		ate
Surfaces in Roc	om No	Yes	Yes		Clea	an as appropria	ate

IAQ Assessment

1611

**Location Number** 

#### **Observations**

#### Findings:

- Occupant advised of mildew smell when entering the room. No odor detected at the time of the assessment
- Heavy dust and debris on HVAC supply and return grills and on ceiling at supply grills
- Dust build up on horizontal surfaces throughout the room
- Dust and debris on floor

# Site Based Maintenance:

- · Clean HVAC supply and return grills with Wexcide disinfectant solution and clean ceiling at supply grills
- Thoroughly clean all horizontal surfaces throughout the room
- Thoroughly clean, sanitize and wax floor
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate and clean AHU coils, drain pan and lines - EQ01370 generated by PPO to address

	Martin Luther	King Elementar	y School		Evaluati	on Requested [	March 1, 2010	
Time of Day	9:45 am				E	valuation Date	March 3, 2010	
Outdoor Conditi	ons Tem	nperature 6	31.8	Relative Hu	midity 48.2	Ambier	nt CO2 349	
Fish Te		Range Relate	tive Humidity 42.4	Range 30% - 60%	<b>CO2</b> 1151	Rang Max 700	ge # Occupants > Ambient 19	
Noticeable Odor No		-			e microbial rowth?	Amount		
Ceiling Type	Ceiling Type 2 x 4 Lay In		No		No		None	
Wall Type	Drywall		No		No	None		
Flooring	12 x 12 Vi	nyl	No		No	None		
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	No	Yes	Yes		Clean and sanitize		e	
HVAC Supply Grills No		Yes	Yes		Clean with Wexcide disinfectant			
HVAC Return G	rills No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
Ceiling at Supp Grills	ly No	Yes	Yes		Clea	an as appropria	ate	
Surfaces in Roc	om No	Yes	Yes		Clea	an as appropria	ate	
•					•			

IAQ Assessment

1611

**Location Number** 

# **Observations**

# Findings:

- Occupant advised every now and then they notice an odor when entering the room. No odor detected at the time of the assessment
- Heavy dust and debris on HVAC supply and return grills and on ceiling at supply grills
- Dust build up on horizontal surfaces throughout the room
- Dust and debris on floor

#### Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution and clean ceiling at supply grills
- Thoroughly clean all horizontal surfaces throughout the room
- Thoroughly clean, sanitize and wax floor
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate and clean AHU coils, drain pan and lines - EQ01370 generated by PPO to address

	Martin Luth	er King Elemer	ntary School		EV	aluation R	equested	March 1, 2010
Time of Day	9:45 am					Evalu	ation Date	March 3, 2010
Outdoor Condit	ions T	Temperature	61.8	Relative Hu	ımidity	48.2	Ambie	nt CO2 349
Fish T	emperature	Range F	elative Humidity	Range	CC	<b>D2</b>	Ran	ge # Occupants
855	71.6	72 - 78	41.7	30% - 60%	4	.77		> Ambient 16
Noticeable Odd	or No		Visible water damage / staining		le microbia jrowth?		Amount of aterial affec	
Ceiling Type	2 x 4 L	ay In	No		No			None
Wall Type	Dryw	vall	No		No			None
Flooring	12 x 12	! Vinyl	No		No			None
	Clean	Minor Du / Debris		I	С	Corrective	Action Re	quired
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply (	Grills Yes	No	No					
HVAC Return C	Grills No	Yes	Yes		Clea	n with We	excide disi	nfectant
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Ro	om Yes	No	No					
oservations								
Findings: - Occupant advise properly and the - Minor dust on the -	room gets ve	ery uncomforta		-				/C does not work
	eturn grills wit		infectant solutior gns of microbial		ell as dust a	and debris	s accumula	tion and clean as
Physical Plant ( - Evaluate and c			nd lines - EQ01:	370 generate	ed by PPO	) to addre	SS	

**IAQ Assessment** 

1611

**Location Number**