

managing risk with responsibility

July 9, 2010	Signature on File	For Custodial Supervisor II		
Risk Management	t Department	Fax:	754 321-1917	
Asion A. Heiny,	ouper visor	reiephone.	734 321-1900	
Aston A. Henry, S	Supervisor	Telephone:	754 321-1900	

TO: Ms. Marvis Ward, Principal

Martin Luther King Elementary School

FROM: Robert Krickovich, Coordinator, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 855

On May 28, 2010 I conducted a follow-up assessment of FISH 855 at Martin Luther King Elementary School. The assessment consisted of a reevaluation walkthrough of the previously identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included reviewing previously generated work orders, if applicable, as well as observation of the area of concern as stated in the IAQ Assessment performed on March 3, 2010. Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Leontine Butler, Area Superintendent

Carletha Shaw, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Aston Henry, Supervisor, Risk Management

Jack Cooper, Senior Project Manager, Facilities and Construction Management

Jerrod Neal, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

Martin Luther King Elementary School						Evaluation Requested May 24, 2010			
Time of Day 9:40 am					Evaluation Date May 28, 2010				
Outdoor Condi	tions Te	emperature	83.4	Relative Humi	dity 65	Ambie	nt CO2 40)5	
Fish T 855 Colling Type	73.4 or No 2 x 4 La	72 - 78 da	63.2 Visible water amage / staining	Range 30% - 60% Visible m ? grow	rth?	Max 700 Amount of material affect	> Ambient	2	
Wall Type	Drywa	all	No		<u> </u>	None			
Flooring	12 x 12 \	/inyl	No	No			None		
	Clean	Minor Dus / Debris	t Needs Cleaning		Correc	ctive Action Re	equired		
Ceiling	Yes	No	No						
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide dis	infectant		
HVAC Return	Grills No	Yes	Yes		Clean wit	h Wexcide disi	infectant		
Ceiling at Sup Grills	ply Yes	No	No						
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropri	ate		
bservations									

IAQ Assessment

1611

Location Number

Findings

- Minor dust on HVAC supply and return grills
- Dust build up on window blinds
- Minor water staining on drywall above ceiling (dry at the time of the assessment)
- Many Oak trees in bloom on the property at the time of the assessment which could contribute to allergy symptoms
- Humidity level was slightly elevated at the time of the assessment

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean window blinds
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level