

managing risk with responsibility

Aston A. Henry, Supervisor Risk Management Department

754 321-1900 Telephone: Fax: 754 321-1917

April 13, 2012

Signature on File

TO: Marvis Ward, Principal

Martin Luther King Elementary School

FROM: Robert Krickovich, Coordinator I, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

For Custodial Supervisor Use Only						
	Custodial Issues Addressed					
	Custodial Issues Not Addressed					
	-					
-						

On February 14, 2012 I conducted an assessment at Martin Luther King Elementary School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

Area Superintendent cc:

Area Directors

Shelley Meloni, Executive Director, Facilities and Construction Management Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Sonja Coley, Project Manager III, Facilities and Construction Management Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management Broward Teachers Union

Federation of Public Employees

RK/tc Enc.

Martin Luther King Elementary School						Evaluation Requested February 9, 2012			
Time of Day	9:20				E	Evaluation Date	Februar	y 14, 2012	
Outdoor Condi	tions	Temperature	77.1	Relative Humidity	49.3	Ambier	nt CO2	482	
	Temperature	¬ ''ango r	Relative Humidity	Trailige	CO2	Ran		Occupants	
160	71.5	72 - 78	60.7	30% - 60%	692	Max 700 :	> Ambien	t 8	
Noticeable Odor No			Visible water damage / staining	Visible micro growth?		Amount of material affect	ted		
Ceiling Type	2 x 4	Lay In	Yes	No		1 ce	eiling tile		
Wall Type	Drywall		No	No		None			
Flooring	12 x 1	2 Vinyl	No	No			None		
	Clean	Minor D / Debri		ı	Correc	ctive Action Re	quired		
Ceiling	No	Yes	Yes		Ren	nove and repla	ce		
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply	Grills No	Yes	Yes		Clea	an as appropria	ite		
HVAC Return	Grills Yes	No	No						
Ceiling at Sup Grills	ply Yes	No	No						
Surfaces in Ro	oom Yes	No	No						
hearvations									

IAQ Assessment

1611

Location Number

Observations

Findings

- Dust build up on HVAC supply grills
- Stained ceiling tiles
- A/C filters not taped together properly in FISH 162 (AHU)
- Humidity level was slightly elevated

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Remove and replace stained ceiling tiles. If stain returns contact COMPASS to generate a work order for Physical Plant Operations to evaluate.
- FISH 162 (AHU) Ensure A/C filters are taped together properly to prevent bypass of dust and particulates.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level
- NOTE: Work order EQ02339 generated 3-7-12

	Martin Lut	ther King Eleme	entary School		Evaluation F	Requested [February 9, 2012
Time of Day	9:20				Evalu	uation Date	February 14, 2012
Outdoor Condi	tions	Temperature	77.1	Relative Humidity	49.3	Ambie	nt CO2 482
Fish 161 Noticeable Od Ceiling Type Wall Type	2 x 4	72 - 78	Felative Humidity 59.5 Visible water damage / staining Yes No	30% - 60% Visible micro		Amount of aterial affec	> Ambient 2
Flooring	12 x 1	2 Vinyl	No	No			None
Ceiling	Clean	/ Debri				Action Re	
Walls	Yes		No			•	
Flooring	Yes	No	No				
HVAC Supply	Grills Yes	No	No				
HVAC Return	Grills Yes	No	No				
Ceiling at Sup Grills	ply Yes	No	No				
Surfaces in Ro	oom Yes	No	No				
bservations							
Findings							

IAQ Assessment

1611

Location Number

- Stained ceiling tiles
- A/C filters not taped together properly in FISH 162 (AHU)
- Humidity level was slightly elevated

Site Based Maintenance:

- Remove and replace stained ceiling tiles. If stain returns contact COMPASS to generate a work order for Physical Plant Operations to evaluate.
- FISH 162 (AHU) Ensure A/C filters are taped together properly to prevent bypass of dust and particulates.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level
- NOTE: Work order EQ02339 generated 3-7-12

Martin Luther King Elementary School Evaluation Requested February 9, 2012						February 9, 2012	
Time of Day	9:20				Evaluation Date	February 14, 2012	
Outdoor Condi	tions Tem	perature 7	7.1 Re	elative Humidity	49.3 Ambiei	nt CO2 482	
Fish 3	Comporature =		e de dice				
Fish 163		Range Rela 2 - 78	tive Humidity 56.5	Trailige	Ran Max 700	ge # Occupants > Ambient 2	
Noticeable Od		<u> </u>	ાંડાંble water	Visible microbi			
		dam	age / staining?	growth?	material affec	ted	
Ceiling Type	2 x 4 Lay I	n	No	No	None		
Wall Type	Drywall		No	No		None	
Flooring	12 x 12 Ving	yl	No	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning	C	Corrective Action Re	quired	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills No	Yes	Yes		Clean as appropria	ate	
HVAC Return (Grills Yes	No	No				
Ceiling at Supp Grills	oly Yes	No	No				
Surfaces in Ro	om Yes	No	No				
 Observations							
Findings							
	on HVAC supply	•	162 (AULI)				
- Avo niters not t	- A/C filters not taped together properly in FISH 162 (AHU)						
Site Based Maintenance: - Clean HVAC supply grills with Wexcide disinfectant solution - FISH 162 (AHU) - Ensure A/C filters are taped together properly to prevent bypass of dust and particulates Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate							
Physical Plant Operations: - Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level - NOTE: Work order EQ02339 generated 3-7-12							

IAQ Assessment

1611

Location Number