

managing risk with responsibility

Aston A. Henry, Supervisor	Telephone:	754 321-1900
Risk Management Department	Fax:	754 321-1917

June 21, 2010 Signature on File

TO: Mrs. Heather Hedman-Devaughn, Principal

Lauderdale Manors Elementary School

FROM: Aston A. Henry, Supervisor

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 718, 719, 721 and 724

For Custodial Supervisor Use Only							
	Custodial Issues Addressed						
	Custodial Issues Not Addressed						

On June 16, 2010 I conducted an assessment of FISH 718, 719, 721 and 724 at **Lauderdale Manors Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Leontine Butler, Area Superintendent

Michaelle Pope, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance

Sheldon Dash, Project Manager, Facilities and Construction Management

Charles Ricks, Project Manager, Facilities and Construction Management

Dane Ramson, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AAH/tc Enc.

L	auderdale Mar	nors Elementary	School	i	Evaluation R	equested [June 10, 2010	
Time of Day					Evalua	ation Date [June 16, 2010	
Outdoor Condition	ons Tem	perature 9	5.2	Relative Humidity	73.7	Ambier	nt CO2 357	
Fish Te 718		Range Relati 2 - 78	ive Humidity	Range (30% - 60%	CO2	Rang Max 700	ge # Occupant > Ambient	ts
Noticeable Odo	r No	=	isible water age / stainingʻ	Visible microb growth?		Amount of aterial affect		
Ceiling Type	2 x 4 Lay	ln	Yes	No		5 staine	d ceiling tiles]
Wall Type	Drywall/Pla	ster	No	No		ı	None	
Flooring	Tile		No	No			None]
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	quired	
Ceiling	No	Yes	Yes	Remov	e and repla	ce stained	ceiling tiles]
Walls	Yes	No	No]
Flooring	Yes	No	No]
HVAC Supply G	rills Yes	No	No]
HVAC Return G	rills Yes	No	No]
Ceiling at Suppl Grills	y Yes	No	No]
Surfaces in Roo	m Yes	No	No]
bservations								

0431

Location Number

0

Findings

- HVAC system was not operational at the time of the assessment
- 5 stained ceiling tiles. HFSP advised that numerous work orders have been called in to address roof leaks.
- All surfaces were extremely clean at the time of the assessment.

Site Based Maintenance:

- Remove and replace stained ceiling tiles. Continue to monitor and change ceiling tiles as necessary until repairs are completed by Physical Plant Operations.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

	Lauderdale M	anors Elementar	y School	ı	Evaluation	Requested	June	10, 2010
Time of Day					Eval	uation Date	June	16, 2010
Outdoor Condit	tions Te	mperature 9	5.2	Relative Humidity	73.7	Ambien	t CO2	357
Fish T 719	emperature	Range Relat	ive Humidity	Range 0	CO2	Rang Max 700 >	•	Occupants
Noticeable Od	or No		/isible water age / staining	Visible microb ? growth?		Amount of naterial affect	ed	
Ceiling Type	2 x 4 La	y In	Yes	No		5 stained	d ceiling t	iles
Wall Type	Drywall/P	aster	No	No		N	lone	
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correctiv	e Action Red	quired	
Ceiling	No	Yes	Yes	Remov	e and rep	lace stained	ceiling ti	iles
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return (Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					
bservations								

0431

Location Number

0

Findings

- HVAC system was not operational at the time of the assessment
- 5 stained ceiling tiles. HFSP advised that numerous work orders have been called in to address roof leaks.
- All surfaces were extremely clean at the time of the assessment.

Site Based Maintenance:

- Remove and replace stained ceiling tiles. Continue to monitor and change ceiling tiles as necessary until repairs are completed by Physical Plant Operations.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

	Lauderdale Mar	nors Elementary	/ School	1	Evaluation R	equested [June 10, 2010
Time of Day					Evalua	ation Date [June 16, 2010
Outdoor Condit	ions Tem	perature 9	5.2	Relative Humidity	73.7	Ambier	nt CO2 357
Fish To 721		Range Relat 2 - 78	ive Humidity	Range 30% - 60%	CO2	Rang Max 700 :	ge # Occupants > Ambient
Noticeable Odd	or No		'isible water age / staining'	Visible microb growth?		Amount of aterial affect	
Ceiling Type	2 x 4 Lay	In	Yes	No		various sta	ined ceiling tiles
Wall Type	Drywall/Pla	ster	No	No			None
Flooring	Tile		No	No			None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	quired
Ceiling	No	Yes	Yes	Remov	e and repla	ce stained	ceiling tiles
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply C	Grills Yes	No	No				
HVAC Return C	Grills Yes	No	No				
Ceiling at Supp Grills	oly Yes	No	No				
Surfaces in Roo	om Yes	No	No				
hservations							

0431

Location Number

Observations

Findings

- HVAC system was not operational at the time of the assessment
- Various stained ceiling tiles. HFSP advised that numerous work orders have been called in to address roof leaks.
- All surfaces were extremely clean at the time of the assessment.

Site Based Maintenance:

- Remove and replace stained ceiling tiles. Continue to monitor and change ceiling tiles as necessary until repairs are completed by Physical Plant Operations.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

	Lauderdale Mai	nors Elementary	y School	1	Evaluation R	Requested [June 10, 2010
Time of Day					Evalu	ation Date [June 16, 2010
Outdoor Condit	ions Tem	perature 9	5.2	Relative Humidity	73.7	Ambiei	nt CO2 357
Fish To 724		Range Relat 2 - 78	ive Humidity	Range 30% - 60%	CO2	Ran Max 700	ge # Occupants > Ambient
Noticeable Odd	or No		'isible water age / staining	Visible microb growth?		Amount of aterial affect	
Ceiling Type	2 x 4 Lay	ln	Yes	No		various sta	ined ceiling tiles
Wall Type	Drywall/Pla	ster	No	No			None
Flooring	Tile		No	No			None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	quired
Ceiling	No	Yes	Yes	Remov	e and repla	ace stained	ceiling tiles
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply C	Grills Yes	No	No				
HVAC Return C	Grills Yes	No	No				
Ceiling at Supp Grills	oly Yes	No	No				
Surfaces in Roo	om Yes	No	No				
hservations							

0431

Location Number

Observations

Findings

- HVAC system was not operational at the time of the assessment
- Various stained ceiling tiles. HFSP advised that numerous work orders have been called in to address roof leaks.
- All surfaces were extremely clean at the time of the assessment.

Site Based Maintenance:

- Remove and replace stained ceiling tiles. Continue to monitor and change ceiling tiles as necessary until repairs are completed by Physical Plant Operations.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations: