



Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

March 10, 2005

TO: Ms. Karla Gary-Orange, Principal Maplewood Elementary School

- FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental Control Risk Management Department
- SUBJECT: Indoor Air Quality (IAQ) Assessment FISH 404

On February 25, 2005 the IAQ Assessment Team conducted an assessment FISH 404 at **Maplewood Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent Ulysses Jackson, Area Director Jeffrey S. Moquin, Director, Risk Management Greg Boardman, Project Manager II, Facilities and Construction Management Ruby Fitzgerald, Broward Teachers Union Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Project Manager II, Facilities and Construction Management

KP/tc Enc.

IAQ Assessment								
Maplewood Elementary School					Evaluation	Requested	Febru	ary 24, 2005
Time of Day	1:35 pm				Eval	luation Date	Febru	ary 25, 2005
Outdoor Condi	tions Ten	perature	80	Relative Humidity	69	Ambie	nt CO2	407
Fish 1	Temperature	Range Rela	ative Humidity	Range	CO2	Ran	ge	# Occupants
404	73.8 7	2 - 78	64.3	30% - 60%	1043	< 1,000	) PPM	24
Noticeable Odor No			Visible water Visible microbi damage / staining? growth?			Amount of material affected		
Ceiling Type 2 x 4 Lay In		In	No			None		
Wall Type	Wall Type Drywall/Tackable		No	No		None		
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning	I	Correctiv	e Action Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	Νο	No					
HVAC Return (	Grills No	Yes	Yes	C	lean with V	Vexcide disi	nfectan	t
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

### Observations

#### Findings:

- Exterior wall expansion joints of 402 and 404 are lacking caulk and seal
- Heavy dust and debris on HVAC return grills
- Humidity level is elevated
- False ceiling plenum appears clean and dry at accessed locations
- Ductwork, coils and drain pain are clean
- Dust and debris on HVAC filters
- FISH 204 Air Handler Room Microbial growth on drywall behind both HVAC units

# Recommendations:

### Site Based Maintenance:

- Caulk and seal expansion joints on exterior wall of 402 and 404
- Clean HVAC return grills with wexcide disinfectant solution
- Replace HVAC filters

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations Division:

- Assess and evaluate wall surface options
- Evaluate and repair HVAC system in order to lower the humidity level
- Evaluate and repair cause of microbial growth in FISH 204 Air Handler Room