

Aston A. Henry, Director

managing risk with responsibility

754 321-1900

Telephone:

Risk Manage	ement Department	Fax:	754 321-1917
August 20, 2	Signature on File	For Custodia	l Supervisor Use Only
TO:	Thomas Schroeder, Principal Margate Elementary School		Issues Addressed Issues Not Addressed
FROM:	Robert Krickovich, Coordinator I, LEA Risk Management Department		
SUBJECT:	Indoor Air Quality (IAQ) Assessment		

On August 15, 2013, I conducted an assessment at **Margate Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RK/tc Enc.

IAQ Assessment

M	argate Elemer	<u>ntary</u> Evaluatio	on Date August 1	15, 2013	Time of Day	10:00
Outdoor Conditions Te	emperature	81.1 Re	elative Humidity	91.2	Ambient CO2	555
Fish Temperature 205 69.4	e Range] 72 - 78	Relative Humidity	/ Range 30% - 60%	CO ² 488	Range # 0 MAX 700 > Ambient	Occupants 4
Noticeable Odor Ye	es .	Visible water damag staining?	e / Visible mid growtl		Amount of material affected	
Ceiling 2' X 4' Lay i	n	Yes	No] [8 tiles	
Walls Plaster		Yes	No] [Entire West wal	I
Floor 12" x 12" Vin	yl	No	No] [
Ceiling Clean Yes Walls Clean Yes	- 1	HVAC Supply Grills Clean	Yes		HVAC Return Grills Clean	No
Flooring Clean No]	Inside of Sup Duct Clean	Yes		Inside of Return Duct Clean	N/A
Room Surfaces Yes Clean]	Ceiling at Su Grills Clean	pply N/a			
Trash Removed Yes]	Exhaust Fans Worl	king Yes		Unapproved Chemicals Cleaners in Room	/ No
Signs of Pests No		Drain Traps	Wet Yes			
Room Cluttered No	1	Food if Stored in Roc in Sealed Containers	- I NI/A I		Air Fresheners in Room	No
Mechanical Equipment Loc	cation Ceilin	g Hung Unit			Mechanical Room Clean	N/A
Filters Installed Properly	Yes	Filters Cl	ean No	In	side of HVAC Unit Clean	N/A
Condensate Pan Clean	N/A	Cooling Coil Cl	ean N/A			
Fresh Air Intake Location Pollutant Sources Near Air Intake	Roof None	top		▼	Fresh Air Intake Free of Obstruction	Yes
Observations						
Slight musty odor in room	- Entire west	t wall water damag	ed (exterior wall cr	acks on en	tire exterior)	
Corrective Actions to be	Completed by	Site Based Staff	Correct	tive Actions	to be Completed by F	PPO
Remove and re	eplace A/C filt	ters 🔻		Repair	roof leaks	▼

Remove and replace A/C filters	▼
Thoroughly clean and sanitize flooring	▼
	▼
	▼
	▼
	▼
	▼
	▼

Repair roof leaks	▼
Remove and replace stained ceiling tiles	▼
Repair exterior stucco cracks	▼
Paint exterior west wall of 205	•
Repair interior west plaster wall	•
Set temperature to 72 - 78 degrees	•
	▼
	▼

IAQ Assessment

Margate Elem	nentary Evaluation Date	August 15, 2013	Time of Day 10):00
Outdoor Conditions Temperature	81.1 Relative	Humidity 91.2	Ambient CO2 55	5
Fish Temperature Range 223 69.4 72 - 78	i	tange CO ² 541	Range # Occ MAX 700 > Ambient	cupants 4
Noticeable Odor Yes	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling Tectum	No	No		
Walls Drywall	No	No		
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Walls Clean Yes Flooring Clean Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	No
Room Surfaces No Clean	Ceiling at Supply Grills Clean	N/a		
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	Yes		
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Location Cei	ling Mounted Unit		Mechanical Room Clean	N/A
Filters Installed Properly N/A	Filters Clean	N/A	Inside of HVAC Unit Clean	No
Condensate Pan Clean N/A	Cooling Coil Clean	N/A		
Fresh Air Intake Location Roc	of top	▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	ne	▼	or obstruction	
Observations				
Slight musty odor - pipe above ceilin facilities service person) - Multiple s		eaking - ceiling tile had	d microbial growth (remov	ed by
Corrective Actions to be Completed	by Site Based Staff	Corrective Action	ns to be Completed by PP	 0

Clean wall surfaces in 223A above and below	▼
ceiling	▼
Remove stuffed animals from room	▼
	▼
	▼
	▼
	T▼
	T▼

10 20 00 mp.otou 27 1 1 0	0011001110710110110110
HVAC System ▼	Clean entire H
above ceiling in 223A ▼	Repair leaking pipe at
eiling in 223A ▼	Replace ceili
e to 72 - 78 degrees	Set temperature to
▼	
▼	
▼	
▼	