

managing risk with responsibility

Jeffrey S. Moquin, DirectorTelephone:754-321-3200Risk Management DepartmentFacsimile:754-321-3290

January 7, 20	08 Signature on File	For Custodial Supervisor Use Only
TO:	Dr. Theodore Toomer, Principal Markham Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Edward See, Project Manager Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On November 19, 2007 I conducted an assessment of FISH 301, 302, 303, 304 and 401 at **Markham Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

FISH 301, 302, 303, 304 and 401

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent
Jackie Haywood, Area Director
Jeffrey S. Moquin, Director, Risk Management
Gerry Devio, Project Manager, Facilities and Construction Management
Lynn Cavall, Broward Teachers Union
Roy Jarrett, National Federation of Public and Private Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

ES/tc Enc.

			mornary concer			-	,
Time of Day	2:35 pn	n			E	valuation Date Novem	ber 19, 2007
Outdoor Condi	tions	Temperatur	e 81.1	Relative Humidity	68.9	Ambient CO2	515
Fish	Гетрегаtur	^e Range	Relative Humidit	y Range	CO2	Range	# Occupants
301	63.3	72 - 78	69.3	30% - 60%	461	Max 700 > Ambie	ent 1
Noticeable Od	or Ye	es	Visible water damage / stainin	Visible micr g? growth		Amount of material affected	
Ceiling Type	2 x 4	1 Lay In	No	No		None	
Wall Type	PI	aster	No	No		None	
Flooring	12 x	12 Vinyl	No	No		None	
	Clea	n Minor / Del		g	Correc	tive Action Required	
Ceiling	Yes	s N	o No				
Walls	Yes	s N	o No				
Flooring	Yes	s N	o No				
HVAC Supply	Grills No	Ye	Yes		Clean with	Wexcide disinfectant	t
HVAC Return (Grills No	Ye	Yes		Clean with	Wexcide disinfectant	t
Ceiling at Supp Grills	ply Ye:	S N	o No				
Surfaces in Ro	oom No	Ye	s Yes		Clea	n as appropriate	

Markham Flementary School

1671

Evaluation Requested November 19, 2007

Location Number

Observations

Findings:

- · Musty odor in room
- -Dust and debris on HVAC supply and return grills
- Dust build up on environmental surfaces and window sills
- Temperature was low and humidity was elevated
- Items stored in FISH 301B (air handler room)

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Thoroughly clean environmental surfaces and window sills throughout the room
- Remove items from FISH 301B
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Current project to upgrade HVAC system ongoing. Project Manager advised and will take care of findings related to HVAC with contractor.

	Maı	kham Elemer	ntary School		Evaluati	ion Requested N	ovember 19, 2007
Time of Day	2:35 pm]			E	Evaluation Date N	ovember 19, 2007
Outdoor Condi	tions Te	mperature	81.1	Relative Humidity	68.9	Ambient C	515
Fish	Temperature	Range R	elative Humidity	Range	CO2	Range	# Occupants
302	66.1	72 - 78	59.5	30% - 60%	475	Max 700 > A	mbient 1
Noticeable Od	lor Yes		Visible water lamage / staining	Visible micro g? growth?	bial	Amount of materia affected	al
Ceiling Type	2 x 4 La	y In	No	No		Noi	ne
Wall Type	Plaste	r	No	No		Nor	ne
Flooring	12 x 12 V	inyl	No	No		No	ne
	Clean	Minor Dus	st Needs Cleaning	ı	Correc	ctive Action Requi	red
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills No	Yes	Yes	С	lean witl	h Wexcide disinfe	ctant
HVAC Return (Grills No	Yes	Yes	С	lean witl	h Wexcide disinfe	ctant
Ceiling at Sup Grills	ply Yes	No	No				
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropriate	

1671

Location Number

Observations

Findings:

- Musty odor in room
- -Dust and debris on HVAC supply and return grills
- Dust build up on environmental surfaces and window sills
- Temperature was low
- Items stored in FISH 302B (air handler room)

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Thoroughly clean environmental surfaces and window sills throughout the room
- Remove items from FISH 302B
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Current project to upgrade HVAC system ongoing. Project Manager advised and will take care of findings related to HVAC with contractor.

	Mar	kham Elemen	tary School		Evaluat	ion Requested Novem	nber 19, 2007
Time of Day	2:35 pm]	•		E	Evaluation Date Novem	nber 19, 2007
Outdoor Condi	itions Ter	mperature [81.1	Relative Humidity	68.9	Ambient CO2	515
Fish	Temperature	Range R	elative Humidity	' Range	CO2	Range	# Occupants
303	66.9	72 - 78	68.1	30% - 60%	472	Max 700 > Ambie	ent 3
Noticeable Oc	lor No]d	Visible water amage / stainin	Visible micro g? growth?		Amount of material affected	
Ceiling Type	2 x 4 Lay	[,] In	No	No		None	
Wall Type	Drywa	I	No	No		None	
Flooring	12 x 12 V	inyl	No	No		None	
	Clean	Minor Dus / Debris	t Needs Cleaning	ı	Corre	ctive Action Required	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills No	Yes	Yes	С	lean wit	h Wexcide disinfectan	t
HVAC Return	Grills No	Yes	Yes	С	lean wit	h Wexcide disinfectan	t
Ceiling at Sup Grills	ply Yes	No	No				
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropriate	

1671

Evaluation Requested November 19, 2007

Location Number

Observations

Findings:

- Dust and debris on HVAC supply and return grills
- Dust build up on environmental surfaces and window sills
- 2 broken ceiling tiles
- Temperature was low and humidity level was slightly elevated
- Items stored in FISH 303B (air handler room)
- Dust and debris on A/C filters (FISH 303B)

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Thoroughly clean environmental surfaces and window sills throughout the room
- Remove and replace broken ceiling tiles
- Remove items from FISH 303B
- Remove and replace A/C filters (FISH 303B)
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

Current project to upgrade HVAC system ongoing. Project Manager advised and will take care of findings related to HVAC with contractor.

		Ma	rkham Elem	entary School			Evaluat	tion Requested	Novem	nber 19, 2007
Time of Day	2:35	5 pm					I	Evaluation Date	Novem	nber 19, 2007
Outdoor Condi	itions	Te	mperature	81.1	Rela	ative Humidity	68.9	Ambie	ent CO2	515
Fish	Tempera	ature	Range	Relative Humi	dity F	Range	CO2	Rar	nge	# Occupants
304	74.	5	72 - 78	60.3	30%	% - 60%	470	Max 700	> Ambie	ent 3
Noticeable Od	dor	Yes		Visible wa damage / stai		Visible microgrowth?		Amount of ma affected	terial	
Ceiling Type	2	2 x 4 La	y In	No		No			None	
Wall Type		Drywa	all	No		No			None	
Flooring	12	2 x 12 \	/inyl	No		No			None	
	С	lean	Minor D / Debri				Corre	ctive Action Re	equired	
Ceiling		Yes	No	No	•					
Walls	[Yes	No	No)					
Flooring		No	Yes	Ye	s		CI	ean and sanitiz	ze	
HVAC Supply	Grills [No	Yes	Ye	s	C	lean wit	th Wexcide dis	infectan	t
HVAC Return	Grills [No	Yes	Ye	S	С	lean wit	th Wexcide dis	infectan	t
Ceiling at Sup Grills	ply [Yes	No	No	•					
Surfaces in Ro	oom [No	Yes	Ye	s		Cle	an as appropri	ate	

1671

Location Number

Observations

Findings:

- Dust and debris on HVAC supply and return grills
- Dust and debris on floor
- Dust build up on environmental surfaces
- 3 ceiling tiles were not properly secured to grid
- Humidity level was slightly elevated
- Items stored in FISH 304B (air handler room)

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean and sanitize floor
- Thoroughly clean environmental surfaces throughout the room
- Adjust ceiling tiles to prevent gaps
- Remove items from FISH 304B
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Current project to upgrade HVAC system ongoing. Project Manager advised and will take care of findings related to HvAC with contractor.

	Mark	ham Elementary	/ School		⊏vaiuat	ion Requested	November 19, 200) [
Time of Day	2:35 pm				E	Evaluation Date	November 19, 200)7
Outdoor Condi	tions Tem	perature 8	1.1 R	Relative Humidi	ty 68.9	Ambie	nt CO2 515	
Fish	Temperature	Range Relat	ive Humidity	Range	CO2	Ran	ge # Occupa	nts
401	67.2 7	2 - 78	64.6	80% - 60%	1045	Max 700	> Ambient 3	
Noticeable Od	or No		isible water age / staining?	Visible mi growt		Amount of ma	terial	
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Plaster		No	No]		None	
Flooring	12 x 12 Vir	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
HVAC Return (Grills No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropri	ate	
hservations								

1671

Location Number

Findings:

- · Musty odor in room
- -Dust and debris on HVAC supply and return grills
- Dust build up on environmental surfaces and window sills
- Temperature was low and humidity was elevated

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Thoroughly clean environmental surfaces and window sills throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Current project to upgrade HVAC system ongoing. Project Manager advised and will take care of findings related to HVAC with contractor.