

managing risk with responsibility

Aston A. Henry, Supervisor
Risk Management Department

Telephone: 754 321-1900 Fax: 754 321-1917

April 13, 2012

Signature on File

TO: Olivia Vega, Principal

Thurgood Marshall Elementary School

FROM: Robert Krickovich, Coordinator I, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

For Custodial Supervisor Use Only							
	Custodial Issues Addressed						
	Custodial Issues Not Addressed						

On February 10, 2012 I conducted an assessment at **Thurgood Marshall Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Area Superintendent

Area Directors

Shelley Meloni, Executive Director, Facilities and Construction Management Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Sonja Coley, Project Manager III, Facilities and Construction Management Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management Broward Teachers Union Federation of Public Employees

RK/tc

Enc.

Time of Day [12:45	mperature [77.6	Relative Humidity		Ambient CO2 457
Fish 401 Noticeable Od Ceiling Type Wall Type		72 - 78 d	62.2 Visible water amage / staining	Range 30% - 60% Visible micro growth? No		Range # Occupants Max 700 > Ambient 2 Amount of material affected None
Flooring	Carpet		Yes	No		200 square feet
	Clean	Minor Dus / Debris	t Needs Cleaning	1	Correc	ctive Action Required
Ceiling	Yes	No	No			
Walls	Yes	No	No			
Flooring	No	Yes	Yes		Clea	an as appropriate
HVAC Supply	Grills No	Yes	Yes		Clea	an as appropriate
HVAC Return	Grills Yes	No	No			
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropriate

IAQ Assessment

Thurgood Marshall Elementary School

3291

February 8, 2012

Location Number

Evaluation Requested

Observations

Findings

- Slightly elevated humidity level
- Signs of water intrusion at all entry doors of this building
- Carpet at entry doors is heavily stained. Minor staining on carpet, except at entry doors.
- Excessive amount of stuffed animals in the room. Stuffed animals are a source of allergens and must be cleaned regularly.
- Dust build up on HVAC supply grills
- Dust build up on surfaces throughout the room

Site Based Maintenance:

- Thoroughly clean carpet.
- Clean stuffed animals on a regular basis or remove them
- Clean HVAC supply grills with Wexcide disinfectant solution
- Clean all surfaces throughout the room, including shelving and books.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level.
- Evaluate for cause of water intrusion at all entry doors to the building media center
- Evaluate carpet at all entry doors and repair/replace as necessary.
- NOTE: Work orders EQ02335, EQ02336, EQ02337 and EQ02338 generated 3-7-12

Thurgood Marshall Elementary School Evaluation Requested February 8, 2								
Time of Day 12:45 Evaluation Date August 10, 2012							ust 10, 2012	
Outdoor Condition	ons Ter	mperature [77.6	Relative Humidity	85.8	Ambient CO2	457	
401B	71	Range R 72 - 78	elative Humidity 66.3 Visible water	Range 30% - 60%	CO2 712	Range Max 700 > Ambig	# Occupants ent 1	
Noticeable Odor No			lamage / staining		ыаі	Amount of material affected		
Ceiling Type	2 x 4 Lay	[,] In	No	No		None		
Wall Type	Drywal	I	No	No		None		
Flooring	Carpet		No	No		None		
	Clean	Minor Dus	st Needs Cleaning		Correc	ctive Action Required		
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply G	rills No	Yes	Yes		Clea	an as appropriate		
HVAC Return G	rills Yes	No	No					
Ceiling at Suppl Grills	y Yes	No	No					
Surfaces in Roo	om No	Yes	Yes		Clea	an as appropriate		

IAQ Assessment

3291

Location Number

Observations

Findings

- Slightly elevated humidity level
- Dust build up on HVAC supply grills
- Dust build up on surfaces throughout the room (excessive clutter)
- Excessive amount of stuffed animals in the room. Stuffed animals are a source of allergens and must be cleaned regularly.

Site Based Maintenance:

- Clean stuffed animals on a regular basis or remove them
- Clean HVAC supply grills with Wexcide disinfectant solution
- Clean all surfaces throughout the room, including shelving and books.
- Room is too cluttered to clean properly. Encourage occupant to reduce clutter to assist with cleaning efforts.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level
- NOTE: Work orders EQ02335, EQ02336, EQ02337 and EQ02338 generated 3-7-12

	Thur	good M	<u> 1arshall Elei</u>	mentary S	<u>3chool</u>		Evaluat	tion Requested	February 8, 2012
Time of Day	12	2:45					ı	Evaluation Date	August 10, 2012
Outdoor Cond	litions	Т	emperatur	e 77.0	6	Relative Humi	dity 85.8	B Ambie	nt CO2 457
Fish	Temper		Range		e Humidity	Range	CO2	Ran	
401C	74	1.9	72 - 78	5	57.1	30% - 60%	698	Max 700	> Ambient 2
Noticeable Odor No			Visible water Visible mic damage / staining? growth						
Ceiling Type		2 x 4 L	ay In		Yes		es 1 c		eiling tile
Wall Type		Dryw	/all		No	No)	None	
Flooring		Carpet/	VCT		No	No)		None
	(Clean	Minor / Del		Needs Cleaning	l	Corre	ctive Action Re	equired
Ceiling		No	Ye	s	Yes		Remove and replace		
Walls		Yes	No)	No				
Flooring		No	Ye	s	Yes		Clean as appropriate		
HVAC Supply	Grills	Yes	Ne)	No				
HVAC Return	Grills	Yes	No)	No				
Ceiling at Sup Grills	ply	Yes	No)	No				
Surfaces in R	oom	No	Ye	s	Yes		Cle	an as appropri	ate
Observations									
Findings	- (1								

IAQ Assessment

3291

Location Number

- Visible staining on flooring
- Dust build up on surfaces throughout the room

Site Based Maintenance:

- Clean all surfaces throughout the room, including shelving and books.
- Thoroughly clean flooring
- Remove and replace stained ceiling tile and monitor until repairs are completed.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate for cause of stained ceiling tiles and repair as appropriate. Remove and replace ceiling tiles as necessary.

NOTE: Work orders EQ02335, EQ02336, EQ02337 and EQ02338 generated 3-7-12