

# managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

October 12, 2005 Signature on File

TO: Ms. Kellee Stroup, Principal

**McNab Elementary School** 

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 315 and 354

On September 21, 2005 the IAQ Assessment Team conducted an assessment of FISH 315 and 354 at **McNab Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joanne Harrison, Area Superintendent
Jackie Haywood, Area Director
Jeffrey S. Moquin, Director, Risk Management
Jack Cooper, Senior Project Manager, Facilities and Construction Management
LaFrances Trotter, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

Time of Day	2:45 pm				E	September 21, 2005			
Outdoor Condi	tions	Temperature	89.3	Relative Humidity	67.3	Ambient CO2 418			
Fish	<b>Temperature</b>	Range	Relative Humidity	' Range	CO2	Range # Occupants			
315	<b>74.1 72 - 78</b>		55.7	30% - 60%	675	Max 700 > Ambient 4			
Noticeable Odor No			Visible water Visible microbia damage / staining? growth?			Amount of material affected			
Ceiling Type	2 x 4 Lay In		Yes	No		7 Ceiling tiles			
Wall Type	Drywall		No	No		None			
Flooring	12 x 12 Vinyl		No	No		None			
	Clean	Minor   / Deb		ı	Correc	ctive Action Required			
Ceiling	Yes	No	No						
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply Grills No		Ye	Yes	С	Clean with Wexcide disinfectant				
HVAC Return (	Grills No	Ye	Yes	С	lean witl	h Wexcide disinfectant			
Ceiling at Support Grills	ply Yes	No	No						
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropriate			

IAQ Assessment

McNab Elementary School

0841

Evaluation Requested September 19, 2005

**Location Number** 

#### **Observations**

#### Findings:

- Cobwebs in corners and dust on environmental surfaces
- Non-approved SBBC chemicals under sink (Lysol, Clorox)
- Sink cabinet needs to be caulked
- 7 ceiling tiles and side of restroom wall at range disconnect are stained
- Visible condensation and microbial growth inside cabinet over range hood

## Recommendations:

## Site Based Maintenance:

- Thoroughly clean surfaces throughout the room
- Remove non-approved chemicals from room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### **Physical Plant Operations Division:**

- Evaluate and repair cause of stained ceiling tiles and replace ceiling tiles as appropriate
- Evaluate and repair cause of water stains on side of restroom wall at range disconnect and repair/replace wall as appropriate
- Evalaute and repair cause of condensation and microbial growth inside cabinet over range hood and clean or replace cabinets as appropriate
- Remove and replace caulking on sink cabinet to back splash

	Мс	Nab Elementa	ry School		Evaluation	n Requested	October	3, 2005		
Time of Day	3:10 pm				Eva	aluation Date	October	5, 2005		
Outdoor Condi	itions Tem	perature		Relative Humidity		Ambien	it CO2			
Fish	Temperature F	Range Rela	ative Humidity	Range	CO2	Rang	ie # C	ccupants		
354		2 - 78	43.7	30% - 60%	562	Max 700 >	•	4		
Noticeable Odor No			Visible water nage / staining	Visible micro growth?	7					
Ceiling Type	2 x 4 Lay	ln	No	No		ľ	None			
Wall Type	Drywall		No	No		N	lone			
Flooring	12 x 12 Vin	yl	No	No			None			
Clean Minor D			Needs Cleaning	Corrective Action Peguired						
Ceiling	Yes	No	No							
Walls	Yes	No	No							
Flooring	Yes	No	No							
<b>HVAC Supply</b>	Grills Yes	No	No							
HVAC Return	Grills Yes	No	No							
Ceiling at Sup Grills	ply Yes	No	No							
Surfaces in Ro	oom Yes	No	No							
bservations										
Findings: - Complaint of odor was received on 10/3/05. There was no odor detected on the date of the assessment Returned on 10/10/05 at 6:30 a.m. and there was no odor detected at that time										
Recommendations:										
Site Based Mai	intenance:									
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate										

**IAQ Assessment** 

0841

**Location Number**