

Aston A. Henry, Supervisor Risk Management Department

# managing risk with responsibility

Telephone:754 321-1900Fax:754 321-1917

November 22	2, 2010	Signature on File
TO:		a Patterson, Principal E <b>lementary School</b>
FROM:		Ienry, Supervisor gement Department
SUBJECT:		• Quality (IAQ) Assessment 66CX, 505C, 506C, 547C, 548C 66VE

Custodial Issues Addressed
Custodial Issues Not Addressed

On November 4, 2010, I conducted an assessment of **Portable 266CX**, **505C**, **506C**, **547C**, **548C**, **853 and 856VE** at **Nob Hill Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Desmond Blackburn, Area Superintendent Carle Shaw, Area Director Jeffrey S. Moquin, Executive Director, Support Operations Greg Boardman, Project Manager, Facilities and Construction Management Ralph Eckhart, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager I, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AH/tc Enc.

			IAQ As	sessment	Location Number	2671
	Not	o Hill Elementa	ry School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm	]			Evaluation Date	November 4, 2010
Outdoor Condit	tions Ten	nperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
Fish T	Temperature	Range Rela	ative Humidity	Range	CO2 Ran	ige # Occupants
P-266CX	71.5	72 - 78	56.2	30% - 60%	819 Max 700	> Ambient 3
Noticeable Od	or No		Visible water mage / staining	Visible micro ? growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/Tac	kable	Yes	Yes	Sc	outh wall
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		Evaluate and repart	air
Flooring	Yes	No	No			
HVAC Supply	Grills Yes	No	No			
HVAC Return (	Grills Yes	No	No			
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings

- Elevated moisture content in South wall under A/C unit with minor microbial growth

#### Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of elevated moisture content in South wall under A/C unit

# NOTE: EQ01548 generated to address findings

			IAQ Ass	sessment	Location Number	2671
	Nol	o Hill Elementa	ary School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm	]			Evaluation Date	November 4, 2010
Outdoor Condi	itions Ter	nperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
Fish	Temperature	Range Rel	lative Humidity	Range	CO2 Ran	ige # Occupants
P-505C	74	72 - 78	57.5	30% - 60%	1399 Max 700	> Ambient 2
Noticeable Od	lor No	] da	Visible water mage / staining	Visible micro ? growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/Tac	kable	Yes	No	No	orth wall
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		Evaluate and repa	air
Flooring	Yes	No	No			
HVAC Supply	Grills Yes	No	No			
HVAC Return	Grills Yes	No	No			
Ceiling at Sup Grills	oply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings

- Elevated moisture content in North wall under A/C unit

- CO2 level was elevated at the time of the assessment

### Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate cause of elevated moisture content in North wall under A/C unit
- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2 level

# NOTE: EQ01518 and EQ01524 generated to address findings

			IAQ Ass	sessment	Location Number	2671
	Not	Hill Elementa	ry School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm	]			Evaluation Date	November 4, 2010
Outdoor Condi	itions Ter	nperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
Fish	Temperature	Range Rela	ative Humidity	Range	CO2 Ran	ge # Occupants
P-506C	71.6	/2 - 78	49.7	30% - 60%	1382 Max 700	> Ambient 3
Noticeable Od	lor No	]da	Visible water mage / staining	Visible micro ? growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/Tac	kable	Yes	Yes	No	orth wall
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		Evaluate and repa	air
Flooring	Yes	No	No			
HVAC Supply	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings

- Elevated moisture content in North wall under A/C unit
- Visible microbial growth under posters and items hanging on wall
- CO2 level was elevated at the time of the assessment
- Dust and debris on A/C grills
- Dust build up on A/C filters

### Site Based Maintenance:

- Wipe down walls with Wexcide disinfectant solution
- Clean A/C grills with Wexcide disinfectant solution
- Remove and replace A/C filters
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate cause of elevated moisture content in North wall under A/C unit
- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2 level

# NOTE: EQ01519 and EQ01525 generated to address findings

			IAQ Ass	sessment	Location Number	2671
	Not	Hill Elementa	ry School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm				Evaluation Date	November 4, 2010
Outdoor Condi	itions Ten	nperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
Fish	Temperature	Range Rel	ative Humidity	Range	CO2 Ran	ige # Occupants
P-547C	73.9	2 - 78	51.6	30% - 60%	1065 Max 700	> Ambient 3
Noticeable Od	lor No	da	Visible water mage / staining	Visible micro ? growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/Tacl	kable	No	No		None
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	Yes	No	No			
Flooring	Yes	No	No			
HVAC Supply	Grills Yes	No	No			
HVAC Return	Grills Yes	No	No			
Ceiling at Sup Grills	oply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings

- No issues identified at the time of the assessment

# Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ Ass	sessment	Location Number	2671
	No	b Hill Elementa	ry School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm	]			Evaluation Date	November 4, 2010
Outdoor Condi	itions Ter	mperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
Fish	Temperature	Range Rela	ative Humidity	Range	CO2 Ran	ige # Occupants
P-548C	73.1	72 - 78	54.4	30% - 60%	927 Max 700	> Ambient 2
Noticeable Od	lor No	]dai	Visible water mage / staining	Visible microl ? growth?	bial Amount o material affec	-
Ceiling Type	2 x 4 Lay	In	Yes	No	2 c	eiling tiles
Wall Type	Drywall/Tac	kable	Yes	No	W	lest wall
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	No	Yes	Yes	Re	move and replace cei	iling tiles
Walls	No	Yes	Yes		Evaluate and repa	air
Flooring	Yes	No	No			
HVAC Supply	Grills Yes	No	No			
HVAC Return	Grills Yes	No	No			
Ceiling at Sup Grills	oply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings

-Elevated moisture content in West wall under A/C unit

- 2 stained ceiling tiles

#### Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate cause of elevated moisture content in West wall under A/C unit
- Evaluate cause of stained ceiling tiles and repair as appropriate. Remove and replace stained ceiling tiles as necessary.

# NOTE: EQ01520 and EQ01523 generated to address findings

			IAQ Ass	essment	Location Number	2671
	Not	Hill Elementar	y School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm				Evaluation Date	November 4, 2010
Outdoor Condit	tions Ten	nperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
	emperature	Range Rela	tive Humidity	Range	CO2 Rar	ige # Occupants
P-853	7	/2 - 78		30% - 60%	Max 700	> Ambient
Noticeable Od	or No		/isible water age / staining?	Visible microl ? growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/Tacl	kable	Yes	No	E	ast wall
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		Evaluate and repa	air
Flooring	Yes	No	No			
HVAC Supply	Grills Yes	No	No			
HVAC Return (	Grills Yes	No	No			
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	om Yes	No	No			

#### Findings

A/C unit not in operation at time of the assessment
Elevated moisture content in East wall under A/C unit

#### Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of elevated moisture content in East wall under A/C unit

# NOTE: EQ01521 generated to address findings

			IAQ As	sessment	Location Number	2671
	Not	Hill Elementa	ry School		Evaluation Requested	October 21, 2010
Time of Day	3:45 pm				Evaluation Date	November 4, 2010
Outdoor Condi	tions Ten	nperature	79.7	Relative Humidity	60 Ambie	nt CO2 412
Fish 1	Temperature	Range Rela	ative Humidity	Range	CO2 Ran	ige # Occupants
P-856VE	72.2 7	2 - 78	59.2	30% - 60%	1127 Max 700	> Ambient 2
Noticeable Od	or No	dai	Visible water mage / staining	Visible micro growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/Tacl	kable	Yes	No	E	ast wall
Flooring	Tile		No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		Evaluate and repart	air
Flooring	Yes	No	No			
HVAC Supply	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings

- Elevated moisture content in East wall under A/C unit
- CO2 level was elevated at the time of the assessment
- Dust and debris on A/C grills
- Dust build up on A/C filters

# Site Based Maintenance:

- Clean A/C grills with Wexcide disinfectant solution

- Remove and replace A/C filters

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

### Physical Plant Operations:

- Evaluate cause of elevated moisture content in East wall under A/C unit
- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2 level

# NOTE: EQ01522 and EQ01526 generated to address findings