

## managing risk with responsibility

Aston A. Henry, Supervisor	Telephone:	754 321-1900
Risk Management Department	Fax:	754 321-1917

February 1, 2010 Signature on File

TO: Ms. Camille LaChance, Principal

North Side Elementary School

FROM: Edward See, Project Manager

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 103, 160 and 806

On January 28, 2010, I conducted an assessment of FISH 103, 160 and 806 at North Side Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Leontine Butler, Area Superintendent

Jan Beal, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Aston Henry, Supervisor, Risk Management

Frank Alfieri, Project Manager, Facilities and Construction Management

Dane Ramson, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

		North S	Side Eleme	entary S	chool			Evaluati	on Requested		
Time of Day	10:15	am						E	valuation Date	Janu	ary 28, 2010
Outdoor Condi	tions	Tem	perature	70.9		Relative Hu	midity	53.7	Ambie	nt CO2	380
Fish T	Temperat 71.5		Range 2 - 78		Humidity 7.3	Range 30% - 60%		<b>CO2</b> 807	Rar Max 700	_	# Occupants ent 2
Noticeable Od	or _	Yes			ole water e / stainin		e microl	bial ,	Amount o material affect		
Ceiling Type	2	x 4 Lay	n		Yes		No	L	1 0	eiling til	e
Wall Type	Dry	/wall/Plas	ster		No		No	[		None	
Flooring	12	2 x 12 Vir	nyl		No		No			None	
	Cl	ean	Minor D / Debri		Needs Cleaninç	]		Correc	tive Action Re	equired	
Ceiling		No	Yes		Yes		R	emove a	and replace ce	eiling tile	•
Walls		Yes	No		No						
Flooring		Yes	No	]	No						
HVAC Supply	Grills [	No	Yes		Yes		CI	ean witl	n Wexcide dis	infectan	it
HVAC Return	Grills [	No	Yes		Yes		CI	ean witl	h Wexcide dis	infectan	it
Ceiling at Sup Grills	ply [	Yes	No		No						
Surfaces in Ro	oom [	No	Yes		Yes			Clea	an as appropri	ate	

IAQ Assessment

0041

**Location Number** 

## **Observations**

## Findings:

- 1 stained ceiling tile (old stain)
- Odor in room from air freshener non-approved chemical
- 1 potted plant in room
- Dust build up on elevated surfaces
- Dust and debris on HVAC supply and return grills

## Site Based Maintenance:

- Remove and replace stained ceiling tile
- Remove non-approved chemical air freshener
- Remove potted plant. Soil is a source of microbial growth.
- Thoroughly clean elevated surfaces
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

	North Side Elem	entary School	Evaluat	ion Requested			
Time of Day 10:	:15 am			Evaluation Date	January 28, 20	10	
Outdoor Conditions	Temperature	70.9 Rela	ative Humidity 53.	7 Ambien	nt CO2 380		
Noticeable Odor  Ceiling Type  Wall Type	Range 3.9 72 - 78  No 2 x 4 Lay In  Drywall/Plaster 12 x 12 Vinyl		Range CO2 % - 60% 1297 Visible microbial growth? No No No	Amount of material affect	Ambient 17		
	Clean Minor D		Corre	ctive Action Rec	quired		
Ceiling	Yes	No					
Walls	Yes No	No					
Flooring	Yes No	No					
HVAC Supply Grills	Yes No	No					
HVAC Return Grills	Yes No	No					
Ceiling at Supply Grills	Yes No	No					
Surfaces in Room	No	Yes	Cle	an as appropria	ite		
bservations							
Findings: - Room A/C unit was turned off at the time of the assessment and CO2 level was slightly elevated at a result - Dust build up on environmental surfaces  Site Based Maintenance: - Ensure that A/C unit is turned on periodically to ventilate the room - Thoroughly clean environmental surfaces throughout the room - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate							

**IAQ Assessment** 

0041

**Location Number** 

	North Side E	ementary School		Evaluation Requested [			
Time of Day	10:15 am			Evaluation Date	January 28, 2010		
Outdoor Condition	ns Temperat	ure 70.9	Relative Humidity	53.7 Ambier	nt CO2 380		
Fish Tem 806  Noticeable Odor Ceiling Type Wall Type Flooring	Perature Range 72.2 72 - 78  No  2 x 4 Lay In  Drywall/Plaster  12 x 12 Vinyl	Relative Humidity 51.2  Visible water damage / staining  No  No  No	30% - 60% Visible micros	Dial Amount of material affec	> Ambient 8		
Ceiling Walls Flooring HVAC Supply Gri HVAC Return Gri Ceiling at Supply Grills Surfaces in Room	Yes	or Dust Needs Cleaning No		Corrective Action Re	quired		
Findings: - 1 ceiling tile was not seated properly - Occupant advised that it was cold in the room during the cold snap in early January. Environmental parameters - temperature, humidity and CO2 - were within range at the time of the assessment.  Site Based Maintenance: - Ensure that ceiling tiles are seated properly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate							

**IAQ** Assessment

0041

**Location Number**