

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

March 15, 2006

Signature on File

TO: Mr. Chuck McCanna

Nova Blanche Forman Elementary School

FROM: Kenneth I. Partee, Project Manager

Occupational Health and Environmental Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 148 and 152

On February 28, 2006, members of the District's IAQ Assessment Team, along with a representative from the Facilities Task Force and the location's Head Facilities Serviceperson conducted an IAQ evaluation of FISH 148 and 152 at **Nova Blanche Forman Elementary School**. The evaluation was conducted in response to teacher complaints regarding increased absenteeism of students and the increased frequency of non-specific respiratory ailments of staff and students. The teacher occupant further reported these occurrences became apparent subsequent to Hurricane Wilma. Additionally, the occurrences appeared correlated to a date when the accordion wall system between Rooms 148 and 152 was temporarily opened.

This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment maintained on the building's roof. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

This IAQ evaluation identified several conditions potentially impacting IAQ and the appropriate work orders will be generated to correct these issues. At the time of the evaluation, no issues were identified to suggest an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and/or conditions identified during the evaluation.

Therefore, to further improve IAQ, prevent development of further IAQ problems, and to reduce the potential for IAQ-related complaints by building occupants, it is recommended appropriate follow up be given to each of the items identified in the Evaluation.

These findings were shared with the teacher occupant and it was agreed to conduct further evaluations in the event these corrective actions did not alleviate occupant concerns.

Should any questions arise, please feel free to contact me at (754) 321-3200.

cc: Dr. Harry LaCava, Area Superintendent
Dr. Linda Bedell, Area Director
Jeffrey S. Moquin, Director, Risk Management
Juana Romaniuk, Project Manager, Facilities and Construction Management
Dane Ramson, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

Nova Blanche Forman Elementary School					Evaluation F	Requested	Februa	ry 27, 2006
Time of Day	11:40 am				Evalu	ation Date	Februa	ry 28, 2006
Outdoor Condi	tions Tem	nperature		Relative Humidity		Ambier	nt CO2	
Fish	Temperature F	Range Relat	tive Humidity	Range	CO2	Rang	ge	# Occupants
148	70.5 7	'2 - 78	49	30% - 60%	1421	Max 700 :	> Ambieı	nt 15
Noticeable Od		/isible water lage / staining	Visible micro g? growth?	,	ount of mate affected	erial		
Ceiling Type	2 x 4 Lay	In	Yes	No		v	arious	
Wall Type	e Plaster/Tackable		No			None		
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning	1	Corrective	Action Rec	quired	
Ceiling	No	Yes	Yes		Replace sta	ined ceilin	g tiles	
Walls	No	Yes	Yes		Clean as appropriate			
Flooring	No	Yes	Yes		Clean, sa	nitize and v	wax	
HVAC Supply	Grills No	Yes	Yes	С	lean with Wo	excide disi	nfectant	
HVAC Return (Grills No	Yes	Yes	С	lean with Wo	excide disi	nfectant	
Ceiling at Support Grills	ply No	Yes	Yes	Repl	ace ceiling t	tiles for dirt	impacti	on
Surfaces in Ro	oom No	Yes	Yes		Clean as	s appropria	ite	

IAQ Assessment

1282

Location Number

Observations

Findings:

- Several stained ceiling tiles and tiles with dirt impaction at HVAC supply grills
- Heavy dust and debris on bookshelves and books behind teacher's desk
- Dust, insect parts and cobwebs on walls and ceiling
- Dust and debris on floor
- Dust and debris on HVAC supply and return grills and on ceiling tiles at supply grills
- Dust and debris on accordian wall between FISH 148 and 152 and storage area
- Dust and debris on environmental surfaces throughout the room
- HVAC filters were not properly taped together allowing bypass of air
- Non-approved chemicals in room (cleaners and paint thinner)
- Stuffed animals, flowers and toys in room
- Leaves and other debris around drains for ventilation system

Recommendations:

Site Based Maintenance:

- Remove and replace stained ceiling tiles and ceiling tiles with dirt impaction at HVAC supply grills
- Remove books from bookshelves and clean shelves and books as appropriate
- Clean walls and ceilings as appropriate to remove dust, insect parts and cobwebs
- Clean, sanitize, strip and wax floor
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean accordian wall between FISH 148 and 152 and and wall storage area (if accessible) with Wexcide disinfectant solution
- Clean all environmental surfaces throughout the room as appropriate
- Remove and replace HVAC filters and tape together properly
- Remove non-approved chemicals from room
- Remove stuffed animals, flowers and toys from room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Roof repair lining in AHU #18 and evaluate cause of stagnant water on Southeast corner of roof
- Clear leaves and other debris from drains for ventilation system

Nova Blanche Forman Elementary School					Evaluation	Requested [Februa	ry 27, 2006
Time of Day	11:25 am	I			Eval	uation Date	Februa	ry 28, 2006
Outdoor Condi	tions Tem	nperature		Relative Humidity		Ambier	nt CO2	
Fish	Temperature F	Range Rela	ative Humidity	Range	CO2	Ranç	ge ;	# Occupants
152	72 7	72 - 78	52.2	30% - 60%	1365	Max 700 :	> Ambier	nt 19
Noticeable Odor No						mount of mate affected	erial	
Ceiling Type	2 x 4 Lay	In	Yes	No		v	arious	
Wall Type	Plaster		No			None		
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning	1	Correctiv	e Action Red	quired	
Ceiling	No	Yes	Yes		Replace st	ained ceilin	g tiles	
Walls	Yes	No	No					
Flooring	No	Yes	Yes		Clean, s	anitize and v	wax	
HVAC Supply	Grills No	Yes	Yes	С	lean with W	/excide disi	nfectant	
HVAC Return (Grills No	Yes	Yes	С	lean with W	/excide disi	nfectant	
Ceiling at Supp Grills	ply No	Yes	Yes		Clean a	as appropria	ite	
Surfaces in Ro	oom No	Yes	Yes		Clean a	as appropria	ite	

IAQ Assessment

1282

Location Number

Observations

Findings:

- Several stained ceiling tiles
- · Heavy dust and debris on bookshelves and books behind teacher's desk
- Dust and debris on floor
- Dust and debris on HVAC supply and return grills and on ceiling tiles at supply grills
- Dust and debris on accordian wall between FISH 148 and 152 and storage area
- Dust and debris on environmental surfaces throughout the room
- Vines at rear of building and open conduit above roof
- Dry erase board in room with dirty marker tray
- Cabinets in the room are deteriorated from previous moisture intrusion
- HVAC filters were not properly taped together allowing bypass of air

Recommendations:

Site Based Maintenance:

- Remove and replace stained ceiling tiles
- Remove books from bookshelves and clean shelves and books as appropriate
- Clean, sanitize, strip and wax floor
- Clean HVAC supply and return grills with Wexcide disinfectant solution and clean ceiling tiles at supply grills as appropriate
- Clean accordian wall between FISH 148 and 152 and storage area with Wexcide disinfectant solution
- Clean all environmental surfaces throughout the room as appropriate
- Clean dry erase board marker tray as appropriate
- Remove and replace HVAC filters and tape together properly
- · Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate false ceiling for possible leak and seal conduit area in false ceiling at rear of room
- Remove vines at rear of building and seal open conduit above roof to eliminate conduit for moisture
- Remove and replace cabinets in room as appropriate due to previous moisture intrusion