

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

October 12, 2005 Signature on File

TO: Ms. Dorothy Cain, Principal

Palm Cove Elementary School

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable 838C

On September 19, 2005 the IAQ Assessment Team conducted an assessment of Portable 838C at **Palm Cove Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Sam Gregg, Area Superintendent
Pat Dixon, Area Director
Jeffrey S. Moquin, Director, Risk Management
Angelino Garcia, Project Manager II, Facilities and Construction Management
Steve Feldman, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

| Palm Cove Elementary School | | | | | Evaluation Requested September 18, 2005 | | | |
|-----------------------------|--------------|-------------------|--|-------------------|---|-----------------------------|-----------|--------------|
| Time of Day | 10:15 am | | | | E | Evaluation Date | Septem | ber 19, 2005 |
| Outdoor Cond | itions To | emperature | 91.2 | Relative Humidity | 54.1 | Ambie | ent CO2 | 517 |
| Fish | Temperature | Range | Relative Humidity | / Range | CO2 | Rar | nge | # Occupants |
| 838C | 81 | 72 - 78 | 54.1 | 30% - 60% | 1844 | Max 700 | > Ambie | nt 24 |
| Noticeable Odor Yes | | | Visible water Visible micro damage / staining? growth? | | bial | Amount of material affected | | |
| Ceiling Type | 2 x 4 Lay In | | Yes No | | | 1 ceiling tile | | |
| Wall Type | Tackable | | Yes No | | | South and East Wall | | |
| Flooring | 12 x 12 | Vinyl | No | No | | None | | |
| | Clean | Minor D / Debr | | 3 | Correc | ctive Action Re | equired | |
| Ceiling | Yes | No | No | | | | | |
| Walls | Yes | No | No | | | | | |
| Flooring | Yes | No | No | | | | | |
| HVAC Supply Grills No Ye | | Yes | Yes Clean with Wexcide disinfectant | | | | | |
| HVAC Return | Grills No | Yes | Yes | С | lean wit | h Wexcide dis | infectant | |
| Ceiling at Sup Grills | oply | | | | Wa | II mounted un | its | |
| Surfaces in Ro | oom Yes | No | No | | | | | |

IAQ Assessment

3311

Location Number

Observations

Findings:

- Dust and debris on HVAC supply and return grills
- Dust and debris on HVAC filters
- Visible water damage on East tackable wall surface three 4' x 8' panels
- Visible water damage on South wall under windows
- Visible water damage on building exterior (siding)
- Dust and debris on HVAC coils
- Only one A/C unit was on at the time of assessment

Recommendations:

Site Based Maintenance:

- · Clean HVAC supply and return grills with Wexcide disinfectant solution
- Remove and replace HVAC filters
- Ensure that both A/C units are on
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate and repair exterior of building to prevent water intrusion
- Evaluate and repair/replace water damaged tackable interior walls (East wall three 4' x 8' panels -and South wall under windows)
- Clean HVAC coils