

Aston A. Henry, Supervisor Risk Management Department

TO:

FROM:

# managing risk with responsibility

Telephone: 754 321-1900 Fax: 754 321-1917

December 2, 2009 **Signature on File** Ms. Susan Colton, Principal **Parkside Elementary School** Edward See, Project Manager **Risk Management Department** Indoor Air Quality (IAQ) Assessment

SUBJECT: FISH 308, 313, 314, 315, 316, 317, 318, 319, 320

Custodial Issues Addressed
Custodial Issues Not Addressed

On November 23, 2009, Robert Krickovich and I conducted an assessment of FISH 308, 313, 314, 315, 316, 317, 318, 319 and 320 at Parkside Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

Sharon Airaghi, Area Superintendent cc: Anne Dilgen, Area Director Jeffrey S. Moquin, Executive Director, Support Operations Aston Henry, Supervisor, Risk Management Gerry Devio, Project Manager, Facilities and Construction Management Gary Itzkowitz, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management ES/tc Enc.

			IAQ As	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requested	November 19, 2009
Time of Day	8:30 am				Evaluation Dat	e November 23, 2009
Outdoor Condi	itions Ten	nperature	79.7	Relative Humidity	72.5 Amb	ient CO2 430
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Ra	ange # Occupants
308	67.3 7	/2 - 78	58.4	30% - 60%	526 Max 70	0 > Ambient 2
Noticeable Od	lor No		/isible water age / staining	Visible micro ? growth?	bial Amount material aff	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	nyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action	Required
Ceiling	Yes	No	No			
Walls	Yes	No	No			
Flooring	Yes	No	No			
HVAC Supply	Grills No	Yes	Yes	C	lean with Wexcide d	isinfectant
HVAC Return	Grills No	Yes	Yes	C	lean with Wexcide d	isinfectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings:

- Cart full of sports balls in hallway. Odor from ball material.
- Dust and debris on HVAC supply and return grills
- Temperature was low at the time of the assessment
- FISH 309 Dust inside of air handler unit
- Outside air intake is low to the ground with plants in the area

# Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Ensure that sports equipment is properly stored
- Adjust thermostat to increase temperature

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Facilities and Construction Management:

- Have contractor clean out air handler unit in FISH 309

			IAQ As	sessment	Location Nu	ımber	3631	
	Park	side Elementa	ary School		Evaluation R	equested	Novembe	er 19, 2009
Time of Day	8:30 am				Evalua	ation Date	Novembe	er 23, 2009
Outdoor Conditior	ns Ten	nperature	79.7	Relative Humidity	72.5	Ambie	nt CO2	430
Fish Tem	perature	Range Rel	ative Humidity	Range	CO2	Ran	ige #	Occupants
313	72.5 <b>7</b>	2 - 78	54.1	30% - 60%	693	Max 700	> Ambient	2
Noticeable Odor	No	da	Visible water mage / staining	Visible micro ? growth?		Amount of aterial affect		
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Drywall/ Pla	aster	No	No			None	
Flooring	12 x 12 Vi	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Gri	lls No	Yes	Yes	CI	ean with We	excide dis	infectant	
HVAC Return Gril	lls No	Yes	Yes	CI	ean with We	excide dis	infectant	
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Room	Yes	No	No					

#### Findings:

- Dust and debris on HVAC supply and return grills

- Multiple plants in standing water with visible microbial growth. Plants are associated with a science project - temporary

## Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requested	November 19, 2009
Time of Day	8:30 am	]			Evaluation Date	November 23, 2009
Outdoor Cond	itions Ten	nperature	79.7	Relative Humidity	72.5 Ambie	ent CO2 430
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Ra	nge # Occupants
314	73 7	/2 - 78	54.6	30% - 60%	895 Max 700	<b>) &gt; Ambient</b> 20
Noticeable Oc	lor No		Visible water nage / staining	Visible micro ? growth?	741104111	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	nyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired
Ceiling	Yes	No	No			
Walls	Yes	Νο	No			
Flooring	Yes	Νο	No			
HVAC Supply	Grills No	Yes	Yes	C	lean with Wexcide dis	sinfectant
HVAC Return	Grills No	Yes	Yes	C	lean with Wexcide dis	sinfectant
Ceiling at Sup Grills	oply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

### Findings:

- Reduced air flow in room - stagnant

- Dust and debris on HVAC supply and return grills

#### Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Facilities and Construction Management:

- Evaluate HVAC system for proper operation and repair as appropriate to increase air flow to room

			IAQ Ass	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requested	November 19, 2009
Time of Day	8:30 am	]			Evaluation Date	November 23, 2009
Outdoor Condi	itions Ten	nperature	79.7	Relative Humidity	72.5 Ambie	ent CO2 430
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Rar	nge # Occupants
315	73.2	/2 - 78	55.3	30% - 60%	789 Max 700	> Ambient 15
Noticeable Od	lor Yes		/isible water hage / staining	Visible micro ? growth?	bial Amount o material affeo	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	nyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	Yes	Νο	No			
Flooring	Yes	Νο	No			
HVAC Supply	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings:

- Reduced air flow in room - stagnant

- Dust and debris on HVAC supply and return grills

- Odor from off gassing of new materials

- Multiple plants in the room associated with a science project - temporary

#### Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Facilities and Construction Management:

- Evaluate HVAC system for proper operation and repair as appropriate to increase air flow to room

			IAQ As	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requested	November 19, 2009
Time of Day	8:30 am				Evaluation Date	November 23, 2009
Outdoor Condi	tions Ten	nperature	79.7	Relative Humidity	72.5 Ambie	ent CO2 430
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Rar	nge # Occupants
316	73.5	72 - 78	55.7	30% - 60%	816 Max 700	> Ambient 24
Noticeable Od	lor Yes		Visible water nage / staining	Visible micro ? growth?	bial Amount o material affe	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	nyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired
Ceiling	Yes	No	No			
Walls	Yes	Νο	No			
Flooring	Yes	Νο	No			
HVAC Supply	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom No	Yes	Yes		Clean as appropr	iate

#### Findings:

- Dust and debris on HVAC supply and return grills

- Odor from off gassing of new materials

- Dust build up on environmental surfaces

# Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Thoroughly clean environmental surfaces throughout the room

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Facilities and Construction Management:

			IAQ As	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requested	November 19, 2009
Time of Day	8:30 am				Evaluation Date	November 23, 2009
Outdoor Condi	itions Ten	nperature	79.7	Relative Humidity	72.5 Ambi	ent CO2 430
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Ra	nge # Occupants
317	71.9	/2 - 78	54.3	30% - 60%	804 Max 700	> Ambient 23
Noticeable Od	lor No		/isible water age / staining	Visible micro ? growth?	bial Amount of material affe	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	nyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired
Ceiling	Yes	No	No			
Walls	Yes	No	No			
Flooring	Yes	Νο	No			
HVAC Supply	Grills No	Yes	Yes	C	lean with Wexcide dis	sinfectant
HVAC Return	Grills No	Yes	Yes	C	lean with Wexcide dis	sinfectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

#### Findings:

- Dust and debris on HVAC supply and return grills

- One inch gap at baseboard of West side cabinet
- 3 cans of Rust-o-leum paint in room

# Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Ensure that paint is properly stored and is used outside with adequate ventilation

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Facilities and Construction Management:

- Evaluate West side cabinet and repair as appropriate to reduce gap at baseboard

			IAQ As	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requested	November 19, 2009
Time of Day	8:30 am	]			Evaluation Date	November 23, 2009
Outdoor Cond	itions Ten	nperature	/9.7	Relative Humidity	72.5 Ambie	ent CO2 430
Fish	Temperature	Range Relat	ive Humidity	Range	CO2 Rar	nge # Occupants
318	73.5	72 - 78	54.2	30% - 60%	831 Max 700	> Ambient 22
Noticeable Oc	lor No		/isible water age / staining	Visible micro ? growth?	bial Amount o material affec	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	inyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	No	No			
Walls	Yes	Νο	No			
Flooring	Yes	Νο	No			
HVAC Supply	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	oply Yes	No	No			
Surfaces in R	oom No	Yes	Yes		Clean as appropri	ate

#### Findings:

- Dust and debris on HVAC supply and return grills

- Construction debris left inside South cabinets

# Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Thoroughly clean South cabinets

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location N	lumber	3631	
	Park	side Elementar	y School		Evaluation	Requested	Novembe	er 19, 2009
Time of Day	8:30 am	]			Eval	uation Date	Novembe	er 23, 2009
Outdoor Condi	tions Ter	nperature	79.7	Relative Humidity	72.5	Ambie	nt CO2	430
Fish T	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	nge #	Occupants
319	73.8	72 - 78	53.2	30% - 60%	774	Max 700	> Ambient	20
Noticeable Od	or Yes		/isible water age / staining	Visible micro growth?		Amount on Amount of affect		
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Drywall/ Pl	aster	No	No			None	
Flooring	12 x 12 V	inyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correctiv	e Action Re	equired	
Ceiling	Yes	Νο	No					
Walls	Yes	Νο	No					
Flooring	Yes	Νο	No					
HVAC Supply	Grills No	Yes	Yes		lean with W	/excide dis	infectant	
HVAC Return	Grills No	Yes	Yes		lean with W	/excide dis	infectant	
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

#### Findings:

- Dust and debris on HVAC supply and return grills

- Odor from off gassing of new materials prevalent in hallway

## Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Facilities and Construction Management:

			IAQ As	sessment	Location Number	3631
	Park	side Elementar	y School		Evaluation Requeste	November 19, 2009
Time of Day	8:30 am	]			Evaluation Da	ate November 23, 2009
Outdoor Conditi	ions Ter	nperature	79.7	Relative Humidity	72.5 Am	bient CO2 430
Fish Te	emperature	Range Rela	tive Humidity	Range	CO2	Range # Occupants
320	74.1	72 - 78	52.3	30% - 60%	771 Max 7	<b>700 &gt; Ambient</b> 18
Noticeable Odo	Yes		/isible water age / staining	Visible micro growth?	/	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Drywall/ Pla	aster	No	No		None
Flooring	12 x 12 Vi	inyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action	Required
Ceiling	Yes	Νο	No			
Walls	Yes	Νο	No			
Flooring	Yes	Νο	No			
HVAC Supply G	Grills No	Yes	Yes	C	lean with Wexcide	disinfectant
HVAC Return G	ills No	Yes	Yes	C	lean with Wexcide	disinfectant
Ceiling at Supp Grills	ly Yes	No	No			
Surfaces in Roc	om Yes	No	No			

#### Findings:

- Dust and debris on HVAC supply and return grills
- Odor from off gassing of new materials prevalent in hallway
- Occupant advised of daily headaches since being in the new building

## Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Facilities and Construction Management: