



Jeffrey S. Moquin, Director Risk Management Department

November 21, 2005

Signature on File

Telephone: 754-321-3200 Facsimile: 754-321-3290

- TO: Mrs. Jill D. Wilson, Principal Pasadena Lakes Elementary School
- FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental Control Risk Management Department
- SUBJECT: Indoor Air Quality (IAQ) Assessment FISH 008, 111, 111F and 134

On November 7, 2005 the IAQ Assessment Team conducted an assessment of FISH 008, 111, 111F and 134 at **Pasadena Lakes Elementary School.** The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Sam Gregg, Area Superintendent Pat Dixon, Area Director Jeffrey S. Moquin, Director, Risk Management Sheldon Dash, Project Manager II, Facilities and Construction Management Steve Feldman, Broward Teachers Union Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

			IAQ As	sessment	Locat	ion Number	2071	
	Pasadena	Lakes Eleme	ntary School		Evalua	tion Requested	November 6, 2008	5
Time of Day	10:00 a.m.					Evaluation Date	November 7, 2008	5
Outdoor Cond	litions To	emperature	86.7	Relative Humid	ity 60.	6 Ambie	nt CO2 524	
Fish	Temperature	Range F	Relative Humidity	Range	CO2	Ran	ge # Occupar	nts
008		72 - 78		30% - 60%		Max 700	> Ambient	
Noticeable O	dor No		Visible water damage / staining	Visible mi ? growt		Amount of ma affected	erial	
Ceiling Type	2 x 4 La	ay In	Yes	Yes		Drywall	in false ceiling	
Wall Type	Drywall/F	Plaster	Νο	No			None]
Flooring			No	No			None	
	Clean	Minor Du / Debris			Corre	ective Action Re	quired	
Ceiling	No	Yes	Yes					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom Yes	No	No					

Findings: (Corridor)

- Visible microbial growth on drywall in false ceiling plenum (mid hallway)

- Dust and debris on ceiling tile tracks

Recommendations:

Site Based Maintenance:

- Clean ceiling tile tracks as appropriate

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate cause of microbial growth on drywall in false ceiling plenum and repair/replace drywall as appropriate

			IAQ As	sessment	Location Num	ber	2071	
	Pasadena L	akes Elementa	ry School		Evaluation Req	uested	November 6, 2	2005
Time of Day	10:00 a.m.				Evaluati	on Date	November 7, 2	2005
Outdoor Condi	tions Terr	perature	86.7	Relative Humidity	60.6	Ambient	CO2 524	
Fish 7	Temperature	Range Rela	ative Humidity	Range	CO2	Range	e # Occu	pants
111	69.6 7	2 - 78	59.7	30% - 60%	605 N	/lax 700 > /	Ambient	3
Noticeable Od	or No		Visible water nage / staining	Visible micro growth?		nt of mater affected	ial	
Ceiling Type	2 x 4 Lay	In	Yes	Yes		Drywall in	false ceiling	
Wall Type	Drywall/Pla	ster	No	No		No	one	
Flooring	Carpet		No	No		N	one	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective A	ction Requ	uired	
Ceiling	No	Yes	Yes					
Walls	Yes	Νο	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	Νο	No					
HVAC Return (Grills Yes	Νο	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Findings: (media center)

- Visible microbial growth on drywall in false ceiling plenum

- Visible microbial growth on books
- Temperature was low at the time of the assessment
- Dust and debris on ceiling tile tracks

Recommendations:

Site Based Maintenance:

- Clean ceiling tile tracks as appropriate

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate cause of microbial growth on drywall in false ceiling plenum and repair/replace drywall as appropriate
- Evaluate and adjust/repair HVAC system to increase temperature
- Clean books to remove microbial growth

			IAQ As	sessment	Locati	on Number	2071	
	Pasadena I	Lakes Elementa	ary School		Evaluat	ion Requested	Novemb	er 6, 2005
Time of Day	10:00 a.m.]			I	Evaluation Date	Novemb	er 7, 2005
Outdoor Cond	itions Te	mperature	86.7	Relative Humi	dity 60.6	6 Ambie	nt CO2	524
Fish	Temperature	Range Rel	ative Humidity	Range	CO2	Ran	ge #	Occupants
111F	61.7	72 - 78	67.9	30% - 60%	621	Max 700	> Ambient	t 0
Noticeable Oc	lor No		Visible water nage / staining	Visible n ? grov		Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay	y In	Yes	Ye	s	Drywall	in false ceil	ing
Wall Type	Drywall/Pl	aster	No	No	D		None	
Flooring	Carpet	t	No	Ν	þ		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	quired	
Ceiling	No	Yes	Yes					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Findings: (AV storage)

- Visible microbial growth on drywall in false ceiling plenum

- Temperature was low and humidity level was elevated at the time of the assessment

- Dust and debris on ceiling tile tracks

Recommendations:

Site Based Maintenance:

- Clean ceiling tile tracks as appropriate

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate cause of microbial growth on drywall in false ceiling plenum and repair/replace drywall as appropriate

- Evaluate and adjust/repair HVAC system to increase temperature and lower humidity level

			IAQ As	sessment	Locati	on Number	2071	
	Pasadena	Lakes Element	ary School		Evaluat	ion Requested	Novemb	er 6, 2005
Time of Day	10:00 a.m.				I	Evaluation Date	Novemb	er 7, 2005
Outdoor Cond	itions Te	mperature	86.7	Relative Humi	dity 60.6	Ambie	nt CO2	524
Fish	Temperature	Range Re	lative Humidity	Range	CO2	Ran	ge #	Occupants
134	68.7	72 - 78	67.1	30% - 60%	766	Max 700	> Ambient	t 13
Noticeable Oc	lor No	da	Visible water mage / staining		nicrobial wth?	Amount of mat affected	terial	
Ceiling Type	2 x 4 La	y In	Yes	Ye	es	Drywall	in false ceil	ing
Wall Type	Drywall/Pl	aster	Νο	N	0		None	
Flooring	Carpe	t	No	N	0		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	quired	
Ceiling	No	Yes	Yes					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Findings:

- Visible microbial growth on drywall in false ceiling plenum above teacher's desk

- Temperature was low and humidity level was elevated at the time of the assessment

- Dust and debris on ceiling tile tracks

Recommendations:

Site Based Maintenance:

- Clean ceiling tile tracks as appropriate

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate cause of microbial growth on drywall in false ceiling plenum and repair/replace drywall as appropriate

- Evaluate and adjust/repair HVAC system to increase temperature and lower humidity level