

Aston A. Henry, Director

SUBJECT:

managing risk with responsibility

754 321-1900

Telephone:

Risk Management Department		Fax:	754 321-1917
October 7, 2014	Signature on File	For Custodia	l Supervisor Use Only
TO:	Sandra Shipman, Principal Pembroke Lakes Elementary School		Issues Addressed Issues Not Addressed
FROM:	Richard Rosa, Project Manager Risk Management Department		

On October 1, 2014, I conducted an assessment at **Pembroke Lakes Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

Indoor Air Quality (IAQ) Assessment

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

IAQ Assessment

Pembroke Lakes Elei	<u> </u>	october 1, 2014	Time of Day2.00	
Outdoor Conditions Temperature	e 91.2 Relativ	/e Humidity 58.2	Ambient CO2 436	
Fish Temperature Range 185 70.5 72 - 78		Range <u>CO</u> 0% - 60% ⁷⁸³		oants
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	No	No		
Walls Tack Board	No	No		
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean No	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	'es
Walls Clean Yes Flooring Clean Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	'es
Room Surfaces No Clean	Ceiling at Supply Grills Clean	No		
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A	Air Frankariana	
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners In Room	No
Mechanical Equipment Location FIS	SH 188		Mechanical Room Clean	'es
Filters Installed Properly No	Filters Clean	Yes	Inside of HVAC Unit Clean	'es
Condensate Pan Clean Yes	Cooling Coil Clean	Yes		
Fresh Air Intake Location Pollutant Sources Near Air Intake	of top	▼	Fresh Air Intake Free of Obstruction	'es
Observations				
Corrective Actions to be Completed			ons to be Completed by PPO	
Clean ceilings around HVAC s			the supply drops	▼
Clean HVAC supply grills wit			ate filter spacer in HVAC	
Coordinate a schedule between classroom Instructor to clean properties.			ture to 72 - 78 degrees to reduce humidity level	▼
, Giassi Doini ilisti uctor to cieani prope	zi iy due to cidtler *	L Repail HVAC	o reduce numberly lever	▼

▼

IAQ Assessment

Pembroke Lakes Elem	entary Evaluation Dat	e October 1, 2014	Time of Day 2:30
Outdoor Conditions Temperature	91.2 Relative	Humidity 58.2	Ambient CO2 436
Fish Temperature Range 186 71.4 72 - 78		Range <u>CO</u> % - 60% 736	
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected
Ceiling 2' X 4' Lay in	Yes	No	16 ceiling tile stains < 2 sq ft
Walls Tack Board	No	No	
Floor 12" x 12" Vinyl	No	No	
Ceiling Clean No	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean Yes
Walls Clean Yes	Inside of Supply	No	Inside of Return
Flooring Clean Yes	Duct Clean	NO	Duct Clean Yes
Room Surfaces No Clean	Ceiling at Supply Grills Clean	No	
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room
Signs of Pests No	Drain Traps Wet	N/A	A: 5 - 1
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners No in Room
Mechanical Equipment Location FISH 188 Mechanical Room Clean Yes			
Filters Installed Properly No	Filters Clean	Yes	Inside of HVAC Unit Clean Yes
Condensate Pan Clean Yes	Cooling Coil Clean	Yes	
Fresh Air Intake Location Roo	f top	▼	Fresh Air Intake Free of Obstruction
Pollutant Sources Near Air Intake		▼	of Obstruction
Observations			

There is an unused exhaust duct where once used stoves were placed. The stoves have been removed and sheet metal is placed over exhaust duct in the classroom. The sheet metal is sweating profusely, recommend to cap off the roof penetration to not allow humid air to enter duct work and create an IAQ concern. Recommend carpenters to remove sheet metal and evaluate the cabinet woodwork. Recommend Safety Department to start creating work orders to cap off rooftop stove exhaust duct.

Corrective Actions to be Completed by Site Based Staff

411
▼
▼
▼
▼
▼
▼
▼
▼

Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 11 C	
Remove stove roof exhaust fan and cap off	▼
Install appropriate filter spacer in HVAC	▼
Repair HVAC to reduce humidity level	▼
Evaluate and repair cause of stained ceiling tiles	▼
Evaluate water damage around sheet metal	▼
Clean the supply drops	▼
	▼
	▼

IAQ Assessment

Pembroke L	akes Elementary Evaluation Da	ate October 1, 2014	Time of Day1:00
Outdoor Conditions Ten	nperature 91.2 Relativ	ve Humidity 58.2	Ambient CO2 436
Fish Temperature 187 70.5	Range Relative Humidity 72 - 78 62.7 3	Range CO ² 0% - 60% 754	Range # Occupants MAX 700 > Ambient
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected
Ceiling 2' X 4' Lay in	Yes	No	3 ceiling tile stains < 1 sq ft
Walls Tack Board	No	No	
Floor 12" x 12" Vinyl	No	No	
Ceiling Clean No Walls Clean Yes Flooring Clean Yes	HVAC Supply Grills Clean Inside of Supply Duct Clean	Yes	HVAC Return Grills Clean Inside of Return Puct Clean Yes
Room Surfaces No Clean	Ceiling at Supply Grills Clean	No	Duct Clean Tes
Trash Removed Yes Signs of Pests No	Exhaust Fans Working Drain Traps Wet	N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners No
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	in Room
Mechanical Equipment Loca	tion FISH 188		Mechanical Room Clean Yes
Filters Installed Properly	No Filters Clean	Yes	Inside of HVAC Unit Clean Yes
Condensate Pan Clean	Yes Cooling Coil Clean	Yes	
Fresh Air Intake Location	Roof top	▼	Fresh Air Intake Free
Pollutant Sources Near Air Intake	No	▼	of Obstruction
Observations			

There is an unused exhaust duct where once used stoves were placed. The stoves have been removed and sheet metal is placed over exhaust duct in the classroom. The sheet metal is sweating profusely, recommend to cap off the roof penetration to not allow humid air to enter duct work and create an IAQ concern. Recommend carpenters to remove sheet metal and evaluate the cabinet woodwork. Recommend Safety Department to start creating work orders to cap off rooftop stove exhaust duct.

Corrective Actions to be Completed by Site Based Staff

211
▼
▼
▼
▼
▼
▼
▼
▼

Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 110	
Remove roof stove exhaust fan and cap off	▼
Install appropriate filter spacer in HVAC	▼
Repair HVAC to reduce humidity level	▼
Evaluate and repair cause of stained ceiling tiles	▼
Evaluate water damage around sheet metal	▼
Clean the supply drops	▼
Set temperature to 72 - 78 degrees	▼
	▼