

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

September 22,	2008 Signature on File
TO:	Ms. Lori McConaughey, Principal Quiet Waters Elementary School
FROM:	Edward See, Project Manager Risk Management Department
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 501, 503 and 512

<u>F</u>	or Custodial Supervisor Use Only
	Custodial Issues Addressed
	Custodial Issues Not Addressed

On September 9, 2008 I conducted an assessment of FISH 501, 503 and 512 at **Quiet Waters Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Sharon Airaghi, Area Superintendent
Ulysses Jackson, Area Director
Jeffrey S. Moquin, Director, Risk Management
Marshall Washington, Project Manager, Facilities and Construction Management
Lynn Cavall, Broward Teachers Union
Roy Jarrett, Federation of Public Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

		IAQ As	sessment	Location Number	3121
	Quiet Waters Ele	mentary School		Evaluation Requested	August 27, 2008
Time of Day 1	:00 pm			Evaluation Date	September 9, 2008
Outdoor Conditions	5 Temperatur	e 88.9	Relative Humidity	76.9 Ambie	ent CO2 365
Fish Temp	erature Range	Relative Humidity	Range	CO2 Rar	nge # Occupants
501	72 72 - 78	61.2	30% - 60%	1328 Max 700	> Ambient 20
Noticeable Odor	No	Visible water damage / stainin	Visible micro g? growth?	bial Amount of ma affected	terial
Ceiling Type	2 x 4 Lay In	No	No		None
Wall Type	Drywall/Plaster	No	No		None
Flooring	12 x 12 Vinyl	No	No		None
Ceiling	Clean Minor / Del Yes N	bris Cleaning	9	Corrective Action Re	equired
Walls	Yes	0 No			
Flooring	Yes	o No			
HVAC Supply Grills	s Yes N	o No			
HVAC Return Grills	s Yes N	o No			
Ceiling at Supply Grills	Yes	o No			
Surfaces in Room	Yes	Νο			

Observations

Findings:

- Observed 3 stuffed animals

Recommendations:

Site Based Maintenance:

- Advise occupant to thoroughly clean stuffed animals on a regular basis or remove from room. Stuffed animals are a source of allergens.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As:	sessment	Location N	lumber	3121	
	Quiet W	aters Elementa	ary School		Evaluation	Requested	August	27, 2008
Time of Day	1:00 pm]			Eval	uation Date	Septemb	er 9, 2008
Outdoor Cond	itions Ter	mperature	88.9	Relative Humidity	/ 76.9	Ambie	nt CO2	365
·	Temperature	Range Rel	lative Humidity	Range	CO2	Ran	ge #	Occupants
503	69.8 ·	72 - 78	64.2	30% - 60%	723	Max 700	> Ambient	2
Noticeable Oc	dor No] da	Visible water mage / staining	Visible micr ? growth?		mount of mat affected		
Ceiling Type	2 x 4 Lay	[,] In	Yes	No		1 c	eiling tile	
Wall Type	Drywall/Pla	aster	Νο	No			None	
Flooring	12 x 12 V	inyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	e Action Re	quired	
Ceiling	No	Yes	Yes	F	Remove and	replace cei	ling tiles	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom Yes	No	No					

Observations

Findings:

- Observed A/C drain pipe leading to sink. Physical Plant Operations is currently addressing A/C drain pipe

- 1 stained ceiling tile

- Temperature was low and humidity level was elevated

Recommendations:

Site Based Maintenance:

 Remove and replace stained ceiling tile. If stains return, contact Physical Plant Operations to generate a work order to evaluate for cause.

- Adjust thermostat to increase temperature which will also lower the humidity level. If necessary call in a work order for PPO to evaluate HVAC operation.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

		IAQ As	sessment	Location Number	3121
	Quiet Waters El	ementary School		Evaluation Requested	August 27, 2008
Time of Day 1	:00 pm			Evaluation Date	September 9, 2008
Outdoor Conditions	5 Temperatu	re 88.9	Relative Humidity	76.9 Ambie	ent CO2 365
Fish Temp	erature Range	Relative Humidity	Range	CO2 Rar	nge # Occupants
512 7	72.3 72 - 78	58.8	30% - 60%	1088 Max 700	> Ambient 3
Noticeable Odor	Yes	Visible water damage / stainin	Visible micro g? growth?		terial
Ceiling Type	2 x 4 Lay In	No	No		None
Wall Type	Drywall/Plaster	No	No		None
Flooring	12 x 12 Vinyl	No	No		None
		r Dust Needs ebris Cleaning	3	Corrective Action Re	equired
Ceiling	Yes	No			
Walls	Yes	No			
Flooring	Yes	No			
HVAC Supply Grills	s Yes	No			
HVAC Return Grills	S Yes	No			
Ceiling at Supply Grills	Yes	No No			
Surfaces in Room	Yes	lo No			

Observations

Findings:

- Observed A/C drain pipe leading to sink. Physical Plant Operations is currently addressing A/C drain pipe

- Elevated moisture in and around sink backsplash area.

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate and repair sink backsplash